actlawsociety

The Law Society of the Australian Capital Territory: Contract for Sale

Schedule

Land	The unexpired term of the Lease	Unit	UP No.	Block	Section	Division/District
				38	32	CAMPBELL
		and known as 10 Elliott Street, Campbell ACT 2612				
Seller	Full name	Michael Douglas McCormack & Spencer Lawrence Wright				
	ACN/ABN					
	Address	10 Elliott Street, Campbell, ACT 2612				
Seller Solicitor	Firm	O'Connor Harris & Co Pty Limited				
	Email	elenag@oconnorharris.com.au			Ref: Elena Griffin	
	Phone	(02) 6247 6077				
	DX/Address	GPO Box 1483, Canberra ACT 2601				
Stakeholder	Name	Hive Property (ACT) Pty Ltd Trust Account				
Seller Agent	Firm	Hive Property (ACT) Pty Ltd				
	Email	josh@hiveproperty.co			Ref: Josh Morrissey	
	Phone	0437 799 234				
	DX/Address	PO Box 819, Dickson ACT 2602				
Restriction on Transfer	*Mark as applicable*	☒ Nil	☐ section 370	☐ section 280	☐ section 306	☐ section 351
Land Rent	*Mark one*	☒Non-Land Rent Lease	☐Land Rent Lease			
Occupancy	*Mark one*	☒Vacant possession	☐Subject to tenancy			
Breach of covenant or unit articles	Description *(Insert other breaches)*	As disclosed in the Required Documents				
Goods	Description	Fixed floor coverings, window treatments, light fittings, as inspected				
Date for Registration of Units Plan						
Date for Completion		On or before 30 days from the date hereof				
Electronic Transaction?		☐ No	☒ Yes, using Nominated ELN:	PEXA		
Land Tax to be adjusted?		☐ No	☒ Yes			
Residential Withholding Tax		New residential premises?		☒ No	☐ Yes	
		Potential residential land?		☒ No	☐ Yes	
		Buyer required to make a withholding payment?		☒ No	☐ Yes (insert details on p.3)	
Foreign Resident Withholding Tax		~~Relevant Price more than $750,000.00?~~		~~☐ No~~	~~☐ Yes~~	
		Clearance Certificates attached for all the Sellers?		☒ No	☐ Yes	

An agent may only complete the details in this black box and exchange this contract. See page 3 for more information.

Buyer	Full name			
	ACN/ABN			
	Address			
Buyer Solicitor	Firm			
	Email			Ref:
	Phone			
	DX/Address			
Price	Price		(GST inclusive unless otherwise specified)	
	Less deposit		(10% of Price)	☐ Deposit by Instalments (clause 52 applies)
	Balance			
Date of this Contract				

Co-Ownership	*Mark one (show shares)*	☐ Joint tenants	☐Tenants in common in the following shares:

Read This Before Signing: Before signing this Contract you should ensure that you understand your rights and obligations. You should read the important notes on page 3. You should get advice from your solicitor.

Seller signature	**Buyer signature**
Seller witness name and signature	Buyer witness name and signature

Seller Disclosure Documents

The following marked documents are attached and form part of this Contract. The Buyer acknowledges that by execution of this Contract the Buyer certifies in writing that the Buyer received the marked documents prior to entering into this Contract.

- ☒ Crown lease of the Land (including variations)
- ☒ Current certified extract from the land titles register showing all registered interests affecting the Property
- ☒ Deposited Plan for the Land
- ☒ Energy Efficiency Rating Statement
- ☒ Encumbrances shown on the land titles register (excluding any mortgage or other encumbrance to be discharged)
- ☐ If there is an encumbrance not shown on the land titles register — a statement about the encumbrance complying with the Civil Law (Sale of Residential Property) Regulations
- ☒ Lease Conveyancing Inquiry Documents for the Property
- ☒ Building Conveyancing Inquiry Document (except if:
  - the Property is a Class A Unit
  - the residence on the Property has not previously been occupied or sold as a dwelling; or
  - this Contract is an "off-the-plan purchase")
- ☒ Building and Compliance Inspection Report(s) (except if section 9(2)(a)(ii) or section 9(2)(a)(iii) of the Sale of Residential Property Act applies).
- ☒ Pest information (except if the property is a Class A Unit or is a residence that has never been occupied): Pest Inspection Report(s).
- ☐ Regulated Swimming Pool documentation required under section 9 (1)(ja) of the Sale of Residential Property Act (on and from 1 May 2024).

If the Property is off-the-plan:

- ☐ Proposed plan
- ☐ Inclusions list

If the Property is a Unit where the Units Plan is not registered:

- ☐ Inclusions list
- ☐ Disclosure Statement

If the Property is a Unit where the Units Plan is registered:

- ☐ Units Plan concerning the Property
- ☐ Current certified extract from the land titles register showing all registered interests affecting the Common Property
- ☐ Unit Title Certificate
- ☐ Registered variations to rules of the Owners Corporation
- ☐ (If the Unit is an Adaptable Housing Dwelling) drawings and plans demonstrating compliance with Australian Standard AS 4299-1995 (Adaptable Housing) as in force from time to time
- ☐ (If the Owners Corporation is a party to a Building Management Statement) Building Management Statement

If the Property is a Lot that is part of a Community Title Scheme:

- ☐ Section 67 Statement, as first or top sheet
- ☐ Community Title Master Plan
- ☐ Community Title Management Statement

If the Property is a Lot that will form part of a Community Title Scheme:

- ☐ Proposed Community Title Master Plan or sketch plan
- ☐ Proposed Community Title Management Statement

GST

- ☒ Not applicable
- ☐ Input taxed supply of residential premises
- ☐ Taxable supply (including new residential premises)
- ☐ GST-free supply of going concern
- ☐ Margin scheme applies

Tenancy

- ☐ Tenancy Agreement
- ☐ No written Tenancy Agreement exists

Invoices

- ☒ Building and Compliance Inspection Report
- ☒ Pest Inspection Report

Asbestos

- ☒ Asbestos Advice
- ☐ Current Asbestos Assessment Report

Damages for delay in Completion – applicable interest rate and legal costs and disbursements amount (see clause 22)

Interest rate if the defaulting party is the Seller	0% per annum
Interest rate if the defaulting party is the Buyer	10% per annum
Amount to be applied towards legal costs and disbursements incurred by the party not at fault	$440.00 (GST inclusive)

Tenancy Summary

Premises		Expiry date	
Tenant name		Rent	
Commencement date		Rent review date	
Term		Rent review mechanism	

Managing Agent Details for Owners Corporation or Community Title Scheme (if no managing agent, secretary)

Name		Phone	
Address			

SPECIAL CONDITIONS

A. CONDITIONS OF SALE BY AUCTION

1. The auctioneer may make 1 bid for the seller of the property at any time during the auction.
2. Each person bidding must be entered on the bidders record.
3. The auctioneer may refuse any bid.
4. The auctioneer may decide the amount by which the bidding is to be advanced.
5. The auctioneer may withdraw the property from sale at any time.
6. The auctioneer may refer a bid to the seller at any time before the end of the auction.
7. If there is a dispute about a bid, the auctioneer may resubmit the property for sale at the last undisputed bid or start the bidding again.
8. If there is a dispute about a bid, the auctioneer is the sole arbiter and the auctioneer's decision is final.
9. The sale is subject to a reserve price unless the auctioneer announces otherwise.
10. The highest recorded bidder will be the buyer, subject to any reserve price.
11. If a reserve price has been set for the property and the property is passed in below the reserve price, the seller must first negotiate with the highest bidder for the purchase of the property.
12. The buyer must sign the contract and pay the deposit immediately after the fall of the hammer.

1. ELECTRONIC SIGNATURE AND EXCHANGE CONDITION

(a) Each party consents to:

(i) The electronic exchange of this Contract; and

(ii) Notices being served or received under this Contract electronically, including by email.

(b) Each party agrees to accept:

(i) Electronic signatures; or

(ii) A copy of a wet signature

and the parties warrant that this is sufficient evidence of:

(iii) The parties' intention to enter into and be bound by the Contract;

(iv) The parties' consent to conducting this Contract electronically; and

(v) The Contract itself being a document which is in writing and signed in a manner that results in a binding agreement.

2. AMENDMENTS TO THE STANDARD TERMS

The ACT Law Society Printed Terms are amended as follows:

(a) Clause 2.3 the word "cash (up to $3,000.00)" is deleted and replaced with "electronic funds transfer".

(b) in Clause 2.6 the words "or in cash (up to $200)" are deleted.

(c) in Clause 8.4 the words "Buyer Solicitor" are deleted and replaced with "Seller Solicitor".

(d) Clause 13.10.1 is deleted in its entirety.

(e) Clause 17.1.1 delete "5%" and replace it with "$1,000.00".

(f) Clause 17.1.2 (b) is deleted in its entirety.

(g) Clause 26 Insert new clause 26.2.6 as follows: "sends it by email. A party's email address is that contained in the Contract or which the lawyer or conveyancer for the party receiving the notice has most recently used to communicate with the party sending the notice. A notice sent by email is treated as given and received:

(i) If delivered by 5.00pm on a business day – at the time (local time in the place of receipt) specified in the delivery confirmation or receipt generated by the sender's email; or

(ii) if delivered after 5.00pm on a business day or on a day that is not a business day – on the next business day after the time (local time in the place of receipt) specified in the delivery confirmation or receipt generated by the senders email."

(h) in Clause 28.2 delete "5%" and replace it with "$1,000.00".

(i) in Clause 53.2, delete the words "7 days after the date of this Contract" and replace with "7 days before the Date of Completion".

(j) in Clause 53.6.2, delete the words "7 days prior to Completion" and replace with "1 day prior to Completion".

3. SPECIAL CONDITIONS ESSENTIAL AND PREVAILING

These Special Conditions are essential terms of this Contract and where an inconsistency exists between the Standard Terms of this Contract and these Special Conditions, these Special Conditions shall prevail.

4. CONDITION OF PROPERTY

(a) The Buyer acknowledges that it does not rely on any representation, statement, warranty, condition or promise made by or on behalf of the Seller except as stated in this Contract or where implied by legislation and cannot be excluded.

(b) The Buyer cannot require the Seller to carry out any repairs or works to the Property unless the repairs or works required to be carried out are specified in these Special Conditions or are required by legislation.

(c) The Buyer accepts the Property as is (including with respect to the state of cleanliness of the Property) and acknowledges that they cannot make a claim, requisition, rescind or terminate this Contract, or delay Completion, in respect of the nature, quality, state of repair and condition, latent or patent defects, dilapidation or infestation of the Property unless the Buyer has a statutory right to take such action.

5. AGENT'S COMMISSION

(a) The Buyer warrants that it has not been introduced directly or indirectly to either the Seller or the Property by any person other than the Seller's Agent and indemnifies the Seller against any claim or demand for commission arising from a breach of this warranty.

(b) This special condition does not merge on completion.

6. TERMINATION ON INCAPACITY OF A PARTY

(a) If the Buyer or the Seller being a natural person (and, if comprising more than one person, any one or more of them) before Completion;

(i) dies; or

(ii) is found by a court or tribunal to be incapable of administering his or her estate or affairs;

then either Party may rescind the Contract and the provisions of clause 21 shall apply.

(b) If the Buyer being:

(i) a natural person (and, if comprising more than one person, any one or more of them) before Completion;

1. enters a scheme of arrangement; or

2. makes an assignment for the benefit of creditors; or

(ii) an incorporated entity (and, if comprising more than one incorporated entity, any one or more of them) before Completion:

1. appoints or has appointed an administrator or receiver over the whole or any part of its assets or undertaking; or

2. resolves to go into liquidation; or

3. has a summons or application presented or an order made for its winding up; or

4. enters into a deed of arrangement, assignment or composition for the benefit of creditors

then this shall constitute a non-refutable default under the contract by the Buyer and the Seller shall be entitled to terminate this Contract immediately and the provisions of clause 19 shall apply.

7. ADJUSTMENTS

(a) For the purpose of this special condition, Income means all income derived from the Property including rents, licence agreement fees and payments, and profits.

(b) If Completion does not occur by the Date for Completion due solely to the delay or default of the Buyer, then the Buyer shall be liable for all Land Charges from the Date for Completion.

(c) Notwithstanding Clause 8 of this Contract, the Seller will be entitled to all Income up to and including the date Completion is effected.

(d) In the event of an error or omission in relation to the adjustments, the parties agree to adjust any amount owed after completion. This clause shall not merge at completion.

(e) Irrespective of anything in the Contract, all rental adjustments at settlement must be made on the basis of the net rent received by the Seller. For avoidance of doubt any management agent fee is to be deducted from the rent for the purposes of rental adjustment.

(f) At least 3 Business Days prior the Date for Completion the Buyer must provide the Seller Solicitor with all certificates and other information required to calculate the adjustments including a special water meter reading certificate, failure of which will result in no adjustment being made on settlement for any amount shown on the certificate and the Buyer acknowledges that they will not be entitled to retain any amount from the balance of the Price or the Deposit to pay or adjust for any amount shown on the certificate.

8. COMMUNITY TITLE CERTIFICATE

If the Property is:

(a) a unit; and

(b) within a Community Title scheme; and

(c) the Community Title levies are paid by the Owners Corporation of the Units Plan (i.e. the Community Title levies are not paid by individual unit holders);

then

(d) the parties agree that the Seller is not required to provide the Buyer with a section 56 certificate for the purpose of adjustment on completion.

9. KEYS ON COMPLETION

Upon Completion the Seller will provide the Buyer with all keys necessary for the Buyer to enter the Improvements and any other keys in the Seller's possession. The Buyer will make no objection, requisition or claim for compensation with respect to the availability or otherwise of any other keys to the Improvements.

10. ASBESTOS

(a) The Seller does not warrant that the Property is free of any form of asbestos.

(b) In entering into this Contract the Buyer warrants and acknowledges that they have made and relied on their own enquiries as to whether any form of asbestos is present in the Property and the consequences of the presence of any asbestos on the Property

and will make no claim, requisition, rescind, terminate or delay Completion, in respect of the existence or discovery of asbestos on or in the Property.

11. ENTIRE AGREEMENT

The Buyer agrees that this Contract sets out the entire understanding between the parties concerning the subject matter of this Contract and that it supersedes any prior arrangement, contract or other agreement in relation to the subject matter of this Contract.

12. RELIANCE AND REPRESENTATIONS

The Buyer warrants to the Seller that it has entered into this Contract entirely own its own investigations and enquiries and does not rely on any representation by the Seller, Seller Solicitor or Seller Agent in relation to any matter in relation to the Property or this Contract.

13. FIRB APPROVAL

(a) The Buyer warrants to the Seller that it does not require any approvals under the Australian Governments foreign investment policy to acquire the Property ("**FIRB Approval**") and that the Treasurer cannot make an order under Part II of the FATA regarding the acquisition of the Property by the Buyer.

(b) The Buyer indemnifies the Seller against all liability or loss suffered or incurred by the Seller which arises directly or indirectly from a breach of any of the obligations of the Buyer under this special condition.

14. ENERGY EFFICIENCY RATING

The Seller warrants that since the date of the Energy Efficiency Rating Report attached to this Contract for Sale:

(a) no building work under the Building Act 2004 has been carried out on the premises that affects the energy efficiency rating contained in the energy efficiency rating statement for the habitable part of the premises; and

(b) no other building element or external element used in producing the energy efficiency rating statement has been materially altered or changed since the energy efficiency rating statement was issued that would make the energy efficiency rating statement false or misleading.

15. RELEASE OF DEPOSIT

(a) If requested by the Seller, the Buyer hereby agrees and authorises the release of the balance of the deposit (less the agent's commission and marketing fees) to be paid to the Seller's solicitor's trust account prior to completion, to be released on completion for the use of settlement.

16. DEPOSIT BOND

(a) In this Contract the word "Bond" means either:

(i) the Deposit Insurance Bond issued to the Seller at the request of the Buyer and in and to the effect of the form annexed hereto; or

(ii) a Bank Guarantee issued by a Bank operating in Australia and in and to the effect of the form annexed hereto.

(b) Subject to paragraphs (c) and (d) below, the delivery of the Bond upon or before the making of this contract to the Seller's Solicitors shall, to the extent of the amount

guaranteed under the Bond, be deemed for the purposes of this contract to be payment of the deposit in accordance with this contract.

(c) The Buyer shall pay the amount stipulated in the Bond to the Seller in cash or by unendorsed bank cheque on completion of this contract or at such other time as may be provided for the deposit to be accounted to the Seller.

(d) If the Seller serves on the Buyer a notice in writing claiming to forfeit the deposit then, to the extent that the amount has not already been paid under the Bond, the Buyer shall forthwith pay the deposit (or so much thereof as has not been paid) to the person nominated in this contract to hold the deposit.

(e) The Seller acknowledges that payment under the Bond shall, to the extent of the amount paid, be in satisfaction of the Buyer's obligations to pay the deposit under paragraph (d) above.

(f) If seven (7) days prior to the expiration of the term of this Bond or if extended then seven (7) days prior to the expiration of the extended period of the Bond the Buyer has not either:-

(i) completed this contract; or

(ii) delivered to the Seller's Solicitors a Bond in identical terms for an extended period; or

(iii) paid the amount covered by the Bond as deposit to the stakeholder;

the Buyer shall be in default. If the Buyer is in default under any provision of this sub clause then immediately and without the notice otherwise necessary under clause 18 the provisions of clause 19 will apply.

(g) If the Bond provider is placed under external administration of any nature before the completion date, the Buyer must, within 24 hours, secure the Deposit to the Seller by either:

(i) providing a replacement Bond by another Bond provider reasonably acceptable to the Seller: or

(ii) payment of the Deposit in accordance with Clause 2.1

and this Special Condition is for the benefit of the Seller and the performance of the obligations by the Buyer are an essential condition of this Contract for Sale.

17. DEFT AUCTION PAY

(a) Subject to the following clauses, the Buyer may pay the Deposit payable under the terms of this Contract on the Date of this Contract to the Stakeholder using DEFT Auction Pay (being the Macquarie Bank online funds transfer system).

(b) This special condition will only apply if the Buyer pays the Deposit on the Date of this Contract using DEFT Auction Pay and the Stakeholder is provided with evidence of payment of the Deposit on the Date of this Contract. If not, then this special condition will not apply to this Contract for Sale and the Deposit will be strictly payable in accordance with the terms and conditions of this Contract.

(c) If the Stakeholder does not receive the cleared funds equal to the amount of the Deposit into its trust account within three business days of the Date of this Contract (**Payment Period**), then the Buyer must pay the Deposit payable on the Date of this Contract by delivering an unendorsed bank cheque to the Stakeholder within 24 hours of the Seller or its Solicitor notifying the Buyer that the payment referred to in (a) was not received within the Payment Period.

18. DIRECTOR'S GUARANTEE AND INDEMNITY

(a) If the Buyer is a corporation (other than a company listed on a public stock exchange) the Buyer must cause all the directors of that corporation to guarantee the performance of the Buyer's obligations under this Contract by duly completing and signing the form of guarantee and indemnity set out in Schedule 1.

(b) If the guarantee and indemnity is not executed and delivered as required by this clause:

(i) the Buyer will be in breach of an essential term of this Contract; and

(ii) the Seller will be entitled to enforce all remedies available under this Contract and at law for such breach.

(c) This Special Condition is an essential term of this Contract.

SCHEDULE 1 – GUARANTEE AND INDEMNITY

(a) In consideration of the Seller entering into this Contract at the Guarantor's request, the Guarantor guarantees to the Seller:

(i) payment of all money payable by the Buyer under this Contract; and

(ii) the performance of all of the Buyer's other obligations under this Contract.

(a) The Guarantor:

(i) indemnifies the Seller against any claim, action, Loss, damage, cost, liability, expense or payment incurred by the Seller in connection with or arising from any breach or default by the Buyer of its obligations under this Contract; and

(ii) must pay on demand any money due to the Seller under this indemnity.

(b) The Guarantor is jointly and separately liable with the Buyer to the Seller for:

(i) the performance by the Buyer of its obligations under this Contract; and

(ii) any damage incurred by the Seller as a result of the Buyer's failure to perform its obligations under this Contract or the termination of this Contract by the Seller.

(c) The Guarantor must pay to the Seller on written demand by the Seller all expenses incurred by the Seller in respect of the Seller's exercise or attempted exercise of any right under this clause.

(d) If the Seller assigns or transfers the benefit of this Contract, the transferee receives the benefit of the Guarantor's obligations under this clause.

(e) The Guarantor's obligations under this clause are not released, discharged or otherwise affected by:

(i) the granting of any time, waiver, covenant not to sue or other indulgence;

(ii) the release or discharge of any person;

(iii) an arrangement, composition or compromise entered into by the Seller, the Buyer, the Guarantor or any other person;

(iv) any moratorium or other suspension of the right, power, authority, discretion or remedy conferred on the Seller by this Contract, a statute, a Court or otherwise;

(v) payment to the Seller, including payment which at or after the payment date is illegal, void, voidable, avoided or unenforceable; or

(vi) the winding up of the Buyer.

(f) The deed constituted by this clause binds each party who signs it even if other parties do not, or if the execution by other parties is defective, void or voidable.

(g) This clause binds the Guarantor and the executors, administrators and assigns of the Guarantor.

(h) This clause operates as a deed between the Seller and the Guarantor.

EXECUTED BY)
)
)

_____ _____

Name of Guarantor Signature of Guarantor

in the presence of:

_____ _____

Name of Witness Signature of Witness

EXECUTED BY)
)
)

Name of Guarantor	Signature of Guarantor

in the presence of:

Name of Witness	Signature of Witness

RW Amount

(residential withholding payment) — further details

The supplier will frequently be the Seller. However, sometimes further information will be required as to which entity is liable for GST (eg if the Seller is part of a GST group, where the GST representative has the GST liability). If more than one supplier, provide details for each supplier.

Supplier	Name			
	ABN		Phone	
	Business address			
	Email			
Residential Withholding Tax	Supplier's portion of the RW Amount:			$
	RW Percentage:			%
	RW Amount (ie the amount that the Buyer is required to pay to the ATO):			$
	Is any of the consideration not expressed as an amount in money?			☐ No ☐ Yes
	If 'Yes', the GST inclusive market value of the non-monetary consideration:			$
	Other details (including those required by regulation or the ATO forms):			

Cooling Off Period

(for residential property only)

1 The Buyer may rescind this Contract at any time before 5pm on the 5th Business Day after the day this Contract is made except if any circumstance in paragraph 2 applies.

2 There is no cooling off period if:

- the Buyer is a corporation; or
- the Property is sold by tender; or
- the Property is sold by auction; or
- before signing this Contract, the Buyer gives the Seller a certificate in the form required by the Sale of Residential Property Act signed by the Buyer Solicitor; or
- this Contract is made on the same day the Property was offered for sale by auction but passed in and the Buyer was recorded in the bidders record as a bidder or a person for whom a bidder was bidding.

3 A Buyer exercising the cooling off right by rescinding this Contract forfeits 0.25% of the Price. The Seller is entitled to recover the amount forfeited from the Deposit and the Buyer is entitled to a refund of any balance.

Block 108 Section 32 Campbell

Warnings

1 The Lease may be affected by the *Residential Tenancies Act 1997* (ACT) or the *Leases (Commercial & Retail) Act 2001* (ACT).

2 If a consent to transfer is required by law, see clause 4 as to the obligations of the parties.

3 As some risks associated with the Property pass from the Seller to Buyer on the Date of this Contract, (except if the Property is a Unit) the Buyer should take out insurance on the Property on the Date of this Contract.

4 The Buyer will usually have to pay stamp duty on the purchase of the Land. The Buyer may incur penalties if the Buyer does not pay the stamp duty within the required time.

5 There are serious risks to a Buyer releasing the Deposit before Completion. The Buyer should take legal advice before agreeing to release the Deposit.

6 The Buyer should consider the application of the Territory Plan and other planning and heritage issues before signing this Contract.

7 If the Lease is a concessional lease then restrictions on transfer and other dealings may apply.

Disputes

If there is a dispute, the Law Society encourages the use of informal procedures such as negotiation, independent expert appraisal or mediation to resolve the dispute.

Exchange of Contract

1 An Agent, authorised by the Seller, may:

- insert:
  - the name and address of, and contact details for, the Buyer;
  - the name and address of, and contact details for, the Buyer Solicitor;
  - the Price;
  - the Date of this Contract,
- insert in, or delete from, the Goods; and
- exchange this Contract.

2 An Agent must not otherwise insert, delete or amend this Contract.

3 **The Agent must not exchange this Contract unless expressly authorised by the Seller or (if a solicitor is acting for the Seller) by the Seller or the Seller Solicitor.**

The Seller agrees to sell and the Buyer agrees to buy the Property for the Price on these terms:

1. Definitions and interpretation

1.1 Definitions appear in the Schedule and as follows:

Affecting Interests means any mortgage, encumbrance, lease, lien, charge, notice, order, caveat, writ, or other interest;

Adaptable Housing Dwelling has the meaning in the Sale of Residential Property Act;

Agent has the meaning in the Sale of Residential Property Act;

ATO means the Australian Taxation Office, and includes the Commissioner for Taxation;

Balance of the Price means the Price less the Deposit;

Breach of Covenant means:

- a Development not approved under the Planning Act including a development for which design and siting approval has not been obtained;
- a breach of the Building and Development Provision;
- a breach of any obligation of the Seller in a registered restrictive covenant affecting the Lease;
- a breach of any other term of the Lease;
- a breach of the articles of the Owners Corporation (if the Property is a Unit); or
- an Unapproved Structure;

Building Act means the *Building Act 2004* (ACT);

Building and Development Provision has the meaning in the Planning Act;

Building Conveyancing Inquiry Document has the meaning in the Sale of Residential Property Act;

Building and Compliance Inspection Report has the meaning in the Sale of Residential Property Act;

Building Management Statement has the meaning in the Land Titles Act;

Business Day means any day other than a Saturday, Sunday, public holiday or bank holiday in the Australian Capital Territory;

Class A Unit has the meaning in the Sale of Residential Property Act;

Common Property for a Unit has the meaning in the Unit Titles Act;

Common Property for a Lot that forms part of a Community Title Scheme has the meaning in the Community Title Act;

Community Title Act means the *Community Title Act 2001* (ACT);

Community Title Body Corporate means the entity referred to as such in the Community Title Act;

Community Title Management Statement has the meaning in the Community Title Act;

Community Title Master Plan has the meaning in the Community Title Act;

Community Title Scheme has the meaning in the Community Title Act;

Completion means the time at which this Contract is completed and **Completed** has a corresponding meaning;

Compliance Certificate means a certificate issued for the Lease under section 296 of the *Planning and Development Act* 2007,Division 10.12.2 of the Planning Act or under section 28 of the *City Area Leases Act 1936* or under section 180 of the Land Act;

Covenant includes a restrictive covenant;

Block 58 Section 32 Campbell

Default Notice means a notice in accordance with clause 18.5 and clause;18.6

Default Rules has the meaning in the Unit Titles Management Act;

Deposit means the deposit forming part of the Price;

Developer in respect of a Lot has the meaning in the Community Title Act;

Developer Control Period has the meaning in the Unit Titles Management Act;

Development has the meaning in the Planning Act;

Development Statement has the meaning in the Unit Titles Act;

Disclosure Statement has the meaning in the Property Act;

Disclosure Update Notice has the meaning in section 260(2) of the Property Act;

Encumbrance has the meaning in the Sale of Residential Property Act but excludes a mortgage;

Energy Efficiency Rating Statement has the meaning in the Sale of Residential Property Act;

Excluded Change has the meaning in section 259A(4) of the Property Act;

General Fund Contribution has the meaning in section 78(1) of the Unit Titles Management Act;

GST has the meaning in the *A New Tax System (Goods and Services Tax) Act 1999* (Cth);

GST Rate means the prevailing rate of GST specified as a percentage;

Improvements means the buildings, structures and fixtures erected on and forming part of the Land;

Income includes the rents and profits derived from the Property;

Land Act means the *Land (Planning & Environment) Act 1991* (ACT);

Land Charges means rates, land rent, land tax and other taxes and outgoings of a periodic nature in respect of the Property;

Land Rent Act means the *Land Rent Act 2008* (ACT);

Land Rent Lease means a Lease that is subject to the Land Rent Act;

Land Titles Act means the *Land Titles Act 1925* (ACT);

Lease means the lease of the Land having the meaning in the Planning Act;

Lease Conveyancing Inquiry Document has the meaning in the Sale of Residential Property Act;

Legislation Act means the *Legislation Act 2001*;

Liability of the Owners Corporation means any actual or contingent liability of the Owners Corporation attributable to the Unit on a Unit Entitlement basis (other than normal operating expenses) or expenditure to be made by the Owners Corporation to fulfil its obligations under the Unit Titles Management Act;

Lot has the meaning in the Community Title Act;

Non-Land Rent Lease means a Lease that is not subject to the Land Rent Act;

Notice to Complete means a notice in accordance with clause 18.1 and clause 18.2 requiring a party to complete;

Owners Corporation means the Owners Corporation for the Unit constituted or to be constituted under the Unit Titles Management Act following registration of the Units Plan;

Pest Inspection Report has the meaning in the Sale of Residential Property Act;

Pest Treatment Certificate has the meaning in the Sale of Residential Property Act;

Planning Act means the *Planning Act 2023* (ACT);

Planning and Land Authority has the meaning in the Legislation Act;

Prescribed Building has the meaning in the Building Act;

Prescribed Terms has the meaning in the Residential Tenancies Act;

Property means the unexpired term of the Lease, the Improvements and the Goods, or (if the Land is a Unit) the unexpired term of the Unit Lease, the Improvements and the Goods;

Property Act means *Civil Law (Property) Act 2006* (ACT);

Required Documents has the meaning in the Sale of Residential Property Act and includes a Unit Title Certificate but excludes a copy of this Contract;

Rescission Notice has the meaning in the Sale of Residential Property Act;

Residential Tenancies Act means the *Residential Tenancies Act 1997* (ACT);

Sale of Residential Property Act means the *Civil Law (Sale of Residential Property) Act 2003* (ACT);

Block 38 Section 32 Gilmore

Section 56 Certificate means a certificate for a Lot issued under section 56 of the Community Title Act;

Section 67 Statement means a statement for a Lot complying with section 67(2)-(4) of the Community Title Act;

Service includes air, communication, drainage, electricity, garbage, gas, oil, radio, sewerage, telephone, television, or water service;

Staged Development has the meaning given by section 17(4) of the Unit Titles Act;

Tenancy Agreement includes a lease for any term and whether for residential purposes or otherwise;

Unapproved Structure has the meaning in the Sale of Residential Property Act;

Unit means the Unit referred to in the Schedule and which has the meaning in the Unit Titles Act;

Unit Entitlement for the Unit has the meaning in the Unit Titles Act;

Unit Title is the Lease together with the rights of the registered lessee of the Unit;

Unit Title Certificate means a certificate for the Unit issued under section 119 of the Unit Titles Management Act;

Unit Titles Act means the *Unit Titles Act 2001* (ACT);

Unit Titles Management Act means the *Unit Titles (Management) Act 2011* (ACT);

Units Plan means all the documents relating to the subdivision of the Land registered as the Units Plan for the Unit under the *Land Titles (Unit Titles) Act 1970;* and

Withholding Law means Subdivision 14 of Schedule 1 of the *Taxation Administration Act 1953* (Cth) and associated provisions.

1.2 In this Contract:

- a reference to the Seller or to the Buyer includes the executors, administrators and permitted assigns of any of them, if an individual, and the successors or permitted assigns of any of them, if a corporation;
- the singular includes the plural, and the plural includes the singular;
- a reference to a person includes a body corporate;
- a term not otherwise defined has the meaning in the Legislation Act; and
- a reference to an Act includes a reference to any subordinate legislation made under it or any Act which replaces it.

1.3 Headings are inserted for convenience only and are not part of this Contract.

1.4 If the time for something to be done or to happen is not a Business Day, the time is extended to the next Business Day, except in the case of clause 2.1.

1.5 A reference to "this Contract" extends to the Schedule, any annexure, additional clauses and attachments forming part of this Contract.

1.6 If there is more than one buyer or more than one seller the obligations which they undertake bind them jointly and individually.

1.7 Where the Buyer consists of more than one person, as between themselves, they agree to buy the Property in the specified manner of Co-ownership or if one alternative is not marked, as joint tenants.

1.8 Without limiting clause 13, the parties agree that for the purposes of the *Electronic Transactions Act 2001* (ACT) and the Electronic Transactions Act 1999 (Cth), this Contract may be signed and/or exchanged electronically.

2. Terms of payment

2.1 The Buyer must pay the Deposit on the Date of this Contract, to the Stakeholder or, if no Stakeholder is named, then to the Seller.

2.2 The Deposit becomes the Seller's property on Completion.

2.3 The Deposit may be paid by cheque or in cash (up to $3,000.00) but if it is not paid on time or, if it is paid by cheque which is not honoured on first presentation, the Buyer is in default.

2.4 If the Buyer is in default under clause 2.3, then immediately and without the notice otherwise necessary under clause 18, clause 19 applies.

2.5 On Completion the Buyer must give the Seller an authority directing the Stakeholder to account to the Seller for the Deposit.

2.6 On Completion the Buyer must pay to the Seller in Canberra the Balance of the Price by unendorsed bank cheque, or in cash (up to $200.00).

2.7 Any money payable to the Seller by the Buyer or the Stakeholder must be paid to the Seller or as the Seller Solicitor directs in writing and payment in accordance with that direction will be sufficient discharge to the person paying.

2.8 Completion must take place on the Date for Completion or as otherwise determined by this Contract and if not specified or determined, within a reasonable time.

Block 20 Section 82 Campbell

3. Title to the Lease

3.1 The Lease is or will before Completion be granted under the Planning Act.

3.2 The Lease is transferred subject to its provisions.

3.3 The title to the Lease is or will before Completion be registered under the Land Titles Act.

3.4 The title to the Lease must be transferred free from all Affecting Interests except as otherwise provided.

3.5 The Buyer cannot insist on any Affecting Interests being removed from the title to the Lease before Completion provided, on Completion, the Seller gives the Buyer any documents and registration fees necessary to remove the Affecting Interests.

4. Restrictions on transfer

4.1 The Lease is not subject to any restrictions on transfer other than any Restriction on Transfer.

4.2 If the Lease is subject to a Restriction on Transfer under the Planning Act due to non-compliance with the Building and Development Provision then this Contract is subject to the grant of the approval referred to in section 370 of the Planning Act. A Restriction on Transfer referring to "section 370" refers to this restriction.

4.3 If the Lease is a lease of the type referred to in section 279 of the Planning Act then this Contract is subject to the approval in accordance with the Planning Act. A Restriction on Transfer referring to "section 280" refers to this restriction.

4.3A If the Lease is subject to a Restriction on Transfer under section 306 of the Planning Act, then this Contract is subject to the grant of the approval mentioned in sections 306 and 307 of the Planning Act. A Restriction on Transfer referring to "section 306" refers to this restriction.

4.3B If the Lease is subject to a Restriction on Transfer under section 351 of the Planning Act, then this Contract is subject to the grant of the approval mentioned in section 351 of the Planning Act. A Restriction on Transfer referring to "section 351" refers to this restriction. Immediately after the Date of this Contract the Seller must do everything reasonably necessary to remove the restriction or obtain the consent required. If requested in writing, the Buyer must join in any application of the Seller and must do everything reasonably necessary to enable the Seller to obtain the consent. The Seller must pay all associated fees in connection with the application.

4.4 If the consent referred to in clauses 4.2, 4.3, 4.3A or 4.3B is not granted by the Date for Completion then either party may rescind this Contract (provided that the party seeking to rescind is not then in default) and clause 21 applies.

5. Particulars of title and submission of transfer

5.1 Unless clause 5.3 applies the Seller need not provide particulars of title.

5.2 No later than 7 days before the Date for Completion, the Buyer must give the Seller a transfer of the Lease in the form prescribed by the Land Titles Act, to be returned by the Seller to the Buyer on Completion in registrable form.

5.3 If the Seller is not the registered proprietor of the Lease at the Date of this Contract, the Seller must give to the Buyer no later than 14 days before the Date for Completion a copy of the instrument and any other documents necessary to enable the Seller to be registered as proprietor.

6. Buyer rights and limitations

6.1 If the Buyer establishes before Completion that except as disclosed in this Contract there is any Unapproved Structure on the Property, then the Buyer may:

6.1.1 require the Seller to arrange for the Unapproved Structure to be approved before Completion; and

6.1.2 if the Unapproved Structure is not approved before Completion, rescind or complete and sue the Seller for damages.

6.2 If the Buyer establishes, immediately before Completion, that, except as disclosed in this Contract:

6.2.1 the Property is subject to an encumbrance other than the encumbrances shown on the title to the Lease; or

6.2.2 the Buyer is not entitled to vacant possession,

then the Buyer may either:

6.2.3 rescind; or

6.2.4 complete and sue the Seller for damages.

6.3 The Buyer is not entitled to make any requisitions on the title to the Property.

6.4 The Buyer cannot make a claim or objection or rescind or terminate in respect of:

6.4.1 a Service for the Property being a joint service or passing through another property, or any Service for another property passing through the Property;

6.4.2 a wall being or not being a party wall or the Property being affected by an

Block 38 Section 32 Ormsby Ell

easement for support or not having the benefit of an easement for support;

6.4.3 any change in the Property due to fair wear and tear before Completion;

6.4.4 a promise, representation or statement about this Contract, the Property or the Lease, not made in this Contract;

6.4.5 any Breach of Covenant described in the Schedule or disclosed elsewhere in this Contract;

6.4.6 the ownership or location of any dividing fence;

6.4.7 the ownership of any fuel storage tank; and

6.4.8 anything disclosed in this Contract (except an Affecting Interest).

7. Seller warranties

7.1 The Seller warrants that at the Date of this Contract:

7.1.1 the Seller will be able to complete at Completion;

7.1.2 the Seller has no knowledge of any unsatisfied judgment, order or writ affecting the Property;

7.1.3 the Seller has no knowledge of any current or threatened claims, notices or proceedings that may lead to a judgment, order or writ affecting the Property; and

7.1.4 the Seller is not aware of any material change in the matters disclosed in the Required Documents.

7.2 The Seller warrants that on Completion:

7.2.1 the Seller will be or will be able to be the registered proprietor of the Lease and will own the rest of the Property free from any Affecting Interests;

7.2.2 the Seller will have the capacity to complete;

7.2.3 there will be no unsatisfied judgment, order or writ affecting the Property;

7.2.4 the Seller has no knowledge of any current or threatened claims, notices or proceedings that may lead to a judgment, order or writ affecting the Property;

7.2.5 the Seller is not aware of any encroachments by or upon the Property except as disclosed. This warranty does not extend to the location of any dividing fence;

7.2.6 there will be no Breach of Covenant except as disclosed in this Contract; and

7.2.7 unless disclosed in the Schedule or elsewhere in this Contract, the Lease is a Non-Land Rent Lease and not a Land Rent Lease.

7.3 The Seller gives no warranties as to the present state of repair of any of the Improvements or condition of the Land, except as required by law.

8. Adjustments

8.1 The Seller is entitled to the Income and is liable for all Land Charges up to and including Completion after which the Buyer will be entitled to the Income and liable for the Land Charges, provided the Seller will be liable for all land tax in respect of the Property if the 'Land Tax to be adjusted?' option on the Schedule is marked 'No'.

8.2 The parties must pay any adjustment of the Income and Land Charges calculated under clause 8.1 on Completion.

8.3 Any concessional Land Charges must be adjusted on the concessional amount of those Land Charges.

8.4 If any of the Land Charges have not been assessed on Completion, the Buyer will be entitled to retain in the Buyer Solicitor trust account from the Balance of the Price an amount sufficient to pay the Seller's proportion of those Land Charges.

8.5 Attached are copies of the relevant invoices for the cost of obtaining the Building and Compliance Inspection Report and Pest Inspection Report. The Buyer must pay to the Seller the cost of obtaining the Building and Compliance Inspection Report and the Pest Inspection Report as required by section 18 of the Sale of Residential Property Act on Completion.

9. Terms of possession

9.1 The Seller must give the Buyer vacant possession of the Property on Completion unless otherwise marked in the Schedule.

9.2 If the Property is sold subject to a tenancy, the Seller has:

9.2.1 attached to this Contract a copy of the signed Tenancy Agreement; or

9.2.2 completed the tenancy summary on page 2 of this Contract.

9.3 If the Property is sold subject to a tenancy:

9.3.1 the Seller warrants that except as disclosed in this Contract:

(a) if applicable, the rental bond has been provided in accordance with the Residential Tenancies Act;

(b) if applicable, the Seller has complied with the Residential Tenancies Act;

Block 38 Section 32 Canberra

(c) if applicable, the Seller has no notice of any application by the tenant for the release of the rental bond;

(d) no notices relating to the tenancy have been served on the Seller or any agent of the Seller or on the tenant other than as disclosed in this Contract and there are no outstanding claims or disputes with the tenant;

(e) there is no unremedied breach of the Tenancy Agreement by the tenant or the Seller; and

(f) if applicable, the Tenancy Agreement incorporates:

(i) the Prescribed Terms; and

(ii) any other terms approved by the Residential Tenancies Tribunal.

9.3.2 The Seller must hand to the Buyer on Completion:

(a) any written Tenancy Agreement to which this Contract is subject;

(b) a notice of attornment;

(c) if applicable, any notice required to be signed by the Seller to transfer the rental bond by the Office of Rental Bonds to the Buyer; and

(d) if applicable, any other notice required to be signed by the Seller under the Residential Tenancies Act.

9.3.3 The Buyer indemnifies the Seller in relation to any liability which the Seller incurs or to which the Seller is subject under the tenancy because of matters occurring after Completion.

10. Inspection and condition of Property

10.1 The Buyer may on reasonable notice to the Seller and at reasonable times inspect the Property before Completion.

10.2 The Seller must leave the Property clean and tidy on Completion.

11. Inspection of building file

11.1 The Seller must, if requested by the Buyer, give to the Buyer all authorities necessary to enable the Buyer (or Buyer's nominee) to inspect and obtain at the Buyer's expense, copies of:

11.1.1 any document in relation to the Land and Improvements held by any government or statutory authority; and

11.1.2 any notices issued by any authority in relation to the Land and Improvements.

12. Additional Seller obligations

12.1 Except for any Breach of Covenant disclosed in this Contract, the Seller must before Completion:

12.1.1 comply with any notice issued by any authority before the Date of this Contract which requires work to be done or money to be spent on or in relation to the Property or the Lease;

12.1.2 obtain approval for any Development conducted on the Land;

12.1.3 comply with the Lease to the extent to which the Seller is required to comply up to Completion;

12.1.4 comply with any obligations on the Seller in a registered restrictive covenant affecting the Lease; and

12.1.5 give the Buyer notice of any material change (other than fair wear and tear) the Seller becomes aware of in the matters disclosed in the Required Documents, since the date of each of the relevant Required Documents.

13. Electronic transaction

13.1 In this clause 13, the following words mean:

Adjustment Figures mean details of the adjustments to be made to the Price under this Contract;

Completion Time means the time of day on the Date for Completion when the Electronic Transaction is to be Completed;

Conveyancing Transaction has the meaning given in the Participation Rules;

Digitally Signed has the meaning given in the Participation Rules and **Digitally Sign** has a corresponding meaning;

Discharging Mortgagee means any discharging mortgagee, chargee, covenant chargee or caveator whose provision of a Digitally Signed discharge of mortgage, discharge of charge or withdrawal of caveat is required in order for unencumbered title to the Lease to be transferred to the Buyer;

ECNL means the *Electronic Conveyancing National Law (ACT) Act 2020* (ACT);

Effective Date means the date on which the Conveyancing Transaction is agreed to be an Electronic Transaction under clause 13.2.2 or, if clause 13.2.1 applies, the Date of this Contract;

Bill 30 Section 32 Cancelled

Electronic Document means a caveat, a Crown lease or an instrument as defined in the Land Titles Act which may be created and Digitally Signed in an Electronic Workspace;

Electronic Transaction means a Conveyancing Transaction to be conducted for the parties by their legal representatives as Subscribers using an ELN and in accordance with the ECNL and the Participation Rules;

Electronic Transfer means a transfer of the Lease under the Land Titles Act to be prepared and Digitally Signed in the Electronic Workspace established for the purposes of the parties' Conveyancing Transaction;

Electronic Workspace has the meaning given in the Participation Rules;

Electronically Tradeable means a land title dealing that can be lodged electronically;

ELN has the meaning given in the Participation Rules;

FRCGW Remittance means a remittance which the Buyer must make in accordance with the Withholding Law and clauses 51.4 to 51.8;

GSTRW Payment means a payment which the Buyer must make in accordance with the Withholding Law and clauses 53.5 to 53.9;

Incoming Mortgagee means any mortgagee who is to provide finance to the Buyer on the security of the Lease and to enable the Buyer to pay the whole or part of the price;

Land Registry has the meaning given in the Participation Rules;

Lodgment Case has the meaning given in the Participation Rules;

Mortgagee Details mean the details which a party to the Electronic Transaction must provide about any Discharging Mortgagee of the Land as at Completion;

Nominated ELN means the ELN specified in the Schedule;

Participation Rules mean the participation rules as determined by the ECNL;

Populate means to complete data fields in the Electronic Workspace;

Prescribed Requirement has the meaning given in the Participation Rules;

Subscribers has the meaning given in the Participation Rules; and

Title Data means the details of the title to the Lease made available to the Electronic Workspace by the Land Registry.

13.2 This Conveyancing Transaction is to be conducted as an Electronic Transaction and this Contract is amended as required if:

13.2.1 this Contract says that it is an Electronic Transaction; or

13.2.2 the parties otherwise agree that it is to be conducted as an Electronic Transaction.

13.3 However, this Conveyancing Transaction is not to be conducted as an Electronic Transaction:

13.3.1 if the title to the Lease is not Electronically Tradeable or the transfer of the Lease is not eligible be lodged electronically; or

13.3.2 if, at any time after the Effective Date, but at least 14 days before the Date for Completion, a party serves a notice on the other party stating a valid reason why it cannot be conducted as an Electronic Transaction.

13.4 If, because of clause 13.3.2, this Conveyancing Transaction is not to be conducted as an Electronic Transaction:

13.4.1 each party must:

(a) bear equally any disbursements or fees; and

(b) otherwise bear that party's own costs;

incurred because this Conveyancing Transaction was to be conducted as an Electronic Transaction; and

13.4.2 if a party has paid all of a disbursement or fee which by reason of this clause, is to be borne equally by the parties, that amount must be adjusted on Completion.

13.5 If this Conveyancing Transaction is to be conducted as an Electronic Transaction:

13.5.1 to the extent that any other provision of this Contract is inconsistent with this clause, the provisions of this clause prevail and this Contract is amended to give full effect to the Electronic Transaction;

13.5.2 without limiting clause 13.5.1, clause 5.2 does not apply;

13.5.3 the parties must conduct the Electronic Transaction:

(a) in accordance with the Participation Rules and the ECNL; and

(b) using the Nominated ELN, unless the parties otherwise agree;

13.5.4 a party must pay the fees and charges payable by that party to the ELN and the

Block 38 Section 32 Canberra

Land Registry as a result of this transaction being an Electronic Transaction; and

13.5.5 a document which is an Electronic Document is served as soon as it is first Digitally Signed in the Electronic Workspace on behalf of the party required to serve it.

13.6 The Seller must within 7 days of the Effective Date:

13.6.1 create an Electronic Workspace;

13.6.2 Populate the Electronic Workspace with Title Data, the Date for Completion and, if applicable, Mortgagee Details; and

13.6.3 invite the Buyer and any Discharging Mortgagee to the Electronic Workspace.

13.7 If the Seller has not created an Electronic Workspace in accordance with clause 13.6, the Buyer may create an Electronic Workspace. If the Buyer creates the Electronic Workspace the Buyer must:

13.7.1 Populate the Electronic Workspace with Title Data;

13.7.2 create and Populate the Electronic Transfer;

13.7.3 Populate the Electronic Workspace with the Date for Completion and a nominated Completion Time; and

13.7.4 invite the Seller and any Incoming Mortgagee to join the Electronic Workspace.

13.8 Within 7 days of receiving an invitation from the Seller to join the Electronic Workspace, the Buyer must:

13.8.1 join the Electronic Workspace;

13.8.2 create and Populate the Electronic Transfer;

13.8.3 invite any Incoming Mortgagee to join the Electronic Workspace; and

13.8.4 Populate the Electronic Workspace with a nominated Completion Time.

13.9 If the Buyer has created the Electronic Workspace the Seller must within 7 days of being invited to the Electronic Workspace:

13.9.1 join the Electronic Workspace;

13.9.2 Populate the Electronic Workspace with Mortgagee Details, if applicable; and

13.9.3 invite any Discharging Mortgagee to join the Electronic Workspace.

13.10 To complete the financial settlement schedule in the Electronic Workspace:

13.10.1 the Seller must provide the Buyer with Adjustment Figures at least 2 Business Days before the Date for Completion;

13.10.2 the Buyer must confirm the Adjustment Figures at least 1 Business Day before the Date for Completion; and

13.10.3 if the Buyer must make a GSTRW Payment and / or an FRCGW Remittance, the Buyer must Populate the Electronic Workspace with the payment details for the GSTRW Payment or FRCGW Remittance payable to the ATO at least 2 Business Days before the Date for Completion.

13.11 Before Completion, the parties must ensure that:

13.11.1 all Electronic Documents which a party must Digitally Sign to complete the Electronic Transaction are Populated and Digitally Signed;

13.11.2 all certifications required by the ECNL are properly given; and

13.11.3 they do everything else in the Electronic Workspace which that party must do to enable the Electronic Transaction to proceed to Completion.

13.12 If Completion takes place in the Electronic Workspace:

13.12.1 payment electronically on Completion of the Balance of the Price in accordance with clause 2.6 is taken to be payment by a single unendorsed bank cheque; and

13.12.2 clauses 51.4.3, 51.4.4, 53.8 and 53.9 do not apply.

13.13 If the computer systems of any of the Land Registry, the ELN, the ATO or the Reserve Bank of Australia are inoperative for any reason at the Completion Time agreed by the parties, a failure to complete this Contract for that reason is not a default under this Contract on the part of either party.

13.14 If the computer systems of the Land Registry are inoperative for any reason at the Completion Time agreed by the parties, and the parties agree that financial settlement is to occur despite this, then on financial settlement occurring:

13.14.1 all Electronic Documents Digitally Signed by the Seller, any discharge of mortgage, withdrawal of caveat or other Electronic Document forming part of the Lodgment Case for the Electronic Transaction shall be taken to have been unconditionally and irrevocably delivered to the Buyer or

Block 30 Section 32 Canberra

the Buyer's mortgagee at the time of financial settlement; and

13.14.2 the Seller shall be taken to have no legal or equitable interest in the Property.

13.15 If the parties do not agree about the delivery before Completion of one or more documents or things that cannot be delivered through the Electronic Workspace, the party required to deliver the documents or things:

13.15.1 holds them on Completion in escrow for the benefit of the other party; and

13.15.2 must immediately after Completion deliver the documents or things to, or as directed by the party entitled to them.

14. Off the plan purchase and Compliance Certificate

14.1 If the Lease contains a Building and Development Provision which has not been complied with at the Date of this Contract, and clause 4.2 does not apply:

14.1.1 where the Seller is obliged to construct Improvements by Completion, before the Date for Completion, the Seller must at the Seller's expense complete the construction of the Improvements promptly and in a good and workmanlike manner substantially in accordance with the proposed plan, specifications and inclusions list attached; and

14.1.2 on or before Completion, the Seller must at the Seller's expense give to the Buyer evidence that a Compliance Certificate has been obtained.

15. Goods

15.1 The Seller gives no warranties as to the present state of repair of any of the Goods except as required by law.

15.2 The Goods are included in the Price.

15.3 The Seller warrants that the Goods are unencumbered and that the Seller has the right to sell them.

15.4 The Goods become the Buyer's property on Completion.

15.5 Except for fair wear and tear, the Seller must give the Goods to the Buyer on Completion in the same state of repair they are in at the Date of this Contract.

16. Errors and misdescriptions

16.1 If, before Completion, the Buyer becomes aware of an error in the description of the Property the Buyer may:

16.1.1 identify whether the error is material or not material, and ask the Seller to arrange for the error to be corrected before Completion; and

16.1.2 if the error is not corrected before Completion:

(a) for an error that is material — rescind this Contract, or complete this Contract and make a claim for compensation; and

(b) for an error that is not material — complete this Contract and make a claim for compensation.

16.2 This clause applies even if the Buyer did not take notice of or rely on anything in this Contract containing or giving rise to the error or misdescription.

16.3 The Buyer is not entitled to compensation to the extent the Buyer knew the true position before the Date of this Contract.

17. Compensation claims by Buyer

17.1 To make a claim for compensation (including a claim under clause 16) the Buyer must give notice to the Seller before Completion specifying the amount claimed and:

17.1.1 the Seller can rescind if in the case of a claim that is not a claim for delay:

(a) the total amount claimed exceeds 5% of the Price;

(b) the Seller gives notice to the Buyer of an intention to rescind; and

(c) the Buyer does not give notice to the Seller waiving the claim within 14 days after receiving the notice; and

17.1.2 if the Seller does not rescind under clause 17.1.1, the parties must complete and:

(a) the lesser of the total amount claimed and 5% of the Price must be paid out of the Price to, and held by, the Stakeholder until the claim is finalised or lapses;

(b) the amount held is to be invested by the Stakeholder (at the risk of the party who becomes entitled to it) with an Australian bank in an interest-bearing account at call in the name of

Block 39 Section 32 Campbell

the Stakeholder in trust for the Seller and the Buyer;

(c) the claim must be finalised by an arbitrator appointed by the parties or, if an appointment is not made within 28 days of Completion, by an arbitrator appointed by the President of the Law Society of the Australian Capital Territory at the request of a party;

(d) the decision of the arbitrator is final and binding;

(e) the costs of the arbitration must be shared equally by the parties unless otherwise determined by the arbitrator. For clarity, the arbitrator has the power to award indemnity costs on a legal basis against either party;

(f) the Buyer is not entitled, in respect of the claim, to more than the total amount claimed and the costs of the Buyer;

(g) interest on the amount held, after deduction of all taxes and bank charges, Stakeholder administration fee and other similar charges and expenses, must be paid to the parties equally or as otherwise determined by the arbitrator; and

(h) the claim lapses if the parties do not appoint an arbitrator and neither party asks the President of the Law Society of the Australian Capital Territory to appoint an arbitrator within 90 days after Completion and the amount held by the Stakeholder must be paid immediately to the Seller without any further authority being necessary.

18. Notice to Complete and Default Notice

18.1 If Completion does not take place in accordance with clause 2.8, either party may, at any time after the Date for Completion, serve the other party a Notice to Complete.

18.2 A Notice to Complete must appoint a time during business hours and a date being not less than 14* days after service of the Notice to Complete (excluding the date of service) by which and a place in Canberra at which to complete this Contract.

18.3 At the time the Notice to Complete is served the party serving the Notice to Complete must:

18.3.1 not be in default; and

18.3.2 be ready willing and able to complete but for some default or omission of the other party.

18.4 Completion at the time date and place specified in the Notice to Complete is an essential term.

18.5 Where one party is in default (other than failing to complete) the other party may at any time after the default serve the party in default a Default Notice.

18.6 A Default Notice:

18.6.1 must specify the default;

18.6.2 must require the party served with the Default Notice to rectify the default within 7* days after service of the Default Notice (excluding the date of service), except in the case of a Default Notice for the purposes of clause 52.6, in which case the period specified in clause 52.6 will apply; and

18.6.3 cannot be used to require a party to complete this Contract.

18.7 At the time the Default Notice is served, the party serving the Default Notice must not be in default.

18.8 The time specified in a Default Notice to rectify the specified default is an essential term.

18.9 Clauses 19 or 20 will apply as appropriate where the party served does not comply with the Notice to Complete or the Default Notice which complies with this clause.

18.10 If the party serving a notice under this clause varies the time referred to in the notice at the request of the other party, the time agreed to in the variation remains an essential term. The consent to the variation must be in writing and be served on the other party.

18.11 The parties agree that the time referred to in clauses 18.2 and 18.6.2 is fair and reasonable.

19. Termination — Buyer default

19.1 If the Buyer does not comply with a Notice to Complete or a Default Notice or is otherwise in breach of an essential term then the Seller may by notice served on the Buyer terminate and may then keep, or recover and keep, the Deposit (except so much of it as exceeds 10% of the Price) and either:

19.1.1 sue the Buyer for breach; or

19.1.2 resell the Property and any deficiency arising on the resale and all expenses of and incidental to the resale or attempted resale and the Buyer's default are

Block 32 Section 32 Campbell

* Alter as necessary

recoverable by the Seller from the Buyer as liquidated damages provided the Seller has entered into a contract for the resale of the Property within 12 months of termination.

19.2 In addition to any money kept or recovered under clause 19.1, the Seller may retain on termination any other money paid by the Buyer as security for any damages awarded to the Seller arising from the Buyer's default provided that proceedings for the recovery of damages are commenced within 12 months of termination.

20. Termination — Seller default

20.1 If the Seller does not comply with a Notice to Complete or a Default Notice or is otherwise in breach of an essential term the Buyer may by notice served on the Seller either:

20.1.1 terminate and seek damages; or

20.1.2 enforce without further notice any other rights and remedies available to the Buyer.

20.2 If the Buyer terminates, the Stakeholder is authorised to refund to the Buyer immediately any money paid on account of the Price.

21. Rescission

21.1 Unless section 15 of the Sale of Residential Property Act applies, if this Contract is rescinded, it is rescinded from the beginning, and unless the parties otherwise agree:

21.1.1 the Deposit and all other money paid by the Buyer must be refunded to the Buyer immediately without any further authority being necessary; and

21.1.2 neither party is liable to pay the other any amount for damages, costs or expenses.

22. Damages for delay in Completion

22.1 If Completion does not occur by the Date for Completion, due to the default of either party, the party who is at fault must pay the other party as liquidated damages on Completion:

22.1.1 if the defaulting party is the Seller, interest on the Price at the rate this Contract says on page 2, calculated on a daily basis from the date 7 days after the Date for Completion to Completion;

22.1.2 if the defaulting party is the Buyer, interest on the Price at the rate this Contract says on page 2, calculated on a daily basis from the date 7 days after the Date for Completion to Completion; and

22.1.3 the amount this Contract says on page 2 to be applied towards any legal costs and disbursements incurred by the party not at fault if Completion occurs later than 7 days after the Date for Completion.

22.2 Whether or not percentages are inserted in clauses 22.1.1 or 22.1.2 the party at fault must pay the amount specified in clause 22.1.3 in addition to any other damages to which the party not at fault is entitled both at law and under this Contract.

22.3 The parties agree that:

22.3.1 the amount of any damages payable under clause 22.1.1 or clause 22.1.2 to the party not in default is a genuine and honest pre-estimate of loss to that party for the delay in Completion, and

22.3.2 the damages must be paid on Completion.

23. Foreign Buyer

23.1 The Buyer warrants the Commonwealth Treasurer cannot prohibit and has not prohibited the transfer of the Lease under the *Foreign Acquisitions and Takeovers Act 1975* (Cth).

23.2 This clause is an essential term.

24. GST

24.1 If a party must pay the Price or provide any other consideration to another party under this Contract, GST is not to be added to the Price or amount, unless this Contract provides otherwise.

24.2 If the Price is stated in the Schedule to exclude GST and the sale of the Property is a taxable supply, the Buyer must pay to the Seller on Completion an amount equal to the GST payable by the Seller in relation to the supply.

24.3 If under this Contract a party (Relevant Party) must make an adjustment, pay an amount to another party (excluding the Price but including the Deposit if it is released or forfeited to the Seller) or pay an amount payable by or to a third party:

24.3.1 the Relevant Party must adjust or pay at that time any GST added to or included in the amount; but

24.3.2 if this Contract says this sale is a taxable supply, and payment would entitle the Relevant Party to claim an input tax credit, the adjustment or payment is to be worked out by deducting any input tax credit to which the party receiving the adjustment or payment is or was entitled multiplied by the GST Rate.

24.4 If this Contract says this sale is the supply of a going concern:

Block 19 Section 32 Campbell

24.4.1 the parties agree the supply of the Property is the supply of a going concern;

24.4.2 the Seller must on Completion supply to the Buyer all of the things that are necessary for the continued operation of the enterprise;

24.4.3 the Seller must carry on the enterprise until Completion;

24.4.4 the Buyer warrants to the Seller that on Completion the Buyer will be registered or required to be registered; and

24.4.5 if for any reason (and despite clauses 24.1 and 24.4.1) the sale of the Property is not the supply of a going concern but is a taxable supply:

(a) the Buyer must pay to the Seller on demand the amount of any GST payable by the Seller in respect of the sale of the Property; and

(b) the Buyer indemnifies the Seller against any loss or expense incurred by the Seller in respect of that GST and any breach of clause 24.4.5(a).

24.5 If this Contract says the margin scheme applies:

24.5.1 the Seller warrants that it can use the margin scheme; and

24.5.2 the Buyer and Seller agree that the margin scheme is to apply,

in respect of the sale of the Property.

24.6 If this Contract says the sale is a taxable supply, does not say the margin scheme applies to the sale of the Property, and the sale is in fact not a taxable supply, then the Seller must pay the Buyer on Completion an amount of one-eleventh of the Price.

24.7 Unless the margin scheme applies the Seller must, on Completion, give the Buyer a tax invoice for any taxable supply by the Seller by or under this Contract.

25. Power of attorney

25.1 Any party who signs this Contract or any document in connection with it under a power of attorney must, on request and without cost, provide the other party with a true copy of the registered power of attorney.

26. Notices claims and authorities

26.1 Notices, claims and authorities required or authorised by this Contract must be in writing.

26.2 To serve a notice a party must:

26.2.1 leave it at; or

26.2.2 send it by a method of post requiring acknowledgment of receipt by the addressee to,

the address of the person to be served as stated in the Schedule or as notified by that person to the other as that person's address for service under this Contract; or

26.2.3 serve it on that party's solicitor in any of the above ways; or

26.2.4 deliver it to an appropriate place in the facilities of a document exchange system in which the recipient solicitor has receiving facilities (and in the latter case service is deemed effected on the Business Day following delivery); or

26.2.5 transmit it by email to a party's solicitor to the email address for that solicitor as stated in the Schedule or as notified by that solicitor to the other solicitor as the email address for service under this Contract.

26.3 A party's solicitor may give a notice, claim or authority on behalf of that party.

27. Unit title

27.1 The following clauses 28 to 39 inclusive apply if the Property is a Unit.

28. Definitions and interpretation

28.1 A reference in these clauses 28 to 39 inclusive to a section or Part is a reference to a section or Part of the Unit Titles Management Act.

28.2 For the purposes of a claim for compensation pursuant to clause 39, the provisions of clause 17 will apply provided that clause 17.1.1(c) is amended to read "the Buyer does not give notice to the Seller waiving the claim, or so much of it as exceeds 5% of the Price within 14 days after receiving the notice".

29. Title to the Unit

29.1 Clauses 3.1, 3.2 and 3.3 do not apply.

29.2 The Unit Title is or will before Completion be granted under the Planning Act and is or will before Completion be registered under the *Land Titles (Unit Titles) Act 1970* (ACT).

29.3 The Unit Title is transferred subject to the Units Plan under which the lease to the Unit is held.

30. Buyer rights limited

30.1 In addition to clause 6, the Buyer cannot make any requisition on title or make a claim for compensation in respect of any Breach of Covenant of the Unit Title, any breach of the

Block 18 Section 32 Campbell

lease of the Common Property or breach of rules of the Owners Corporation disclosed in this Contract.

31. Adjustment of contribution

31.1 Any adjustment under clause 8 must include an adjustment of the contributions to the Owners Corporation under section 78 and section 89 of the Unit Titles Management Act.

32. Inspection of Unit

32.1 For the purposes of clause 10.1 Property includes the Common Property.

33. Seller warranties

33.1 The Seller warrants that at the Date of this Contract:

33.1.1 to the Seller's knowledge, there are no unfunded latent or patent defects in the Common Property or Owners Corporation assets, other than the following:

(a) defects arising through fair wear and tear; and

(b) defects disclosed in this Contract;

33.1.2 the Owners Corporation records do not disclose any defects to which the warranty in clause 33.1.1 applies;

33.1.3 to the Seller's knowledge, there are no actual, contingent or expected unfunded liabilities of the Owners Corporation that are not part of the Owners Corporation's normal operating expenses, other than liabilities disclosed in this Contract;

33.1.4 the Owners Corporation records do not disclose any liabilities of the Owners Corporation to which the warranty in clause 33.1.3 applies;

33.1.5 the Seller or any occupier of the Unit has not committed any act or omission which may cause the Owners Corporation to incur any costs or perform any repairs;

33.1.6 there is no amount payable to the Owners Corporation by the Seller other than a contribution due under section 78 and section 89 of the Unit Titles Management Act; and

33.1.7 except for an unregistered Units Plan, the rules of the Owners Corporation are, as appropriate:

(a) as set out in Schedule 4 to the Unit Titles Management Act; or

(b) in respect of a corporation established under the *Unit Titles Act 1970 (repealed)* and that was in existence immediately prior to 30 March 2012, the articles in force immediately prior to 30 March 2012; or

(c) in respect of a corporation established under the Unit Titles Act and that was in existence immediately prior to 30 March 2012, the articles in force immediately prior to 30 March 2012;

except for any alterations to those rules registered under section 108.

33.2 For clauses 33.1.1 to 33.1.4 inclusive, a Seller is taken to have knowledge of a thing if the Seller has actual knowledge, or ought reasonably to have knowledge, of that thing.

33.3 The Seller warrants that at Completion to the Seller's knowledge, there are no circumstances (other than circumstances disclosed in this Contract) in relation to the affairs of the Owners Corporation likely to significantly prejudice the Buyer.

33.4 For the purposes of clause 7, Property includes the Common Property.

33.5 These warranties are in addition to those given in clause 7.

34. Damage or destruction before Completion

34.1 If the Unit is destroyed or substantially damaged before Completion not due to the fault of either party then either party may by notice to the other rescind and clause 21 applies.

34.2 For the purposes of clause 34.1, the Unit is deemed to be substantially damaged if though not destroyed is unfit for the use to which it was being put at the Date of this Contract or, if not being used at that time, for the purpose permitted by the Unit Title.

35. Notice to Owners Corporation

35.1 The parties must comply with the rules of the Owners Corporation in relation to notification of the sale and purchase of the Unit.

36. Unit Title Certificate

36.1 On Completion the Buyer must pay to the Seller the fee as determined by the Minister pursuant to section 119(7) of the Units Title Management Act for the Unit Title Certificate attached.

Image of Section 32 Sample

37. Unregistered Units Plan

Warning: The following clauses 37, 38 and 39 do not encompass all obligations, rights and remedies under Part 2.9 of the Property Act for off the plan contracts.

37.1 This clause 37 applies if at the Date of this Contract, the Units Plan has not been registered.

37.2 The Seller must attach a copy of the proposed Units Plan or a sketch plan showing the location and dimensions of the Unit sufficient to enable the Buyer to determine the location and dimensions of the Unit in relation to other units and the Common Property in the proposed development.

37.3 If the Units Plan is not registered by the date specified in the Schedule, or elsewhere in this Contract, the Buyer may at any time after that date by notice served on the Seller require that the Units Plan be registered within 14 days of the service of the notice. If the Units Plan is not registered within the time limited by the notice the Buyer may at any time after expiry of the time in the notice rescind and clause 21 will apply.

37.4 If the Seller notifies the Buyer that the Units Plan is registered before rescission under this clause, the Buyer will not be entitled to rescind under this clause.

37.5 The Buyer cannot make any objection or requisition on title or claim for compensation in respect of:

37.5.1 any minor variations to the Unit between the plan attached, and the Units Plan registered by the Registrar General; or

37.5.2 any minor alterations required by an authority or the Registrar General in the number, size, location or Unit Entitlement of any other unit in the Units Plan or in or to the Common Property provided the proportion of the Unit Entitlement of the Unit to the other units in the Units Plan is not varied.

In this clause, a minor variation is any variation less than 5% to either the size or value of the Unit described in the plan attached.

37.6 After the Owners Corporation has been constituted under section 8, the Seller must cause the Owners Corporation to comply with the rules of the Owners Corporation and with Parts 2, 3, 4, 5 and 7 to the extent to which the Owners Corporation is required by law to comply with those provisions up to the Date for Completion.

37.7 The Seller must not permit the Owners Corporation to vary the rules of the Owners Corporation from those set out in Schedule 4 of the Unit Title Management Act.

37.8 If clause 37.1 applies, the Seller must give to the Buyer a Unit Title Certificate at the Buyer's expense at least 7 days before Completion.

37.9 The parties acknowledge that the following must form part of the Contract:

37.9.1 a Disclosure Statement for the Unit that complies with the requirements of section 260 of the Property Act; and

37.9.2 if a right to approve the keeping of animals during the Developer Control Period is reserved — details of the reservation, including the kind and number of animals.

37.10 The Seller warrants that the information disclosed in the Disclosure Statement, including information in any Disclosure Update Notice, is accurate.

38. Rescission of Contract

38.1 The Buyer may, by written notice given to the Seller, rescind this Contract if:

38.1.1 there would be a breach of a warranty provided in any of clauses 33.1.1, 33.1.2, 33.1.3, 33.1.4 or 33.3, were this Contract completed at the time it is rescinded; or

38.1.2 there would be a breach of a warranty provided in clause 37.10:

(a) were this Contract completed at the time it is rescinded; and

(b) the Buyer is significantly prejudiced by the breach,

and the breach does not relate to an amendment to the Development Statement that is an Excluded Change.

38.2 A notice must be given:

38.2.1 under clause 38.1.1:

(a) if this Contract is entered before the Units Plan for the Unit is registered — not later than 3 days before the Buyer is required to complete this Contract; or

(b) in any other case — not later than 14 days after the later of the following happens:

(i) the Date of this Contract; and

(ii) another period agreed between the Buyer and Seller ends; or

Prof 38 Section 32 Campbell

38.2.2 under clause 38.1.2 – at any time before the Buyer is required to complete this Contract.

38.3 If the Buyer rescinds this Contract, the Seller must repay any amount paid to the Seller towards the purchase of the Unit and otherwise the provisions of clause 21 will apply.

39. Claims for compensation

39.1 This clause 39 applies if, before Completion, the Buyer reasonably believes that, except as disclosed in this Contract, there would be a breach of a warranty established under any of clauses 33.1.1, 33.1.2, 33.1.3, 33.1.4, 33.3 or 37.10 were this Contract to be completed.

39.2 The Buyer may, by written notice given to the Seller:

39.2.1 tell the Seller:

(a) about the breach; and

(b) that the Buyer will complete this Contract; and

39.2.2 claim compensation for the breach.

39.3 A notice under clause 39.2 must be given:

39.3.1 if this Contract is entered before the Units Plan for the Unit is registered — not later than 3 days before the Buyer is required to complete this Contract; or

39.3.2 in any other case — not later than 14 days after the later of the following happens:

(a) the Buyer's copy of the Contract is received by the Buyer;

(b) another period agreed between the Buyer and Seller ends.

39.4 The Buyer may not claim compensation under this clause 39 only because of the breach of a warranty related to an amendment to the Development Statement that is an Excluded Change.

40. Community title

40.1 The following clauses 41 to 50 inclusive apply if the Property is, or will on Completion form, a Lot within a Community Title Scheme.

41. Definitions and interpretation

41.1 A reference in these clauses 40 to 50 inclusive to a section or Part is a reference to a section or Part of the Community Title Act.

42. Buyer rights limited

42.1 In addition to clause 6, the Buyer cannot make any requisition on title or make a claim for compensation in respect of any breach of the lease of the Common Property or breach of rules or by-laws of the Community Title Body Corporate disclosed in this Contract.

43. Adjustment of contribution

43.1 Any adjustment under clause 8 must include an adjustment of the contributions to the fund under section 45.

44. Inspection of property

44.1 For the purposes of clause 10.1 Property includes the Common Property.

45. Unregistered Community Title Scheme

45.1 This clause 45 applies if at the Date of this Contract, the Community Title Scheme has not registered.

45.2 The Seller must attach a copy of the proposed Community Title Master Plan, or a sketch plan showing the location and dimensions of the Lot sufficient to enable the Buyer to determine the location and dimensions of the Lot in relation to other lots and the Common Property in the proposed scheme.

45.3 The Seller must attach a copy of the proposed Community Title Management Statement.

45.4 The Buyer cannot make any objection or requisition on title or claim for compensation in respect of:

45.4.1 any minor variations to the Lot between the plan attached, and the registered Community Title Master Plan; or

45.4.2 any minor alterations required by an authority or the Registrar General in the number, size, location or entitlement of any other Lot in the Community Title Scheme or in or to the Common Property provided the proportion of the entitlement of the Lot to the other lots in the Community Title Scheme is not varied; or

45.4.3 any minor variations between the proposed Community Title Management Statement and the registered Community Title Management Statement.

In this clause, a minor variation is any variation less than 5% to either the size or value of the Lot described in the plan attached and referred to in the proposed Community Title Management Statement.

45.5 The Seller must not permit the Community Title Body Corporate to vary the by-laws of the

Block 58 Section 32 Campbell

Community Title Scheme from those set out in Schedule 1 of the Community Title Act, unless otherwise disclosed in this Contract.

45.6 After the Community Title Body Corporate has been constituted under section 30, the Seller must cause the Community Title Body Corporate to comply with Part 8 to the extent to which the Community Title Body Corporate is required by law to comply with those provisions up to the Date for Completion.

46. Incomplete development of Community Title Scheme

46.1 This clause 46 applies if at the Date of this Contract, development of the Community Title Scheme has not completed.

46.2 Until the development of a Community Title Scheme is finished, the Developer warrants to the Buyer that the development will be carried out in accordance with the scheme.

46.3 Without limiting the damages recoverable for breach of the warranty in clause 46.2, the Buyer may recover damages for the loss of a reasonably expected capital appreciation of the Lot that would have resulted from completion of the development in accordance with the terms of the Community Title Scheme.

47. Incomplete development of Lot

47.1 This clause 47 applies if at the Date of this Contract, the Lot is to be developed or further developed in accordance with the Community Title Scheme. For clarity, this clause does not apply if an unconditional Compliance Certificate has issued before the Date of this Contract and the Seller gives to the Buyer evidence acceptable to the Registrar General that an unconditional Compliance Certificate has issued for the Lot, or if the Seller gives an unconditional Compliance Certificate to the Buyer on Completion.

47.2 The Buyer becomes bound to develop the Lot in accordance with the Community Title Scheme.

47.3 The Seller must give written notice of the proposed sale of the Lot to the Planning and Land Authority.

47.4 The Buyer must:

47.4.1 give to the Planning and Land Authority a written undertaking to develop the Lot in accordance with the Community Title Scheme (if a form is approved for an undertaking, the form must be used); and

47.4.2 give the Planning and Land Authority any security required by the Planning and Land Authority, within 28 days after notice of the transaction was given to the Planning and Land Authority, for the development of the Lot in accordance with the Community Title Scheme.

48. Required first or top sheet

48.1 The Seller must give to the Buyer, before the Buyer enters into this Contract, a Section 67 Statement.

48.2 The Section 67 Statement must:

48.2.1 state that the Lot is included in a Community Title Scheme that imposes obligations on the owner of the Lot;

48.2.2 state the name and address of:

(a) the body corporate of the scheme; or

(b) if it is the duty of the Community Title Body Corporate manager to act for the Community Title Body Corporate in supplying Section 56 Certificates — the manager;

48.2.3 state the amount of annual contributions currently fixed by the Community Title Body Corporate as payable by the owner of the Lot;

48.2.4 identify improvements on common property of the scheme for which the owner of the Lot is responsible;

48.2.5 be signed by the Seller or a person authorised by the Seller; and

48.2.6 be substantially complete.

48.3 The Seller must attach to this Contract, as a first or top sheet, a copy of the Section 67 Statement given to the Buyer under clause 48.1.

48.4 The Buyer may rescind this Contract if:

48.4.1 the Seller has not complied with clauses 48.1 and 48.3; and

48.4.2 Completion has not taken place.

49. Notice to Community Title Body Corporate

49.1 The parties must comply with the rules and by-laws of the Community Title Body Corporate in relation to notification of the sale and purchase of the Lot.

50. Section 56 Certificate

50.1 The Seller must give to the Buyer a Section 56 Certificate at least 7 days before Completion.

50.2 On Completion, the Buyer must pay to the Seller the fee charged for the Section 56 Certificate.

Block 1 Section 32 Campbell

51. Foreign Resident Withholding Tax

Warning: The questions in the Schedule regarding the Relevant Price and the Clearance Certificates are not binding, and are included to remind the parties of their obligations under the Withholding Law.

Warning: The following clauses 51.1 to 51.8 are subject to the Withholding Law, and do not encompass all obligations under the Withholding Law.

51.1 In this clause 51 the following words have the following meanings:

CGT Asset has the meaning in the *Income Tax Assessment Act 1997*;

Clearance Certificate means a certificate issued under section 14-220 of the Withholding Law that covers the date of Completion;

Relevant Percentage means the percentage amount stated in section 14-200(3)(a) and 14-205(4)(a) of the Withholding Law;

Relevant Price means the higher of:

- the Price (including GST); and
- the market value of the CGT Assets sold under this Contract;

as at the Date of this Contract;

Variation Certificate means a certificate issued under section 14-235 of the Withholding Law that covers the date of Completion;

Withholding Amount means, subject to clauses 51.6 and 51.7, the Relevant Percentage of the first element of the CGT Asset's cost base (for all CGT Assets sold under this Contract) as at the Date of this Contract; and

Withholding Law means Subdivision 14-D of Schedule 1 of the *Taxation Administration Act 1953* and associated provisions.

51.2 If the Relevant Price is less than the dollar amount stated in section 14-215(1)(a) of the Withholding Law as at the Date of this Contract, the parties acknowledge that there are no obligations under the Withholding Law.

51.3 If Clearance Certificates for all the Sellers are provided to the Buyer prior to Completion, the parties acknowledge that there are no obligations under the Withholding Law.

51.4 If neither clauses 51.2 or 51.3 apply, then:

51.4.1 the Seller must provide to the Buyer any information required to enable the Buyer to comply with clause 51.4.2(a), within 5 days of written request from the Buyer;

51.4.2 the Buyer must:

(a) lodge a purchaser payment notification form with the ATO; and

(b) give evidence of compliance with clause 51.4.2(a) to the Seller;

no later than 5 days before the Date for Completion;

51.4.3 the Seller irrevocably instructs the Buyer to draw as part of the Price, and the Buyer must draw and retain on Completion, an unendorsed bank cheque payable to the ATO for the Withholding Amount; and

51.4.4 the parties must both, on the date of Completion, attend the offices of an authorised collection agent of the ATO to deposit the bank cheque referred to in clause 51.4.3 in payment of the Withholding Amount following Completion.

51.5 If clause 51.4 applies and the parties do not comply with clause 51.4.4:

51.5.1 the Buyer indemnifies the Seller for any loss or damage resulting from the Buyer's delay in remitting and/or failure to remit the Withholding Amount to the ATO; and

51.5.2 the Buyer charges the Property (for the benefit of the Seller) with the Buyer's obligations under this clause 51.5.

51.6 Where the Seller gives the Buyer a Variation Certificate prior to Completion, the Withholding Amount is the amount stated in the Variation Certificate.

51.7 Where Clearance Certificates for some but not all of the Sellers are provided to the Buyer prior to Completion, then the Withholding Amount is reduced by the same percentage as the percentage ownership of the Property of the Sellers that are subject to a Clearance Certificate.

51.8 Where a Clearance Certificate is provided by a Seller to the Buyer, the Seller warrants to the Buyer that that Seller is the entity referred to in the Clearance Certificate and is the relevant taxpayer for capital gains tax payable on the sale of the CGT Assets sold under this Contract.

52. Deposit by Instalments

52.1 The following clauses 52.2 to 52.8 inclusive only apply if the 'Deposit by Instalments' option on the Schedule is selected.

52.2 Clauses 2.1, 2.2, 2.3 and 2.4 are deleted.

52.3 The Buyer must pay the Deposit to the Stakeholder. The Seller agrees to accept the payment of the Deposit in two instalments as follows:

Section 32 Compliant

52.3.1 5% of the Price by cheque on the Date of this Contract (**First Instalment**); and

52.3.2 the balance of the Deposit (if it has not already been paid) by unendorsed bank cheque on the Date for Completion (**Second Instalment**);

and in every respect time is of the essence for payment of the First Instalment in this clause 52.3.1.

52.4 The Deposit becomes the Seller's property on Completion or on the earlier termination of this Contract by the Seller for the Buyer's default.

52.5 If the First Instalment of the Deposit is:

52.5.1 not paid on time and in accordance with clause 52.3; or

52.5.2 paid by cheque and the cheque is not honoured on first presentation,

the Buyer is in default and the Seller may terminate this Contract immediately by written notice to the Buyer (without the notice otherwise necessary under clause 18) and clause 19 applies. If the Seller does not terminate this Contract in accordance with this clause 52.5, then this Contract remains on foot, subject to this clause 52.5, until either the Seller terminates the Contract pursuant to this clause 52.5, or waives the benefit of this clause 52.5 pursuant to clause 52.8.

52.6 If the Second Instalment of the Deposit is not paid on time in accordance with clause 52.3, then the Seller cannot immediately terminate the Contract for the Buyer's breach of an essential condition. The Seller must make timing of the payment of the Second Instalment an essential condition of the Contract by serving on the Buyer a Default Notice requiring the Buyer to pay the Second Instalment within 14* days after service of the Default Notice (excluding the date of service).

52.7 For clarity, the Buyer must pay the full Price to the Seller, on or before Completion.

52.8 These clauses 52.2 to 52.8 inclusive are for the benefit of the Seller. The Seller may at any time before this Contract is terminated notify the Buyer in writing that the benefit of these clauses 52.2 to 52.8 inclusive is waived.

53. Residential Withholding Tax

Warning: The following clauses 53.1 to 53.9 are subject to the Withholding Law, and do not encompass all obligations under the Withholding Law.

53.1 In this clause 53 the following words have the following meanings:

RW Amount means the amount which the Buyer must pay under section 14-250 of the Withholding Law;

RW Amount Information means the completed RW Amount details referred to on page 3 of this Contract; and

RW Percentage means the percentage amount stated in section 14-250(6), (8) and (9) of the Withholding Law, as applicable to the supply of the Property from the Seller to the Buyer.

53.2 The Seller must provide the Buyer with the RW Amount Information no later than 7 days after the Date of this Contract.

53.3 If the 'Buyer required to make a withholding payment?' option on the Schedule is selected 'no' or if no selection is made, the Seller warrants to the Buyer that the Buyer is not required to make a payment under section 14-250 in relation to the supply of the Property from the Seller to the Buyer.

53.4 The following clauses 53.5 to 53.9 inclusive only apply if the 'Buyer required to make a withholding payment?' option on the Schedule is selected 'yes'.

53.5 Subject to any adjustments to the Price that may arise after the date that the RW Amount Information is provided in accordance with clause 53.2 and which affect the RW Amount, the Seller warrants to the Buyer on the date that the RW Amount Information is provided to the Buyer that the Seller has provided the Buyer with the information required under section 14 255 of the Withholding Law in relation to the supply of the Property from the Seller to the Buyer, and that this information is true and correct to the Seller's knowledge.

53.6 The Buyer must provide the Seller with a copy of the 'GST property settlement withholding notification online form' confirmation email (or emails, if applicable) issued to the Buyer by the ATO no later than:

53.6.1 21 days after a written request from the Seller; or

53.6.2 7 days prior to the Date for Completion,

whichever is the earlier.

53.7 The Buyer must provide the Seller with evidence of submission by the Buyer to the ATO of the 'GST property settlement date confirmation online form', with such evidence to be provided prior to or on Completion.

Block 32 Section 32 Campbell

* Alter as necessary

53.8 The Seller irrevocably instructs the Buyer to draw as part of the Price, and the Buyer must draw and retain on Completion, an unendorsed bank cheque payable to the ATO for the RW Amount.

53.9 In relation to the unendorsed bank cheque required by clause 53.8, the Buyer must:

53.9.1 forward the unendorsed bank cheque to the ATO immediately after Completion; and

53.9.2 provide the Seller with evidence of payment of the RW Amount to the ATO.

Block 38 Section 32 Campbell

If a home was built before 1990
it may contain dangerous asbestos material

ACT Government

Identify where asbestos materials might be. Five common places are:

1. Exterior
roof sheeting, gutters, downpipes, ridge capping, eaves, cladding, electrical switchboards



5. Building cavities
A small number of homes may still contain loose fill asbestos insulation in the roof cavity, wall cavities or sub-floor space

2. Wet areas - bathroom, laundry and kitchen
wall and ceiling panels, vinyl floor tiles, backing for wall tiles and splashbacks, hot water pipe insulation

3. Internal areas
wall and ceiling panels, carpet underlay, textured paints, insulation in domestic heaters

4. Backyard
fences, sheds, garages, carports, dog kennels, buried or dumped waste, letterboxes, swimming pools

If a home was built before 1990
it may contain dangerous asbestos material

ACT Government

Assess the risk

A licensed asbestos assessor can help identify asbestos in your home and its condition.

Asbestos materials become dangerous when:

Broken or in poor condition

Damaged accidentally



Disturbed during renovation or repairs

Loose fill asbestos insulation

Manage asbestos safely

- Monitor the condition of asbestos in your home
- Inform tradespeople of locations of asbestos in your home
- Avoid disturbing or damaging asbestos if working on your home
- Engage a licensed asbestos removalist to remove asbestos

If you suspect your home contains loose fill asbestos insulation, contact Access Canberra.

For more information, visit www.worksafe.act.gov.au or call Access Canberra contact centre – 13 22 81
If you need interpreting help, telephone the Translating and Interpreting Service on 131 450

*Advice based on the Asbestos Safety and Eradication Agency's residential asbestos disclosure research.

Product	Title Details
Date/Time	31/03/2026 02:53PM
Customer Reference	20260418
Order ID	20260331001353
Cost	$35.00

Volume 1548 **Folio** 54 **Edition** 8

AUSTRALIAN CAPITAL TERRITORY

TITLE SEARCH

LAND

Campbell Section 32 Block 38 on Deposited Plan 9304

Lease commenced on 16/12/1987, granted on 02/03/1999, terminating on 15/12/2086

Area is 711 square metres or thereabouts

Proprietor

SPENCER LAWRENCE WRIGHT

10 ELLIOTT STREET, CAMPBELL ACT 2612

MICHAEL DOUGLAS MCCORMACK

10 ELLIOTT STREET, CAMPBELL ACT 2612

as Joint Tenants

REGISTERED ENCUMBRANCES AND INTERESTS

Original title is **Volume** 1548 **Folio** 54

Restrictions

Purpose Clause: Refer Crown Lease

Easements

Easement In Crown Lease: Current

Registered Date	Dealing Number	Description
10/02/2025	3364930	Mortgage to NATIONAL AUSTRALIA BANK LIMITED (ACN: 004 044 937)

End of interests

This data (excluding administrative interests) is certified correct by the Registrar-General at 14:54:34 on 31/03/2026

Unregistered dealings have not been formally recorded in the register.

ORIGINAL.

Entered in Register Book Vol. 1548 Folio 54

CANCELLED AND COMPUTER CERTIFICATE OF TITLE ISSUED

22 MAR 1999

S. ROBERTSON
DEPUTY REGISTRAR-GENERAL

AUSTRALIAN CAPITAL TERRITORY

LAND (PLANNING AND ENVIRONMENT) ACT 1991

Australian Capital Territory (Planning and
Land Management) Act 1988 (C'th) ss 29, 30 & 31

LEASE GRANTED pursuant to the Land (Planning and Environment) Act 1991 on the second day of March One thousand nine hundred and ninety nine WHEREBY THE AUSTRALIAN CAPITAL TERRITORY EXECUTIVE ON BEHALF OF THE COMMONWEALTH OF AUSTRALIA (hereinafter called "the Commonwealth") grants to the **COMMISSIONER FOR HOUSING FOR THE AUSTRALIAN CAPITAL TERRITORY** (hereinafter called "the Lessee") ALL THAT piece or parcel of land situate in the Australian Capital Territory containing an area of **711 square metres** or thereabouts and being **Block 38 Section 32 Division of Campbell** (hereinafter called "the land") as delineated on **Deposited Plan Number 9304** in the Registrar-General's Office at Canberra in the said Territory and being the land bounded by bold line identified as "A" on the legend on the plan annexed hereto (hereinafter called "the plan") RESERVING as appurtenant to the land being Block 37 Section 32 Division of Campbell (the "Dominant Tenement") full and free right and liberty to overhang eaves and guttering over the piece of land shown on the plan AND ALSO RESERVING as appurtenant to the Dominant Tenement the right and liberty to the lessees of the Dominant Tenement and their servants and agents to enter upon the land for the purposes of inspecting maintaining clearing repairing and replacing the said eaves and guttering PROVIDED THAT in exercising any right of entry upon the land such persons shall (i) enter the land only at reasonable times between the hours of 9.00 am and 5.00 pm and after giving 24 hours prior written notice to the Lessee and occupiers of the land except in the case of an emergency; (ii) cause as little disturbance to the Lessee and occupiers of the land as shall be reasonably possible; and (iii) promptly repair any damage caused to the land or any structures on it whilst exercising the rights reserved in this lease and ALSO RESERVING as appurtenant to the Dominant Tenement an easement of support to retain and to maintain that part of the wall shown as cross hatching identified as "B" on the legend on the plan and to permit it to support that part of the wall shown by hatching identified as "C" on the legend on the plan and also to support the roof timbers and roof of the building erected on the Dominant Tenement and RESERVING to the Territory all minerals AND WITH THE BENEFIT OF the easement reserved in the Crown Lease of the Dominant Tenement and being registered Volume 1548 Folio 56 (as indicated on the plan) TO HOLD unto the Lessee for the term of ninety nine years commencing on the sixteenth day of December One thousand nine hundred and eighty seven (hereinafter referred to as "the date of the commencement of the lease") to be used by the Lessee for the purpose set forth in sub-clause (c) of clause 2 of this lease only YIELDING AND PAYING THEREFOR during the said term rent at the rate of five cents per annum if and when demanded and UPON AND SUBJECT TO the covenants conditions and agreements hereinafter contained.

1. IN THIS LEASE unless the contrary intention appears:

   (a) "Australian Capital Territory Executive" means the Executive established by section 36 of the Australian Capital Territory (Self-Government) Act 1988 (C'th);

   (b) "building" means the building or any buildings on the land at the date of the commencement of the lease or any building or buildings constructed on the land in accordance with the covenants of this lease or any building or buildings replacing the same together with all fittings fixtures (including floor coverings) plant amenities and appurtenances thereof and therein contained or if the context so permits any part thereof;

   (c) "dwelling" means a room or suite of rooms occupied or used or so constructed or adapted as to be capable of being occupied or used as a separate domicile and includes outbuildings, if any, that are normal to the enjoyment and exclusive use of the dwelling;

   (d) "Lessee" shall -

      (i) where the Lessee consists of one person be deemed to include the Lessee and the executors administrators and assigns of the Lessee;

ACT REVENUE OFFICE
ORIGINAL DULY STAMPED
Assessed Value
Duty Paid $20.00
for Land Inc Land Use Entitlement-R
es
00516660 00003 09/03/99 38-32-CAMP

(ii) where the Lessee consists of two or more persons be deemed to include in the case of a tenancy in common the said persons and each of them and their and each of their executors administrators and assigns and in the case of a joint tenancy be deemed to include the said persons and each of them and their and each of their assigns and the executors administrators and assigns of the survivor of them; and

(iii) where the Lessee is a corporation be deemed to include such corporation and its successors and assigns;

(e) "premises" means the land and any building erections and or improvements in on or above the land;

(f) "Territory" means -

(i) when used in a geographical sense the Australian Capital Territory; and

(ii) when used in any other sense the body politic established by section 7 of the Australian Capital Territory (Self-Government) Act 1988 (C'th).

2. THE LESSEE COVENANTS WITH THE COMMONWEALTH as follows:

(a) That the Lessee shall pay to the Territory at Canberra the rent hereinbefore reserved within one month of the date of any demand made by the Territory relating thereto and served on the Lessee;

(b) That the Lessee shall not without the previous approval in writing of the Territory erect any building on the land or make any structural alterations in any building erected on the land;

(c) To use the land for residential purposes only;

(d) That the building erected on the land shall be used only as a single dwelling and any outbuildings erected on the land shall not be used as a habitation;

(e) That the Lessee shall at all times during the said term maintain repair and keep in repair the premises to the satisfaction of the Territory;

(f) If and whenever the Lessee is in breach of the Lessee's obligations to maintain repair and keep in repair the premises the Territory may by notice in writing to the Lessee specifying the repairs and maintenance needed require the Lessee to effect the necessary work in accordance with the notice. If the Territory is of the opinion that a building or some other improvement on the land is beyond reasonable repair the Territory may by notice in writing to the Lessee require the Lessee to remove the building or improvement and may require the Lessee to construct a new building or improvement in place of that removed within the time specified in the notice. If the Lessee does not carry out the required work within the time specified by the Territory any person or persons duly authorised by the Territory with such equipment as is necessary may enter the premises and carry out the necessary work and all costs and expenses incurred by the Territory in carrying out the work shall be paid by the Lessee to the Territory on demand and from the date of such demand until paid shall for all purposes of this lease be a debt due and payable to the Territory by the Lessee;

(g) Subject to the provisions of the Land (Planning and Environment) Act 1991 to permit any person or persons authorised by the Territory to enter and inspect the premises at all reasonable times and in any reasonable manner;

(h) To pay all rates and charges and other statutory outgoings assessed levied or payable in respect of the premises as and when the same fall due.

3. IT IS MUTUALLY COVENANTED AND AGREED as follows:

(a) That if -

(i) the land is at any time not used for a period of one year for the purpose for which this lease is granted; or

(ii) the Lessee shall fail to observe or perform any other of the covenants herein contained on the part of the Lessee to be observed or performed and shall have failed to remedy such breach within a period of six months from the date of service on the Lessee of a notice in writing from the Territory specifying the nature of such breach

the Territory may terminate this lease but without prejudice to any claim which the Territory or the Commonwealth may have against the Lessee in respect of any breach of the covenants on the part of the Lessee to be observed or performed;

(b) That acceptance of rent or other moneys by the Territory during or after any period referred to in paragraph (i) or (ii) of sub-clause (a) of this clause shall not prevent or impede the exercise by the Territory of the powers conferred upon it by sub-clause (a) of this clause;

(c) Subject to the provisions of the Land (Planning and Environment) Act 1991 the Lessee shall be entitled to a further lease of the land for such further term and at such rent and subject to such conditions as may then be provided or permitted by Statute Ordinance or Regulation;

(d) That any notice requirement demand consent or other communication to be given to or served upon the Lessee under this lease shall be deemed to have been duly given or served if signed by or on behalf of the Territory and delivered to or sent in a prepaid letter addressed to the Lessee at the land or at the usual or last-known address of the Lessee or affixed in a conspicuous position on the premises;

(e) Any and every right power and or remedy conferred on the Commonwealth the Territory or the respective Ministers hereunder or implied by law may be exercised on behalf of the Commonwealth the Territory or the respective Ministers as the case may be by -

(i) the Australian Capital Territory Executive;

(ii) the Minister for the time being administering the Land (Planning and Environment) Act 1991 or any Statute Ordinance or Regulation substituted therefor;

(iii) an authority or person for the time being authorised by the Australian Capital Territory Executive or the Minister referred to in (i) or (ii) above or by law to exercise those powers or functions of the Commonwealth the Territory or the relevant Minister; or

(iv) the person to whom the Minister referred to in (ii) above has delegated all his powers or functions under the said Land (Planning and Environment) Act 1991 or any Statute Ordinance or Regulation substituted therefor.

IN WITNESS whereof the Australian Capital Territory Executive on behalf of the Commonwealth and the Lessee have executed this lease.

SIGNED SEALED AND DELIVERED)
by Rosetta ROMANO)
a person duly authorised by the)
Australian Capital Territory Executive)
for and on behalf of the Commonwealth)
in the presence of:)

The Official Seal of the)
Commissioner for Housing)
for the Australian Capital)
Territory was hereunto)
affixed in the presence of:)

TERRITORY FOR THE SEAT OF GOVERNMENT
COMMISSIONER FOR HOUSING

DELEGATE OF THE
COMMISSIONER FOR HOUSING



DIAGRAM B
NOT TO SCALE



DIAGRAM A
NOT TO SCALE

N



This is the plan referred to in the lease of Block 38 Section 32 Division of CAMPBELL granted on the 2nd day of MARCH 1999 as being annexed thereto.



DIAGRAM B

NOT TO SCALE



DIAGRAM A

NOT TO SCALE



REFERENCE MARKS

- Denotes GIP in road 1.83 radially from TP
- " CB " " 1.83 " " TP
- " PLAQUE IN KERB
- " DEEP DRIVEN ROD
- " DH&W IN KERB

(Except as otherwise shown)

Azimuth: A-B (Strom)

All Easements are 2.5 metres wide
(Except as otherwise shown)

Field Books: K21728

I MICHAEL NOLAN LAVIS of CANBERRA a surveyor registered under the Surveyors Act 1967 hereby certify that the survey represented on this plan is accurate and has been made and partly compiled from DP1653 in accordance with Survey Practice Directions and was completed on 12 NOVEMBER 1998

(Signature) 1.12.98

Surveyor registered under the Surveyors Act 1967

I certify that this plan is the plan prepared in accordance with the Districts Act 1966

4/12/1998

Chief Surveyor of the ACT Government

PLAN OF

BLOCKS 37-39 SECTION 32

BEING AN AMENDMENT OF BLOCKS 12-14

DIVISION: CAMPBELL

DISTRICT: CANBERRA CENTRAL

AUSTRALIAN CAPITAL TERRITORY

SCALE 1: 300

0 5 10 20 METRES

Deposited in the office of the Registrar of Titles at Canberra in the Australian Capital Territory the SECOND day of FEBRUARY 1999 at — minutes past TWO o'clock in the AFTER noon

Approved

S. ROBERTSON
DEPUTY REGISTRAR GENERAL

Registrar of Titles

DEPOSITED PLAN

9304

AMENDS DP837 & DP1653

*SE ADC

X16411A

ACCESS CANBERRA
LAND, PLANNING & BUILDING SERVICES
8 Darling Street
MITCHELL ACT 2911

PHONE: 62071923

LEASE CONVEYANCING ENQUIRY

Your response is sought to the following questions in relation to:

LAND: Please provide details of the land you are enquiring about.

Unit	0	Block	38	Section	32	Suburb	CAMPBELL

Leased by the Australian Capital Territory on behalf of the Commonwealth under the Land (Planning and Environment) Act 1991, Planning & Development Act 2007 and Planning Act 2023.

	No	Yes
1. Have any notices been issued relating to the Crown Lease?	(X)	( )
2. Is the Lessor aware of any notice of a breach of the Crown Lease?	(X)	( )
3. Has a Certificate of Compliance been issued? (N/A ex-Government House) [X]	( )	( )

Certificate Number: N/A Dated:

4. Has an application for Subdivision been received under the Unit Titles Act? (see report)

5. Has the Property been nominated for provisional registration, provisionally registered or registered in accordance with provisions of the Heritage Act 2004? (see report)

6. If an application has been determined, is the land subject to an Environmental Impact Statement under Chapter 8 of the Planning & Development Act 2007, or part 6.3 of the Planning Act 2023? (see report)

7. Has a development application been received, or approval (applications lodged prior to 2 April 1992 will not be included)? (see report)

8. Has an application been received or approved for Dual Occupancy? (applications lodged prior to 2 April 1992 will not be included) (see report)

9. Has an Order been made in respect of the Land pursuant to Part 11.3 of the Planning & Development Act 2007 or Part 12.3 of the Planning Act 2023? (see report)

10 Contaminated Land Search - Is there information recorded by Environment ACT regarding the contamination status of the land? (see report)

Applicant's Name : Mee, Mitchell
E-mail Address : contracts@oconnorharris.com.au
Client Reference : 20260418

Date: 31-MAR-26 15:22:19

ACCESS CANBERRA
LAND, PLANNING & BUILDING SERVICES
8 Darling Street
MITCHELL ACT 2911

PLANNING AND LEASE MANAGER (PaLM)
LEASE CONVEYANCING ENQUIRY REPORT

INFORMATION ABOUT THE PROPERTY

CAMPBELL Section 32/Block 38

Area(m2): 711.4
Unimproved Value: $1,150,000 **Year:** 2025
Subdivision Status: Application not received under the Unit Titles Act.

Heritage Status: Nil.

Environment Assessment: The Land is not subject to an Environmental Impact Statement under Chapter 8 of the Planning & Development ACT 2007, or part 6.3a of the Planning Act 2023.

DEVELOPMENT APPLICATIONS ON THE PROPERTY (SINCE APRIL 1992)

Application DA200401215 **Lodged** 03-AUG-04 **Type** Single Dwelling

-- Application Details ----------

Description
Demolition and rebuild - two storey

-- Site Details ----------

District	Division	Section	Block(s)	Unit
Canberra Central	Campbell	32	38-38	

-- Involved Parties ----------

Role	Name
Energy Assessor	Preston
Objector	Objection Withdrawn
Applicant	Morgan Engineers Act

-- Activities ----------

Activity Name	Status
Ba Single Hse (Neighbour Cons)	Approved

DEVELOPMENT APPLICATIONS ON THE ADJACENT PROPERTIES (LAST 2 YEARS ONLY)

The information on development applications on adjacent blocks is to assist purchasers to be aware of possible nearby development activity. Please note however, it doesn't cover all development activity. Exempt activities can include but are not limited to, new residences, additions to residences, certain sheds, carports and pergolas etc. Information on exempt developments can be found at https://www.planning.act.gov.au/applications-and-assessments/development-applications/check-if-you-need-a-da

ACCESS CANBERRA
LAND, PLANNING & BUILDING SERVICES
8 Darling Street
MITCHELL ACT 2911

LAND USE POLICIES

To check the current land use policy in the suburb that you are buying a property in, please check the Territory Plan online at https://www.legislation.act.gov.au/ni/2023-540/

CONTAMINATED LAND SEARCH

Information is not recorded by the Environment Protection Authority regarding the contamination status of this land. However, this does not absolutely rule out the possibility of contamination and should not be interpreted as a warranty that there is no contamination. To be completely sure, independent tests should be arranged.

ASBESTOS SEARCH

ACT Government records indicate that asbestos (loose fill or otherwise) is not present on this land. However, the accuracy of this information is not guaranteed. If the property was built prior to 1 January 2004, you should make your own enquiries and obtain reports (from a licensed Asbestos Assessor) in relation to the presence of loose-fill asbestos insulation (and other forms of asbestos e.g. bonded asbestos) on the premises.

CAT CONTAINMENT AREAS

**Cat containment has been extended across the ACT for cats born on or after 1 July 2022. Containment means keeping your cat on your premise 24 hours a day. This can include your house or apartment, enclosed area in a backyard or courtyard, a cat crate or leash.
Cats born before 1 July 2022 do not have to be contained unless the live in one of the 17 currently declared cat containment suburbs. All cats (regardless of age) located in the following suburbs must be contained to their premise 24 hours a day. However, cats can be walked on a leash and harness under effective control in all containment suburbs: BONNER, COOMBS, CRACE, DENMAN PROSPECT, FORDE, JACKA, LAWSON, MOLONGLO, MONCRIEFF, STRATHNAIRN, THE FAIR in north WATSON, THROSBY, WRIGHT, GUNGAHLIN TOWN CENTRE, MACNAMARA, TAYLOR and WHITLAM. More information on cat containment is available at https://www.cityservices.act.gov.au/pets-and-wildlife/domestic-animals/cats/cat-containment or by phoning Access Canberra on 13 22 81.**

URBAN FOREST ACT 2023

The Urban Forest Act 2023 (or Tree Protection Act 2005 where applicable) protects individual trees of importance and urban forest areas that require particular protection. A Tree Register has been established and can be found on the Transport Canberra and City Services website https://www.cityservices.act.gov.au/trees-and-nature/trees/act_tree_register or for further information please call Access Canberra on 132281.

---- END OF REPORT ----

ACT PROPERTY INSPECTIONS

10 Elliott St,
Campbell ACT 2612

Report prepared: Friday, April 10th 2026

Building Report
Timber Pest Inspection Report
Compliance Report
Conveyancing Report
Energy Efficiency Rating
Insurance Certificates
Tax Invoice

Report



MASTER BUILDERS AUSTRALIAN CAPITAL TERRITORY

REIACT REAL ESTATE INSTITUTE OF THE AUSTRALIAN CAPITAL TERRITORY

Level 1, 33 Altree Court,
Phillip ACT 2606

PO Box 576
Erindale Centre ACT 2903

02 6232 4540
info@actpropertyinspections.com.au

ABN 33 600 397 466
actpropertyinspections.com.au

LIMITED LIABILITY TO A PURCHASER WITHIN THE AUSTRALIAN CAPITAL TERRITORY

This Report is made solely for the use and benefit of the Client. The Consultant is not liable for any reliance placed on this report by any third party. However, within the ACT only and in accordance with the Civil Law (Sale of Residential Property) Act 2003 and the Civil Law (Sale of Residential Property) Regulations 2004, a copy of the report must be attached to the Contract for Sale and may in certain circumstances be relied upon by the Purchaser of residential property.

The circumstances in which a Purchaser of residential property within the ACT may rely on this report in respect of the state of the property at the time of the inspection are as follows:

(a) The inspection was carried out no earlier than three months before the day the property was first advertised or offered for sale or listed by an agent; and

(b) The date on which the contract was entered into was not more than 180 days after the date of the inspection.

(c) The report is provided to the Purchaser prior to or at the time the Contract for Sale is entered into between the Purchaser and vendor.

(d) The service requested is the Standard Inspection Report.

ACT PROPERTY INSPECTIONS

Building Report

CONCLUSION AND SUMMARY

The purpose of the Inspection is to identify the major defects and safety hazards associated with the property at the time of the Inspection. The Inspection and reporting are limited to a visual assessment of the Building Members in accord with Appendix C AS4349.1-2007.

The overall condition of this building has been compared to similar constructed buildings of approximately the same age where those buildings have had a maintenance program implemented to ensure that the building members are still fit for purpose.

The incidence of Major Defects in this Residential Building as compared with similar Buildings is considered: **Low**

The incidence of Minor Defects in this Residential Building as compared with similar Buildings is considered: **Low**

The overall condition of this Residential Dwelling in the context of its age, type and general expectations of similar properties is: **Above Average**

Please Note: This is a general appraisal only and cannot be relied upon on its own – read the Report in its entirety.

This Summary is supplied to allow a quick and superficial overview of the Inspection results. This Summary is NOT the Report and cannot be relied upon on its own. This Summary must be read in conjunction with the full Report and not in isolation from the Report. If there should happen to be any discrepancy between anything in the Report and anything in this Summary, the information in the Report shall override that in this Summary.

PROPERTY STATISTICS

Building Report	Above Average
Compliance Report	Please read full compliance report section of the report
Pest Inspection	No active subterranean termites (live specimen) were found
Energy Efficiency Rating	4.0 Stars
Inspection Date	Friday, April 10th 2026
Name of Assessor	Duncan Clark
Reference Number	69343
Address of Property Inspected	10 Elliott St, Campbell ACT 2612
Client	McCormack & Wright
Block and Section	Block 38 Section 32 CAMPBELL
Year original residence COU was issued	2007
Block size (approximately)	711m^2
House size (approximately)	Upper Residence: 75.00m^2 Lower Residence: 157.80m^2 Studio/Bathroom: 38.50m^2 Garage: 60.90m^2 Total: 332.20m^2
Weather conditions at time of Inspection	Fine
Occupancy Status	Occupied

*The table above is to be used as a quick reference. Please read the full Report before reaching your conclusion regarding the condition of the Property.

Whilst every care has been taken to ensure the accuracy of the property house and block size, we accept no responsibility for any inaccuracies as supplying this information exceeds a standard building inspection under AS4349.1-2007.

PROPERTY CONSTRUCTION DETAILS

Flooring	Concrete and timber flooring
External walls	Brick veneer, concrete block and compressed cladding
Roof framing	Flat roof construction
Roof cladding	Colorbond roof cladding
Glazing	Single glazed windows
Cooktop	Electric cooktop
Oven	Electric oven
Dishwasher	Bosch

*Whilst every care has been taken to ensure the accuracy of the property construction details, we accept no responsibility for any inaccuracies of construction details or testing of appliances.

GENERAL ACCESS LIMITATIONS

Internal	At the time of inspection, the building was furnished. This allows for a limited inspection in areas not restricted by furnishings, stored goods, floor mats, etc.
External	A full inspection was carried out to the exterior of the building
Roof void	No inspection was made inside the roof void due to the flat roof construction
On-top of roof	The inspection was restricted to visually looking from a 3.6m ladder lent against the gutter in several areas around the building. No access was gained onto the upper-level roof due to the height of the roof
Garage	The inspection of the garage was restricted due to stored goods being kept in the area at the time of inspection

*Where access is noted as limited or restricted, it is recommended that access be gained to these areas as these areas may contain concealed defects.

DEFINITIONS

Good	The item is in the Inspector's opinion of an acceptable standard with no defects visible. Superficial defects will not be commented on
Fair	The item in the Inspector's opinion has some minor defects and requires minimal maintenance or repair
Poor	The item in the Inspector's opinion needs significant repair or replacement

ENTRANCE

Ceiling	Good
Walls	Good
Door and door hardware	Good
Floor coverings	Good

LIVING/DINING ROOM

Ceiling	Good
Walls	Good
Floor coverings	Good

FAMILY ROOM

Ceiling	Good
Walls	Good
Door and door hardware	Good
Floor coverings	Good

KITCHEN/MEALS AREA

Ceiling	Good
Walls	Good
Door and door hardware	Good
Floor coverings	Good
Kitchen cupboards	Good. There are minor marks and signs of wear
Bench top	Good
Splashback	Good
Exhaust fan	The exhaust fan was operational at the time of inspection

STAIRWELL

Ceiling	Good
Walls	Good
Door and door hardware	Good
Floor coverings	Good
Handrail	A handrail has not been installed. Recommend installing a compliant handrail

BEDROOM 1

Ceiling	Good
Walls	Good
Door and door hardware	Good
Floor coverings	Good
Wardrobe	Good

BEDROOM 2

Ceiling	Good
Walls	Good
Door and door hardware	Good
Floor coverings	Good
Wardrobe	Good

BEDROOM 3

Ceiling	Good
Walls	Good
Door and door hardware	Good
Floor coverings	Good
Wardrobe	Good

BEDROOM 4

Ceiling	Good
Walls	Good
Door and door hardware	Good
Floor coverings	Good
Wardrobe	Good

ENSUITE

Ceiling	Good
Walls	Good
Door and door hardware	Good
Floor coverings	Good
Shower screen	Good
Water leakage in shower area?	There was no water leakage detected
Floor and wall tiles in shower area	Good
Vanity/Basin	Good
Taps	Good
Toilet suite	Good
Exhaust fan	The exhaust fan was operational at the time of inspection

BATHROOM - UPPER LEVEL

Ceiling	Good
Walls	Good
Door and door hardware	Good
Floor coverings	Good
Shower screen	Good
Water leakage in shower area?	There was no water leakage detected
Floor and wall tiles in shower area	Good
Vanity/Basin	Good
Taps	Good
Toilet suite	Good
Exhaust fan	The exhaust fan was operational at the time of inspection

BATHROOM

Ceiling	Good
Walls	Good
Door and door hardware	Good
Floor coverings	Good
Shower screen	Good
Water leakage in shower area?	There was no water leakage detected
Floor and wall tiles in shower area	Good
Vanity/Basin	Good
Taps	Good
Bath	A spa has been installed. The pumps were not tested at the time of the inspection
Toilet suite	Good
Exhaust fan	The exhaust fan was operational at the time of inspection

LAUNDRY

Ceiling	Good
Walls	Good
Door and door hardware	Good
Floor coverings	Good
Laundry tub	Good
Splashback	Good

STUDIO

Ceiling	Good
Walls	Good
Door and door hardware	Good. There is minor swelling to the door architrave of the shower area due to splashing water from the shower. The shower was run for several minutes and no leakage was evident
Floor coverings	Good
Windows	Good
Cabinetry	Good
Shower screen	Good
Water leakage in shower area?	There was no water leakage detected
Floor and wall tiles in shower area	Good
Vanity/Basin	Good
Taps	Good
Toilet suite	Good – Dual flush

GARAGE AND STORAGE AREA

Ceiling	There is water leakage through from the balcony slab into the storage area. Recommend repairs by a qualified tradesperson
Slab	Good. No major cracking noted
Walls	The white powder on the garage and store room walls is known as 'efflorescence' and is a result of moisture passing through and evaporating on the surface of the brick work. This usually causes minimal harm but indicates excessive moisture on the soil side of the walls.
Garage door	Good
Is an auto opener installed on the roller door?	Yes
Access door	Good

POWDER ROOM TO GARAGE

Walls	Good
Door and door hardware	Good
Toilet suite	Good – Dual flush
Vanity/Basin	Good
Taps	Good

EXTERIOR

Driveway and paths	Good. No major cracking noted
Roof covering	Good
Roof flashings	Good
Eaves	Good
Fascia	Good
Gutters	Good
External walls	Various areas of minor cracking noted in the external walls. The cracking found was not of major structural significance. There were areas of repairs evident to the render around the property. This is a cosmetic defect caused by moisture in the render. Repairs are considered optional
Windows	Good
Fences	Good
Gate	Good
Balcony to family room	The handrails have been constructed lower than 1m in height. Consideration should be given to raising the handrail height to 1m or above to eliminate the fall potential
Balcony to meals areas	The handrails have been constructed lower than 1m in height. Consideration should be given to raising the handrail height to 1m or above to eliminate the fall potential The balcony is leaking. Recommend repairs by a qualified tradesperson
Balcony to bedrooms	Good
Retaining walls	Good
Site drainage	The site generally drains away from the perimeter of the building

DEFINITIONS

Above Average: The overall condition is above that consistent with dwellings of approximately the same age and construction. Most items and areas are well maintained and show a reasonable standard of workmanship when compared with buildings of similar age and construction.
Average: The overall condition is consistent with dwellings of approximately the same age and construction. There will be areas or items requiring some repair or maintenance**.**
Below Average: The Building and its parts show some significant defects and/or very poor non- tradesman like workmanship and/or long-term neglect and/or defects requiring major repairs or reconstruction of major building elements.
Client: The person or persons, for whom the Inspection Report was carried out or their Principal (i.e., the person or persons for whom the report is being obtained).
Building Consultant: A person, business or company who is qualified and experienced to undertake a pre-purchase inspection in accordance with Australian Standard AS 4349.1-2007 'Inspection of Buildings. Part 1: Pre-Purchase Inspections – Residential Buildings'. The consultant must also meet any Government licensing requirement, where applicable.
Building & Site: The inspection of the nominated residence together with relevant features including any car accommodation, detached laundry, ablution facilities and garden sheds, retaining walls more than 700 mm high, paths and driveways, steps, fencing, earth, embankments, surface water drainage and storm water run-off within 30 m of the building, but within the property boundaries. In the case of strata and company title properties, the inspection is limited to the interior and immediate exterior of the nominated residence and does not include inspection of common property.
Readily Accessible Areas: Areas which can be easily and safely inspected without injury to person or property, are up to 3.6 metres above ground or floor levels or accessible from a 3.6 metre ladder, in roof spaces where the minimum area of accessibility is not less than 600 mm high by 600 mm wide and subfloor spaces where the minimum area of accessibility is not less than 400 mm high by 600 mm wide, providing the spaces or areas permit entry. Or where these clearances are not available, areas within the consultant's unobstructed line of sight and within arm's length.
Structure: The loadbearing part of the building, comprising the Primary Elements.
Primary Elements: Those parts of the building providing the basic loadbearing capacity to the Structure, such as foundations, footings, floor framing, loadbearing walls, beams, or columns. The term 'Primary Elements' also includes other structural building elements including those that provide a level of personal protection such as handrails; floor-to-floor access such as stairways; and the structural flooring of the building such as floorboards.
Secondary Elements: Those parts of the building not providing loadbearing capacity to the Structure, or those non-essential elements which, in the main, perform a completion role around openings in Primary Elements and the building in general such as non-loadbearing walls, partitions, wall linings, ceilings, chimneys, flashings, windows, glazing or doors.
Finishing Elements: The fixtures, fittings and finishes applied or affixed to Primary Elements and Secondary Elements such as baths, water closets, vanity basins, kitchen cupboards, door furniture, window hardware, render, floor, and wall tiles, trim or paint. The term 'Finishing Elements' does not include furniture or soft floor coverings such as carpet and lino.
Major Defect: A defect of significant magnitude where rectification has to be carried out in order to avoid unsafe conditions, loss of utility or further deterioration of the property.
Minor Defect: A defect other than a Major Defect.
Safety Hazard: Any item that may constitute an immediate or imminent risk to life, health, or property. Occupational, health and safety or any other consequence of these hazards has not been assessed.
Tests: Where appropriate the carrying out of tests using the following procedures and instruments:
Dampness Tests means additional attention to the visual examination was given to those accessible areas which the consultant's experience has shown to be particularly susceptible to damp problems. Instrument testing using electronic moisture detecting meter of those areas and other visible accessible elements of construction showing evidence of dampness was performed. Physical Tests means the following physical actions undertaken by the consultant: opening and shutting of doors, windows and draws; operation of taps; water testing of shower recesses; and the tapping of tiles and wall plaster.

IMPORTANT ADVICE

NB. In the case of strata and company title properties, the Inspection is limited to the interior and immediate exterior of the particular unit being inspected. The exterior above ground floor level is not inspected. The complete Inspection of other common property areas would be the subject of a Special-Purpose Inspection Report which is adequately specified**.**

Trees: Where trees are too close to the house this could affect the performance of the footing as the moisture levels change in the ground. A Geotechnical Inspection can determine the foundation material and provide advice on the best course of action with regards to the trees.

The Septic Tanks: Should be inspected by a licensed plumber.

Swimming Pools: Swimming Pools/Spas are not part of the Standard Building Report under AS4349.1-2007 and are not covered by this Report. We strongly recommend a pool expert should be consulted to examine the pool and the pool equipment and plumbing, as well as the requirements to meet the standard for pool fencing. Failure to conduct this Inspection and put into place the necessary recommendations could result in finds for non-compliance under the legislation.

Surface Water Drainage: The retention of water from surface run off could have an effect on the foundation material which in turn could affect the footings to the house. Best practice is to monitor the flow of surface water during rainfall and stormwater runoff and have the water directed away from the house or to storm water pipes by a licensed plumber/drainer.

Weep Holes: External brick (and stone) walls are a porous material that behave much like a sponge. During a rain event, the masonry wall absorbs water and actually stores it. The weep holes are designed for two purposes. 1. To provide an opening to allow water to drain out through the bottom of the wall. 2. To allow ventilating air to enter behind the wall to help dry the structure. If weep holes have been noted as being not installed, it is recommended to consult a builder on how to best rectify the problem.

Water Leaks from Roof: The inspector cannot, and does not, offer an opinion on whether the roof currently leaks or may be subject to future leaks. The only way to determine whether a roof is absolutely watertight is to make observations during prolonged rainfall.

Subfloor dampness: The presence of dampness is not always consistent as the prevailing and recent weather conditions at the time an inspection is carried out may affect the detection of damp problems. The absence of any dampness at the time of inspection does not necessarily mean the building will not experience some damp problems in other weather conditions. Likewise, whether or not services have been used for some time prior to an inspection being carried out will affect the detection of dampness.

Shower: Where a shower recess has been water tested, and no leakage was evident, this does not necessarily mean that the shower will not leak after prolonged use. Accordingly, to fully detect and assess a damp problem may require the monitoring of the building over a period of time.

SCOPE AND LIMITATIONS

Any person who relies upon the contents of this Report does so acknowledging that the following clauses, which define the Scope and Limitations of the Inspection, form an integral part of the Report.

1) This Report is not an all-encompassing Report dealing with the building from every aspect. It is a reasonable attempt to identify any obvious or significant defects apparent at the time of the Inspection. Whether or not a defect is considered significant or not, depends to a large extent upon the age and type of the building inspected. This Report is not a Certificate of Compliance with the requirements of any Act, Regulation, Ordinance or By-law. It is not a structural Report. Should you require any advice of a structural nature you should contact a structural engineer.

2) This is a visual Inspection only, limited to those areas and sections of the property fully accessible and visible to the Inspector on the date of Inspection. The Inspection DID NOT include breaking apart, dismantling, removing, or moving objects including, but not limited to, foliage, mouldings, roof insulation/sisalation, floor or wall coverings, sidings, ceilings, floors, furnishings, appliances, or personal possessions. The inspector CANNOT see inside walls, between floors, inside skillion roofing, behind stored goods in cupboards and other areas that are concealed or obstructed. The inspector DID NOT dig, gouge, force or perform any other invasive procedures. Visible timbers CANNOT be destructively probed or hit without the written permission of the property owner.

3) This Report does not and cannot make comment upon: Defects that may have been concealed; the assessment or detection of defects (including rising damp and leaks) which may be subject to the prevailing weather conditions; whether or not services have been used for some time prior to the Inspection and whether this will affect the detection of leaks or other defects (e.g. In the case of shower enclosures the absence of any dampness at the time of the inspection does not necessarily mean that the enclosure will not leak); the presence or absence of timber pests; gas-fittings; common property areas; environmental concerns; the proximity of the property to flight paths, railways, or busy traffic; noise levels; health and safety issues; heritage concerns; security concerns; fire protection; site drainage (apart from **surface** water drainage); swimming pools and spas (non-structural); detection and identification of illegal building work; detection and identification of illegal plumbing work; durability of exposed finishes; neighbourhood problems; document analysis; electrical installation; any matters that are solely regulated by statute; any area(s) or item(s) that could not be inspected by the consultant.

Accordingly, this Report is NOT a guarantee that defects and/or damage does not exist in any inaccessible or partly inaccessible areas or sections of the property.

NB. Such matters may, upon request, be covered under the terms of a 'Special-Purpose Property Report'.

4) Consumer Complaints Procedure: In the event of any dispute or claim arising out of, or relating to the Inspection or the Report, you must notify us as soon as possible of the dispute or claim by email, fax, or mail. You must allow us (which includes persons nominated by us) to visit the property (which visit must occur within twenty eight (28) days of your notification to us) and give us full access in order that we may fully investigate the complaint. You will be provided with a written response to your dispute or claim within twenty-eight (28) days of the date of the Inspection.

If you are not satisfied with our response, you must within twenty one (21) days of your receipt of our written response, refer the matter to a Mediator nominated by us from the Institute of Arbitrators and Mediators of Australia. The cost of the Mediator will be borne equally by both parties, and as agreed as part of the mediated settlement.

Should the dispute or claim not be resolved by mediation, then the dispute or claim will proceed to arbitration. The Institute of Arbitrators and Mediators of Australia will appoint an Arbitrator who will hear and resolve the dispute. The arbitration, subject to any directions of Arbitrator, will proceed in the following manner:

(a) The parties must submit all written submissions and evidence to the Arbitrator within twenty one (21) days of the appointment of the Arbitrator; and

(b) The arbitration will be held within twenty one (21) days of the Arbitrator receiving the written submissions.

The Arbitrator will make a decision determining the dispute or claim within twenty one (21) of the final day of the arbitration. The Arbitrator may, as part of his determination, determine what costs, if any, each of the parties are to pay and the time by which the parties must be paid any settlement or costs.

The decision of the Arbitrator is final and binding on both parties. Should the Arbitrator order either party to pay any settlement amount or costs to the other party but not specify a time for payment, then such payment shall be made within twenty one (21) days of the order.

NB. In the event that you do not comply with the above Complaints Procedure and commence litigation against us, then you agree to fully indemnify us against any awards, costs, legal fees, and expenses incurred by us in having your litigation set aside or adjourned to permit the foregoing Complaints Procedure to complete.

5) Asbestos Disclaimer: "No Inspection for Asbestos was carried out at the property, and no Report on the presence or absence of Asbestos is provided".

Buildings built prior to 1982 may have wall and/or ceiling sheeting, and other products including roof sheeting that contains Asbestos. Even buildings built after this date, up until the early 90s, may contain some Asbestos. Sheeting should be fully sealed. If you are concerned, the building was built prior to 1990, or if asbestos is noted as present within the property, then you should seek advice from a qualified asbestos removal expert as to the amount and importance of the asbestos present and the cost of sealing or removal. Drilling, cutting, or removing sheeting or products containing Asbestos is a high risk to peoples' health. You should seek advice from a qualified asbestos removal expert.

6) Mould (Mildew and non-wood decay fungi) Disclaimer: Mildew and non-wood decay fungi are commonly known as mould. However, mould and their spores may cause health problems or allergic reactions, such as asthma and dermatitis in some people. No Inspection for mould was carried out at the property, and no Report on the presence or absence of mould is provided. If mould is noted as present within the property, or if you notice mould and you are concerned as to the possible health risk resulting from its presence, then you should seek advice from your local Council, State or Commonwealth Government Health Department, or a qualified expert such as an Industry Hygienist.

7) Magnesite Flooring Disclaimer: No Inspection for Magnesite Flooring was carried out at the property, and no Report on the presence or absence of Magnesite Flooring is provided. You should ask the owner whether Magnesite Flooring is present and/or seek advice from a Structural Engineer.

8) Estimating Disclaimer: Any estimates provided in this Report are merely opinions of possible costs that could be encountered, based on the knowledge and experience of the inspector, and are not estimates in the sense of being a calculation of the likely costs to be incurred. The estimates are NOT a guarantee or quotation for work to be carried out. The actual cost is ultimately dependent upon the materials used, standard of work carried out, and what a contractor is prepared to do the work for. It is recommended in ALL instances that multiple independent quotes are sourced prior to any work being carried out. The inspector accepts no liability for any estimates provided throughout this Report.

9) Note: If the Client has any doubt about the purpose, scope, and acceptance criteria on which the Report was based please discuss your concerns with the Consultant on receipt of the Report. The Client acknowledges that, unless stated otherwise, the Client as a matter of urgency should implement any recommendation or advice given in this Report.

IMPORTANT DISCLAIMER

Disclaimer Liability: No Liability shall be accepted on an account of failure of the Report to notify any problems in the area(s) or section(s) of the subject property physically inaccessible for Inspection, or to which access for Inspection is denied by or to the Inspector (including but not limited to or any area(s) or section(s) so specified by the Report).

Disclaimer of Liability to Third Parties: Compensation will only be payable for losses arising in contract or tort sustained by the Client named on the front of this Report. Any third party acting or relying on this Report, in whole or in part, does so entirely at their own risk. However, if ordered by a Real Estate Agent or a Vendor for the purpose of auctioning a property, then the Inspection Report may be ordered up to seven (7) days prior to the auction, copies may be given out prior to the auction and the Report will have a life of 14 days during which time it may be transferred to the purchaser. Providing the purchaser agrees to the terms of this agreement, then they may rely on the Report subject to the terms and conditions of this agreement and the Report itself.

NB. In the ACT under the Civil Law (Sale of Residential Property) Act 2003 and Regulations, the Report resulting from this Inspection may be passed to the purchaser as part of the sale process, providing it is carried out no more than three months prior to listing and is not more than six months old.

Limited Liability to a Purchaser within the Australian Capital Territory only: Within the Australian Capital Territory (ACT) and in accordance with the ACT Civil Law (Sale of Residential Property) Act 2003 and Regulations, a copy of the Report may be attached to the Contract for Sale.

WARNING: The Purchaser is advised that this Report reflects the condition of the property existing at the time of the Inspection (Inspection Date) and may not reflect the current state. It is, therefore, very strongly recommended that you promptly arrange for another Inspection and Report in accordance with Australian Standard AS4349.1 to be carried out prior to the expiration of the 'Cooling off Period' and settlement.

This is not a Compliance Report strictly in accordance with Civil Law (Sale of Residential Property) Regulations: The Report may contain copies of any approved plans, building approvals, building permit and Certificates of Occupancy. However, any comments made by the person who prepared the Report as to whether or not, in the opinion of the Inspector, the structures on the land substantially comply with the approved plans (if any) are made on the basis of a cursory glance of the plans and not upon a detailed examination. Any opinion expressed as to whether or not any building approval or approval under the Land (Planning and Environment) Act, 1991, is based on the limited knowledge and belief, at the time, of the Inspector. The Purchaser is advised that a Special Purpose Report is available through the Inspector to advise more fully in respect to these matters. The structures may have been damaged by pests, storm, strong wind or fire or the Vendor may have carried out alterations and/or additions to the Property since the Inspection Date. The Report may no longer reflect the true condition of the Property. The structure(s) may no longer be in accordance with the attached plans etc. IT IS STRONGLY RECOMMENDED that, if the Purchaser has any concerns in respect to the compliance of the structures, a Special Purpose Report be obtained. Alternatively, the Purchaser should rely upon his, her or their own enquiries.

Contact the Inspector: Please feel free to contact the Inspector who carried out this Inspection. Often it is very difficult to fully explain situations, problems, access difficulties, building faults or their importance in a manner that is readily understandable by the reader. Should you have any difficulty in understanding anything contained within this Report, then you should immediately contact the Inspector and have the matter explained to you. If you have any questions at all, or require any clarification, then contact the Inspector prior to acting on this Report.

OTHER INSPECTIONS AND REPORTS REQUIRED

It is strongly recommended that the following Inspections and Reports be obtained prior to any decision to purchase the Property. Obtaining these Reports will better equip the purchaser to make an informed decision. Although appliances may be listed in the Report, they have not been tested as this is outside the scope of the standard Building Inspection. Other Inspections we recommend the purchaser obtains before making their decision are:

- Electrical Inspection,
- Plumbing Inspection,
- Structural (Engineer),
- Geotechnical Inspection,
- Drainage Inspection,
- Asbestos Inspection,
- Mould Inspection,
- Gas fitting Inspection,
- Appliances Inspection,
- Air-conditioning Inspection,
- Alarm/Intercom/Data Systems,
- Hydraulics Inspection,
- Mechanical Services,
- Hazards Inspection,
- Fire/Chimney Inspection,
- Estimating Report,
- Garage Door Mechanical,
- Durability exposed surfaces

SMOKE DETECTORS

The occupier/purchaser should satisfy themselves as to the working condition of the smoke detectors, if installed. It is highly recommended that suitable smoke detectors be installed in all residential properties. AS 3786 advises that smoke detectors are required for all buildings where people sleep. It is recommended that an electrician be consulted to advise on those installed or install these detectors.

CRACKING OF BUILDING ITEMS

Regardless of the type of crack(s), a Pre-Purchase Building Inspector carrying out a Pre-Purchase Inspection within the scope of a visual Inspection is unable to determine the expected consequences of the cracks.

Obtaining Information regarding the below all fall outside the scope of this Pre-Purchase Inspection:

(a) The nature of the foundation material on which the building is resting,
(b) The design of the footings,
(c) The site landscape,
(d) The history of the cracks and,
(e) Carrying out an invasive Inspection.

However, the information obtained from the five items above is valuable in determining the expected consequences of the cracking and any remedial work needed. Cracks that are small in width and length on the day of the Inspection may have the potential to develop over time into structural problems for the homeowner, resulting in major expensive rectification work being carried out. If cracks have been identified in the Report above, then a Structural Engineer is required to determine the significance of the cracking prior to a decision to purchase**.**

NOTICE TO THE PURCHASER (ACT ONLY)

(a) At the Exchange, and prior to the 'Cooling-off Period', you were given an Inspection Report on the property you intend on purchasing. This Report reflects the condition of the property existing at the time of the Inspection (Inspection Date) and may not reflect the current state. The structures may have been damaged by pests, storm, strong wind or fire or the vendor may have carried out alterations and/or additions to the property since the Inspection date. The Report may no longer reflect the true condition of the property. The structure(s) may no longer be in accordance with the attached plans etc. It is, therefore, very strongly recommended that you urgently arrange for another Inspection and Report in accordance with Australian Standard AS 4349.1 to be carried out prior to exchange, or prior to the expiration of any 'Cooling Off Period' and prior to settlement.

(b) If the Report indicated the presence of termite damage, or recommends any other Inspections or treatments, you should obtain copies of these Reports and any treatment proposals, certificates of treatment carried out, including details of all repairs including copies of quotations, invoices, and any other Reports. It is strongly recommended that you arrange for an Inspection and Report in accordance with AS 4349.3 to verify that the treatment has been successful and carried out in accordance with AS 3660.2, and a further building Inspection in accordance with AS 4349.1.

(c) If you fail to procure a further Inspection and Report as recommended in (a) and (b), or fail to obtain copies of other Reports, treatment proposals, certificates of treatment carried out, details of all repairs including copies of quotations, invoices and any other Reports as recommended in (b) above, then you agree that you have decided not to have a further Inspection and Report carried out, or to obtain copies of treatment proposals, certificates of treatment carried out, details of all repairs including copies of quotations, invoices and any other Reports and have relied upon your own enquires and the Report, knowing the possible consequences, and that the condition of the property, as stated in the Report, may have changed.

(d) You agree that the person carrying out the Inspection **and** the company, partnership or sole trader that employs that person will have no liability to you for any damage or loss you may suffer as a result of your entering the contract to purchase the property, or in connection with completing the purchase of the property as a result of your failure to heed the advice given in (a) and (b) and the warning contained in (c) above, and may use such failure in defense of any claim that you may later make against any of them.

NB. It is a condition of your right to rely upon the Report that you transmit by fax, post, or otherwise deliver the signed "Notice to the Purchaser" (ACT only) to the company, partnership or sole trader at the address detailed on the front of the Report not less than four (4) days prior to the date of settlement. If you fail to complete, sign, or deliver the Notice then it will be deemed that you did not rely upon the report in respect to your decision as to whether or not to purchase the property. This may seriously affect any rights to future compensation to which you may be entitled.

Please cross out the statement below that does not apply: - At the date of settlement, not more than 180 days will have elapsed since the Inspection date.

1. I/We have read and understood the 'Limited Liability to a Purchaser within the Australian Capital Territory only' clause of the Report, and this Notice to the Purchaser. I/We have not arranged for another inspection and report in respect of the property, and it is my/our intention to **rely upon the findings contained in the report**; or

2. I/We have **arranged for another Inspection of the Property and Report** to be carried out, which I/We will use in conjunction with this Report in deciding whether to proceed with the purchase of the property; or

3. I/We have read and understood the 'Limited Liability to a Purchaser within the Australian Capital Territory only' clause of the Report, and this Notice to the Purchaser. I/We have not arranged for another Inspection and Report in respect of the property and have **relied on my/our own enquiries in respect of the condition of the property** as at the date of settlement including any changes in the condition of the property that have taken place since the Inspection date stated in the Report

ACT PROPERTY INSPECTIONS

Timber Pest Report

SUMMARY SHEET

Property Address:	10 Elliott St, Campbell ACT 2612
Client:	McCormack & Wright
Inspection Date:	Friday, April 10th 2026
Inspection carried out by:	Duncan Clark

This summary is supplied to allow a quick and superficial overview of the Inspection results. This summary is NOT the Report and cannot be relied upon on its own. This summary must be read in conjunction with the full Report and not in isolation from the Report. If there should happen to be any discrepancy between anything in the Report, and anything in this summary, the information in the Report shall override that in the summary. The Report is subject to conditions and limitations. Your attention is particularly drawn to the clauses, disclaimer of liability to third parties, limited liability to a purchaser with the Australian Capital Territory (ACT), and to the notice to the purchaser at the back of this Report.

1.0 ACCESS LIMITATIONS

There were access limitations to the inspection/report. Please refer to section 1.0 of the report.

2.0 TERMITE ACTIVITY

No active subterranean termites (live specimens) were found.

No visible evidence of subterranean termite workings or damage was found.

3.0 BORER ACTIVITY

No visible evidence of borers of seasoned timbers was found.

4.0 DECAY FUNGI

No evidence of damage caused by wood decay (rot) fungi was found.

For complete and accurate information, please refer to the attached 'Visual Timber Pest Report', which is prepared in accordance with AS 4349.3.

CONDITIONS OF THIS INSPECTION

Important Information:

Any person who relies upon the contents of this Report does so acknowledging that the following clauses, which define the scope and limitations of the Inspection, form an integral part of the Report.

This is a **Visual Inspection Only**, prepared in accordance with AS 4349.3, 'Inspection of Buildings Part 3: Timber Pest Inspections'. Visual Inspection was limited to those areas and sections of the property to which reasonable access (see definition) was both available and permitted on the date of Inspection.

The Inspection **did not** include breaking apart, dismantling, removing, or moving objects including but not limited to – foliage, mouldings, roof insulation/sisalation, floor or wall coverings, sidings, ceilings, floors, furnishings, appliances, or personal possessions.

The Inspector **cannot** see inside walls, between floors, inside skillion roofing, inside the eaves, behind stored goods in cupboards, or in any other areas that are concealed or obstructed.

The Inspector **did not** dig, gouge, force or perform any other invasive procedures. An invasive Inspection will not be performed unless a separate contract is entered into.

In an occupied property, it must be understood that furnishings or household items may be concealing evidence of Timber Pests, which may only be revealed when the items are moved or removed.

In the case of strata type properties, only the interior of the unit is inspected.

Scope of Report:

This Report only deals with the detection or non-detection of Timber Pest Attack and Conditions Conducive to Timber Pest Attack discernible at the time of inspection. The inspection was limited to the Readily Accessible Areas of the Building and Site (see note below) and was based on a visual examination of surface work (excluding furniture and stored items), and the carrying out of Tests. Note. With strata and company title properties, the inspection was limited to the interior and the immediate exterior of the particular residence inspected. Common property was not inspected.

Limitations:

The Client acknowledges:

(a) This Report does not include the inspection and assessment of matters outside the scope of the requested inspection and report.

(b) The inspection only covered the Readily Accessible Areas of the Building and Site. The inspection did not include areas which were inaccessible, not readily accessible or obstructed at the time of inspection. Obstructions are defined as any condition or physical limitation which inhibits or prevents inspection and may include – but are not limited to – roofing, fixed ceilings, wall linings, floor coverings, fixtures, fittings, furniture, clothes, stored articles/materials, thermal insulation, sarking, pipe/duct work, builder's debris, vegetation, pavements, or earth.

(c) The detection of dry wood termites may be extremely difficult due to the small size of the colonies. No warranty of absence of these termites is given.

(d) European House Borer (Hylotrupes bajulus) attack is difficult to detect in the early stages of infestation as the galleries of boring larvae rarely break through the affected timber surface. No warranty of absence of these borers is given. Regular inspections including the carrying out of appropriate tests are required to help monitor susceptible timbers.

(e) This is not a structural damage report. Neither is this a warranty as to the absence of Timber Pest Attack.

(f) If the inspection was limited to any particular type(s) of timber pest (e.g., subterranean termites), then this would be the subject of a Special-Purpose Inspection Report, which is adequately specified.

(g) This Report does not cover or deal with environmental risk assessment or biological risks not associated with Timber Pests (e.g., toxic Mould) or occupational, health or safety issues. Such advice may be the subject of a Special-Purpose Inspection Report which is adequately specified and must be undertaken by an appropriately qualified inspector. The choice of such inspector is a matter for the Client.

(h) This Report has been produced for the use of the Client. The Consultant or their firm or company are not liable for any reliance placed on this report by any third party, except as provided in the section Limited Liability To a Purchaser within the Australian Capital Territory.

Determining extent of Damage:

This is not a structural building report, and any inexpert opinion we provide on timber damage cannot be relied upon. This Report **will not** state the full extent of any Timber Pest damage. It will state Timber Pest Damage found as either 'slight', 'moderate', 'moderate to extensive', or 'extensive', and this information is not the opinion of an expert. If any evidence of Timber Pest activity and/or damage resulting from Timber Pest activity is reported, either in the structure(s) or the grounds of the property, then you must assume that there may be concealed structural damage within the building(s).

This concealed damage may only be found when wall linings, cladding or insulation are removed to reveal previously concealed timbers. In this case, an Invasive Timber Pest Inspection (for which a separate contract is required) is strongly recommended, and you should arrange for a qualified professional such as a builder, engineer, or architect to carry out a structural Inspection to determine the full extent of the damage, and the extent of repairs that may be required. You agree that neither we, nor the individual conducting the Inspection, are responsible or liable for the repair of any damage, whether disclosed by the Report or not.

Disclaimer of Liability:

No liability shall be accepted on account of failure of the Report to notify any termite activity and/or damage present at, or prior to, the date of the Report, in any area(s) or section(s) of the subject property physically inaccessible for Inspection, or to which access for Inspection is denied by, or to, the licensed Inspector (including, but not limited to, any area(s) or section(s) specified by the Report).

1.0 ACCESS LIMITATIONS

1.1 Area(s) inspected:

Only structures, fences &/or trees within 50m of the building but within the property boundaries were inspected.

1.2 Common area(s) not inspected:

No Inspection was made, and no Report will be submitted, of inaccessible area(s).
These include, but may not be limited to; cavity walls, concealed frame timbers, eaves, flat roofs, fully enclosed patios, inaccessible parts of the subfloors, inaccessible parts of the roof void, soil concealed by concrete floors, fireplace hearths, wall linings, landscaping, rubbish, floor coverings, furniture, pictures, appliances, stored items, insulation, and hollow blocks/posts etc.

1.3 Area(s) in which visual inspection was obstructed or restricted and why:

Clothing and other stored items concealed timbers in cupboards and built in robes/closets. Furniture and stored items concealed some of the skirting boards and architraves inside the house. No access was gained to the roof cavity due to the flat roof construction.

NB. Please note that since a complete Inspection of the above area(s) was not possible, Timber Pest activity and/or damage may exist in these areas.

1.4 The property was furnished at the time of inspection.

Where a property is furnished at the time of Inspection, it must be understood that the furnishings and stored goods may be concealing evidence of Timber Pest activity. This evidence may be revealed when the property is vacated, and a further Inspection of the vacant property is strongly recommended if the house was furnished at the time of inspection.

1.5 Undetected timber pest risk assessment is considered Low/Moderate.

NB. Where the risk is considered “Moderate” or “Moderate-High” or “High”, a further inspection is strongly recommended of areas that were not readily accessible, and of inaccessible or obstructed areas once access has been provided or the obstruction removed. This may require the moving, lifting or removal of obstructions such as floor coverings, furniture, stored items foliage and insulation. In some instances, it may also require the removal of ceiling and wall linings, and the cutting of traps and access holes. Seek further advice from your Consultant.

2.0 TERMITE ACTIVITY

2.1 No active (live) termites were present at the time of Inspection.

2.2 No visible evidence of subterranean termite workings and/or damage was found.

2.3 A termite nest was not found.

2.4 No evidence of timber damage caused by Termite attack was visible at the time of the Inspection.

NB. Where evidence of termite activity by the Nasutitermes or Coptotermes species was found in the grounds, the risk to buildings is very high. A treatment to eradicate the termites and to protect the building(s) should be carried out. Where the evidence of termite workings was found in the grounds or the building(s), then the risk of a further attack is very high.

2.5 Very important:

If live termites or any evidence of termite workings or damage was reported above, within the building(s) or in the grounds and fences, then it must be assumed that there may be concealed termite activity and/or timber damage. This concealed activity or damage may only be found when alterations are carried out, such as when wall linings, cladding or insulation are removed; or if you arrange for an invasive Inspection. We claim no expertise in structural engineering or building, and we strongly recommend that you have a qualified professional such as a builder, engineer, architect, or other qualified expert determine the full extent of the damage, if any. This may require an invasive Inspection. We take no responsibility for the repair of any damage, whether disclosed by this Report or not (see 'Terms and Limitations').

Where visual evidence of termite workings and/or damage is reported above, but no live termites were present at the time of Inspection, you must realise that it is possible that termites are still active in the immediate vicinity, and that the termites may continue to cause further damage. It is not possible, without further investigation and a number of Inspections over a period of time, to ascertain whether any infestation is active or inactive. Active termites may simply have not been present at the time of Inspection due to a prior disturbance or climatic conditions, or they may have been utilizing an alternative feeding source.

Continued, regular Inspections are essential. Unless written evidence of a termite protection program in accordance with 'AS 3660' with ongoing Inspections is provided, you must arrange for a treatment in accordance with 'AS 3660' to be carried out to reduce the risk of further attack.

2.6 Previous termite treatment: There were no signs of a termite treatment or evidence of a possible previous termite treatment, at the time of inspection.

NB. If there is evidence of drill holes in concrete or brickwork, bait stations or other signs of a possible previous treatment are reported, then the treatment was probably carried out because of an active termite attack. Extensive structural damage may exist in concealed areas. You should have an invasive Inspection carried out, and have a builder determine the full extent of any damage, and the estimated cost of repairs, as the damage may only be found when wall linings etc. are removed. Normally, if a termite treatment has been carried out, then a durable notice should be located in the metre box, indicating the type of termite shield system, treated zone or combination that has been installed.

2.7 Termite management: A durable notice (termite management notice) was found during the inspection, indicating a barrier system has been installed. The system installed is Termimesh.

This firm can give no assurances with regard to work that may have been previously performed by other firms. You should obtain copies of all paperwork and make your own enquiries as to the quality of the treatment when it was carried out, and warranty information. In most cases, you should arrange for a treatment in accordance with "Australian Standard 3660" to be carried out to reduce the risk of further attack.

2.8 General remarks:

Where any current visible evidence of Timber Pest activity is found, it is strongly recommended that a more invasive Inspection be performed. Trees on and near the property up to a height of 2 metres, have been visually Inspected where possible and practicable, for evidence of Termite activity. It is very difficult to locate termite nests since they are underground, and evidence in trees is usually well concealed. Therefore, we strongly recommend that you arrange to have the medium to large eucalypt trees within a 50 metre radius of the property test drilled for evidence of termite nests.

3.0 BORER ACTIVITY

3.1 No visible evidence of borers was found.

The **Lyctid Borer** - The most common lyctid borer in Australia is **Lyctus brunneus (powder post beetle**). Attack usually takes place during the first six to twelve months of the service life of timber. However, the powder post beetle is not considered a significant pest of timber and treatment of infestation is not usually required. As only the sapwood of certain hardwoods is destroyed, larger-dimensional timbers (such as rafters, bearers, and joists) in a building are seldom weakened significantly to cause collapse. The **Anobiid Borer** There are many different species of Anobiid borer, the most frequently encountered being Anobium punctatum (furniture beetle) and Calymmaderus incisus (Queensland pine beetle). Attack mainly occurs to softwoods especially pine timbers such as floorboards that have been in service for at least ten years. Should any structural timbers be attacked by Anobiid borers it is often difficult to determine what extent the borer damage has weakened such timbers and replacement is often the only way of ensuring safety from collapse.

In the case of Anobiid borers, once an attack is initiated it is unlikely to cease or die out of its own accord without some sort of eradication treatment. Therefore, unless proof of treatment is provided, evidence of an attack must always be considered active. Although a chemical treatment is an option, replacement of infested timbers with non-susceptible, or treated timber, is the most effective method of treatment. Before any option is considered, competent advice (e.g., from a licensed building contractor) should be sought to determine the extent of any structural damage, and as to the need or otherwise for rectification or repair work.

Other Borers: A further (more invasive) investigation is strongly recommended to determine whether infestation is still active and to positively identify the borer species responsible for the attack. Always seek further advice from the Consultant.

Management Program: Wherever practical, remove any conditions conducive to attack (e.g., Anobium borer thrive in badly ventilated subfloor areas). Regular inspections are recommended at intervals not exceeding 12 months. Always seek further advice from the Consultant.

4.0 DECAY FUNGI

4.1 No evidence of damage caused by wood decay (rot) fungi was found.

NB. If any evidence of fungal decay or damage is reported, you should consult a building expert to determine the full extent of damage, and the estimated cost of repairs or timber.

General Description of Attack Decaying wood contains sufficient moisture to retain its original shape and may have sufficient strength to withstand normal loads. In contrast decayed wood is reduced both in moisture content and size as indicated by cracking either along or across the grain or fibres coming apart in a stringy manner. Decayed wood will have undergone considerable strength reduction.

Economic Significance Fungal decay can cause at one extreme, structural failure of the affected timber, and at the other purely superficial surface damage. The most critical determination is that of which timber is affected and decaying because decay will most likely spread (unless sources of moisture are quickly removed). Affected and decayed timber may warrant timber replacement, but the rot should not spread unless a new moisture source becomes available in that area.

Where evidence of decayed timber exists, competent advice (e.g., from a licensed or registered building contractor) should be sought to determine the extent of any structural damage, and as to the need or otherwise for rectification or repair work. It is important to correct any condition conducive to attack prior to replacing decayed wood.

Where evidence of decaying timber exists, competent advice (e.g., from a licensed or registered building contractor) should be sought to remove the condition(s) conducive to attack, and to determine the extent of any structural damage, and as to the need or otherwise for rectification or repair work.

Where the full extent of damage or the overall condition of the timber is undetermined a further inspection is strongly recommended by a competent person (e.g., from a licensed or registered building contractor). This may require monitoring of the timber over a period and include the assessment of conditions conducive to attack in different weather conditions (e.g., to determine the adequacy of existing drainage).

Management Program Remove any conditions conducive to attack (e.g., lack of ventilation or the presence of excessive moisture). Regular inspections are recommended at intervals not exceeding 12 months. Always seek further advice from the Consultant.

5.0 CONDITIONS THAT ARE CONDUCIVE TO TIMBER PESTS

5.1 Water leaks: At the time of the inspection no leaks were found to be present.

Water leaks, especially in or into the subfloor, or against the external walls; increase the likelihood of termite attack. Leaking showers or leaks from other `wet areas' also increase the likelihood of concealed termite attack. Hot water overflows should be plumbed away from the building.
NB. We claim no expertise in building, and if any leaks were reported, you should consult a plumber or other building expert to determine the full extent of damage, and the estimated cost of repairs.

5.2 Moisture/drainage: Not applicable as the home is built on a concrete slab.

Lack of Adequate Subfloor Ventilation Inadequate ventilation provides a condition suitable for timber pest infestation. For example, subterranean termites thrive in damp humid conditions typical of those provided in a poorly ventilated subfloor space. Where evidence of a lack of adequate ventilation has been identified in the report, the Client should seek competent advice (e.g., from a licensed or registered building contractor) regarding upgrading ventilation. The Presence of Excessive Moisture Ground levels around the building should be maintained in such a way to minimise water entering under the building. Also, the ground surface in subfloor areas should be kept graded to ensure that moisture does not pond or accumulate in any area. Where necessary, sub-surface drains should be installed and maintained to assist with drainage around and under the building. Likewise, the presence of excessive moisture can often be directly related to ventilation limitations and the resultant high humidity. Also, plumbing oversights and defects such as a leaking drain or tap will provide a microclimate conducive to timber pest attack. Where necessary, the Client should seek competent advice (e.g., from a licensed or registered plumbing contractor) to determine the adequacy of existing drainage and remove any conditions conducive to the presence of excessive moisture. The building may need to be monitored over a period of time to detect or confirm a damp problem. The presence of dampness (including moisture) is not always consistent as the prevailing and recent weather conditions at the time an inspection is carried out may affect the detection of damp problems. Importantly, precipitation at or near the time of inspection does not necessarily guarantee that a damp problem will automatically be evident due to such circumstances as prevailing wind conditions or intensity of rainfall. The absence of any dampness at the time of inspection does not necessarily mean the building will not experience some damp problems in other weather conditions. Likewise, whether services have been used for some time prior to an inspection being carried out will affect the detection of dampness.

5.3 Ventilation: Not applicable as the home is built on a concrete slab.

Lack of Adequate Subfloor Ventilation Inadequate ventilation provides a condition suitable for timber pest infestation. For example, subterranean termites thrive in damp humid conditions typical of those provided in a poorly ventilated subfloor space. Where evidence of a lack of adequate ventilation has been identified in the report, the Client should seek competent advice (e.g., from a licensed or registered building contractor) in regard to upgrading ventilation.

5.4 Hot water services and air conditioning units: There is no need for this work to be carried out.

Hot water services and air conditioning units which release water alongside or near to building walls should be piped to a drain (if not possible then several metres away from the building), as the resulting wet area is highly conducive to termites.

5.5 Slab edge exposure: The slab edge inspection zone does not apply to this property.

Where external concrete slab edges are not exposed, there is a high risk of concealed termite entry.
In some buildings built since July 1995, the edge of the slab forms part of the termite shield system. In these buildings an Inspection zone of at least 75mm should be maintained to permit detection of termite entry. The edge should not be concealed by render, tiles, cladding, flashings, adjoining structures, paving, soil, turf, or landscaping etc. Where this is the case, you should arrange to have the slab edge exposed for Inspection.
Concealed termite entry may already be taking place but could not be detected at the time of the Inspection. This may have resulted in concealed timber damage.
NB. A very high proportion of termite attacks are over the slab edge. Covering the slab edge makes concealed entry easy. This is particularly true of infill type slab construction. Termite activity and/or damage may be present in concealed timbers of the building. We strongly recommend frequent regular inspections in accordance with AS 3660.2.

5.6 Weep holes in external walls: Weep holes were clear allowing the free flow of air.

It is very important that soil, lawn, concrete paths, or pavers do not cover the weep holes. Sometimes, they have been covered during the rendering of the brick work. They should be clean and free flowing and covering the weep holes in part or in whole may allow undetected termite entry.

5.7 Termite shields: Not applicable as the home is built on a concrete slab.

Termite Shields (Ant Caps) should be in good order and condition, so termite workings are exposed and visible. This helps prevent termites from gaining undetected entry. Joins in the shielding should have been soldered during the installation. If it is observed that the joins in the shielding have not been soldered, then the shielding must be reported as inadequate. It may be possible for a builder to repair the shielding. If not, a chemical treated zone may need to be installed to deter termites from gaining concealed access to the building. Missing, damaged or poor shields increase the risk of termite infestation. If considered inadequate, a builder or other building expert should be consulted.
Other physical shield systems are not visible to inspection and no comment is made on such systems.

5.8 Bridging or breaching of termite barriers and inspection zones: No bridging or breaching was found.

“Bridging” is the spanning of a termite barrier or inspection zone so that subterranean termites are provided with passage over or around that barrier. “Breaching” is the making of a hole or gap in a termite barrier so that termites are provided with a passage through that barrier.

5.9 Other area(s) and/or situations that appear conducive to (may attract) subterranean termite infestation: Medium to large trees and stumps within a 50 metre radius of the property, due to the nesting conditions.

6.0 OVERALL ASSESSMENT OF THE PROPERTY

6.1 Where evidence of live termites, termite damage or termite workings (mudding) was found in the building(s) then the risk of a further attack is extremely high.

Where evidence of live termites, termite damage or termite workings was found in the grounds but not in the building(s) then the risk to buildings must be reported as high to extremely high.

6.2 At the time of the Inspection, the degree of risk of subterranean termite infestation to the overall property was considered to be **Moderate to High.**

6.3 Subterranean Termite Treatment Recommendation: A management program in accordance with AS 3660-2000 to protect against subterranean termites is considered **not essential, but 6 to 12 monthly inspections are essential.**

6.4 Future Inspections: AS 3660.0-2000 recommends "regular competent Inspections should be carried out at least on an annual basis, but more frequent Inspections are strongly recommended".

It goes on to inform that "regular Inspections will not prevent termite attack but may help in the detection of termite activity. Early detection will allow remedial treatment to be commenced sooner, and damage to be minimized".

Due to the degree of risk of subterranean termite infestation noted above and all other findings of this Report; we strongly recommend that a full Inspection and written Report in accordance with AS 4349.3 or AS 3660.2-2000 is conducted at this property every 6 months, but no more than 12 months.

DEFINITIONS

Timber Pest Attack: Means Timber Pest Activity and/or Timber Pest Damage.
Timber Pest Activity: Means telltale signs associated with 'active' (live) and/or 'inactive' (absence of live) Timber Pests at the time of inspection.
Timber Pest Damage: Means noticeable impairments to the integrity of timber and other susceptible materials resulting from attack by Timber Pests.
Major Safety Hazard: Means any item that may constitute an immediate or imminent risk to life, health or property resulting directly from Timber Pest Attack. Occupational, health and safety or any other consequence of these hazards has not been assessed.
Conditions Conducive to Timber Pest Attack: Means noticeable building deficiencies or environmental factors that may contribute to the presence of Timber Pests.
Readily Accessible Areas: Means areas which can be easily and safely inspected without injury to person or property, are up to 3.6 metres above ground or floor levels, in roof spaces where the minimum area of accessibility is not less than 600 mm high by 600 mm wide and subfloor spaces where the minimum area of accessibility is not less than 400 mm high by 600 mm wide, providing the spaces or areas permit entry. The term 'readily accessible' also includes accessible subfloor areas on a sloping site where the minimum clearance is not less than 150 mm high, provided that the area is not more than 2 metres from a point with conforming clearance (i.e., 400 mm high by 600 mm wide); and areas at the eaves of accessible roof spaces that are within the consultant's unobstructed line of sight and within arm's length from a point with conforming clearance (i.e. 600 mm high by 600 mm wide).
Client: Means the person or persons for whom the Timber Pest Detection Report was carried out or their Principal (i.e., the person or persons for whom the report was being obtained).
Timber Pest Detection Consultant: Means a person who meets the minimum skills requirement set out in the current Australian Standard AS 4349.3 Inspections of Buildings. Part 3: Timber Pest Inspection Reports or state/territory legislation requirements beyond this Standard, where applicable.
Building and Site: Means the main building (or main buildings in the case of a building complex) and all timber structures (such as outbuildings, landscaping, retaining walls, fences, bridges, trees, and stumps with a diameter greater than 100 mm and timber embedded in soil) and the land within the property boundaries up to a distance of 50 metres from the main building(s).
Timber Pests: Means one or more of the following woods destroying agents which attack timber in service and affect its structural properties:
Chemical Delignification: The breakdown of timber through chemical action.
Fungal Decay: The microbiological degradation of timber caused by soft rot fungi and decay fungi, but does not include Mould, which is a type of fungus that does not structurally damage wood.
Wood Borers: Wood destroying insects belonging to the order 'Coleoptera' which commonly attack seasoned timber.
Termites: Wood destroying insects belonging to the order 'Isoptera' which commonly attack seasoned timber.
Tests: Means additional attention to the visual examination was given to those accessible areas which the consultant's experience has shown to be particularly susceptible to attack by Timber Pests. Instrument testing of those areas and other visible accessible timbers/materials/areas showing evidence of attack was performed.
Instrument Testing: Means where appropriate the carrying out of Tests using the following techniques and instruments:
(a) Electronic moisture detecting meter - an instrument used for assessing the moisture content of building elements.
(b) Stethoscope - an instrument used to hear sounds made by termites within building elements.
(c) Probing - a technique where timber and other materials/areas are penetrated with a sharp instrument (e.g., bradawl or pocket knife), but does not include probing of decorative timbers or finishes, or the drilling of timber and trees; and
(d) Sounding - a technique where timber is tapped with a solid object.

IMPORTANT MAINTENANCE ADVICE REGARDING INTEGRATED PEST MANAGEMENT FOR PROTECTING AGAINST TIMBER PESTS

You should read and understand the following important information. It will help explain what is involved in a Timber Pest Inspection, the difficulties faced by a Timber Pest Inspector, and why it is not possible to guarantee that a property is free of Timber Pests. It also details important information about what you can do to help protect your property from Timber Pests. This information forms an integral part of the Report. Any structure can be attacked by Timber Pests. Periodic maintenance should include measures to minimise possibilities of infestation in and around a property. Factors which may lead to infestation from Timber Pests include situations where the edge of the concrete slab is covered by soil or garden debris, filled areas, areas with less than 400mm clearance, foam insulation at foundations, earth/wood contact, damp areas, leaking pipes, etc.; form-work timbers, scrap timber, tree stumps, mulch, tree branches touching the structure, wood rot, etc. Gardens, pathways, or turf abutting or concealing the edge of a concrete slab will allow for concealed entry by timber pests any timber in contact with soil such as form -work, scrap timbers or stumps must be removed from under and around the buildings and any leaks repaired. You should endeavor to ensure such conditions DO NOT occur around your property. We further advise that you engage a professional pest control firm to provide a termite management program in accord with AS 3660 to minimise the risk of termite attack. There is no way of preventing termite attack. Even AS 3660 advises that "the provision of a complete termite barrier will impede and discourage termite entry into a building. It cannot prevent termite attack. Termites can still bridge or breach barriers, but they can be detected more readily during routine inspections."

Reasonable access:

Unless specified in writing, the inspection only covered the Readily Accessible Areas of the Building and Site.

The inspection did not include areas which were inaccessible, not readily accessible or obstructed at the time of inspection. Areas which are not normally accessible were not inspected and include - but not limited to – inside walls, the interior of a flat roof or beneath a suspended floor filled with earth.

Building Interior, the Consultant did not move or remove any ceilings, wall coverings, flooring, floor coverings (including carpeting), furnishing, equipment, appliances, pictures, or other household goods. In an occupied property, furnishings or household items may be concealing evidence of timber pest attack which may only be revealed when the items are moved or removed.

Building Exterior, Roof Exterior and Site, the Consultant did not move or remove any obstructions such as wall cladding, awnings, trellis, earth, plants, bushes, foliage, stored materials, debris, or rubbish. Due to the 'secretive' nature of timber pests, it is possible that hidden damage may exist in concealed areas, e.g., wall framing. Damage may only be found when the obstruction is removed. In the case of buildings constructed on concrete slabs, if the edge of the slab or any weep hole or vent at the base of external walls is concealed by pavements, gardens, lawns, or landscaping then it is possible for termites to gain undetected entry into the building. The building of gardens or planting of shrubs close to the perimeter of the building can promote and conceal termite entry points. The storage of cellulose materials such as building materials and firewood near the ground or building may encourage termite activity.

Roof Space Obstructions such as roofing, stored articles, thermal insulation, sarking, and pipe/duct work may be concealing evidence of timber pest attack which may only be revealed when the obstructions are moved or removed. Also, bodily access should be provided to the interior of all accessible roof spaces. In accordance with Australian Standard ASS 4349 the minimum requirement is a 400mm by 500 mm access manhole.

Subfloor Space Subfloor areas should be kept free from all vegetation (including tree stumps) and other cellulose material which may encourage timber pest activity. Also, storage of materials in subfloor areas is not recommended as it reduces ventilation and makes inspection difficult. Obstructions may be concealing evidence of timber pest attack which may only be revealed when the obstructions are moved or removed. Bodily access should be provided to all accessible subfloor areas with the minimum requirement being a 500 mm x 400 mm access manhole. In the case of suspended floors, if the clearance between the ground and structural components is less than 400 mm, then the ground should be excavated to provide the required clearance, subject to maintaining adequate drainage and support to footings. If the subfloor has been sprayed for subterranean termites or if the area is susceptible to mould growth, appropriate health precautions must be followed before entering the area. Also, special care should be taken not to disturb the treated soil. Always seek further advice from the Consultant.

A further inspection is strongly recommended of those areas that were not readily accessible and of inaccessible or obstructed areas once access has been provided or the obstruction removed. This will involve a separate visit to the site, permission from the owner of the property and additional cost.

Unless stated otherwise, any recommendation or advice given in this Report should be implemented as a matter of urgency.

A more invasive physical inspection is available and recommended:

As detailed above, there are many limitations to this visual Inspection only. With the permission of the owner of the premises we WILL perform a more invasive physical inspection that involves moving or lifting insulation, stored items, furniture, or foliage during the inspection. We WILL physically touch, tap, test and when necessary, force/gouge suspected accessible timbers. We WILL gain access to areas, where physically possible and considered practical and necessary, by way of cutting traps and access holes.

This style of Report is available by ordering with several days' notice. Inspection time for this style of Report will be greater than for a VISUAL INSPECTION.

It involves disruption in the case of an occupied property, and some permanent marking is likely. You must arrange for the written permission of the owner who must acknowledge all the above information and confirm that our firm will not be held liable for any damage caused to the property.

A price is available on request.

Concrete slab homes:

Homes constructed on concrete slabs pose special problems with respect to termite attack. If the edge of the slab is concealed by concrete paths, patios, pavers, garden beds, lawns, foliage, etc. then it is possible for termites to affect concealed entry into the property, and they can then cause extensive damage to concealed framing timbers. Even the most experienced Inspector may be unable to detect their presence due to concealment by wall linings. Only when the termites attack timbers in the roof void, which may in turn be concealed by insulation, can their presence be detected. Where termite damage is in the roof, it should be expected that concealed framing timbers will be extensively damaged. With a concrete slab home, it is imperative that you expose the edge of the slab and ensure that foliage and garden beds do not cover the slab edge. Weep holes must be kept free of obstructions.

It is strongly recommended that you have a Termite Inspection in accordance with AS 3660.2 carried out every 6 to 12 months.

Subterranean termites:

No property is safe from termites. General Description of Attack Timber hollowed beneath; some cracking at the surface of timber; earthen channels present; or pale faecal spots present.

Important note:

As a delay may exist between the time of an attack and the appearance of telltale signs associated with the attack, it is possible that termite activity and damage exists though not discernible at the time of inspection.

Treatment After discovery of an active infestation, it is imperative that the species of termite is accurately identified before costly (and sometimes unnecessary or inappropriate) methods of treatment are initiated. Only economically important species which are known to attack timber structures should be treated.

In the case of economically important species, it is important that the termite workings are not further disturbed until the proposed method of control has been determined by a licensed pest control operator. Premature attempts to repair or replace infested timber may cause the termites to withdraw from the area temporarily, thereby hindering effective treatment. Any repair or replacement of infested timber should be carried out after the appropriate treatment has been completed.

Where evidence of active termites is detected within a building or within 50 metres of any building, it must always be assumed that the termites may also be active in areas of the property not inspected. Accordingly, where the termites are known to be of economic significance, a further (more invasive) inspection is strongly recommended of areas which were inaccessible, not readily accessible or obstructed at the time of inspection.

Termite Workings and Damage Where evidence of damage to building timbers exists, competent advice (e.g. from a licensed or registered building contractor) should be obtained to determine the extent of any structural damage and as to the need or otherwise for rectification or repair work.

Where evidence of inactive termites is located within the building, it is possible that termites are still active in areas of the property not inspected and they may continue to cause damage. A furthermore invasive inspection is strongly recommended of areas which were inaccessible, not readily accessible or obstructed at the time of inspection.

Where evidence of an inactive termite infestation exists, it is not possible, without benefit of further investigation and inspections over a period, to ascertain whether any infestation is active or inactive. Continued, regular, inspections are essential.

Where evidence of termite attack exists to any trees or tree stumps a more conclusive search should be undertaken. This may require the tree or stump to be drilled to determine the existence of a termite nest. In addition, the soundness and stability of any standing trees identified as being affected by termite attack should be confirmed. Always seek further advice from the Consultant.
Previous Treatments Where evidence of a possible termite treatment was located, the Client should obtain and keep on file all relevant documents pertaining to the extent of the treatment, any service warranties and advice in regard to the building owner's obligation to maintain the treatment and/or barrier. If evidence of a previous treatment of termite infestation is noted, and appropriate documentation is not available, the Client must assume that the termite infestation may still be active in areas of the property not inspected. Accordingly, a re-treatment may be required. Always seek further advice from the Consultant.
Frequency of Future Inspections Australian Standard AS 3660 recognises that regular inspections will not prevent termite attack but may help in the detection of termite activity. Early detection will allow remedial treatment to be commenced sooner and damage to be minimised.
Inspections at intervals not exceeding twelve (12) months are recommended. Where the termite risk is high or the building type susceptible to termite attack, more frequent inspections (3-6 months) should be undertaken.

Risk management options:

To help protect against financial loss, it is essential that the building owner immediately control or rectify any evidence of destructive timber pest activity or damage identified in this inspection report. The Client should further investigate any high-risk area where access was not gained. It is strongly advised that appropriate steps be taken to remove, rectify or monitor any evidence of conditions conducive to timber pest attack.
To help minimise the risk of any future loss, the Client should consider whether the following options to further protect their investment against timber pest infestation are appropriate for their circumstances:
Undertake thorough regular inspections at intervals not exceeding twelve months or more frequent inspections where the risk of timber pest attack is high, or the building type is susceptible to attack. To further reduce the risk of subterranean termite attacks, implement a management program in accordance with Australian Standard AS 3660. This may include the installation of a monitoring and/or baiting system, or chemical and/or physical barrier. However, AS 3660 stresses that subterranean termites can bridge, or breach barrier systems and inspection zones and that thorough regular inspection of the building are necessary.

CONTACT THE INSPECTOR

Please feel free to contact the Inspector who carried out this inspection. Often it is very difficult to fully explain situations, problems, access difficulties or timber pest activity and/or damage in a manner that is readily understandable by the reader. Should you have any difficulty in understanding anything contained within this Report, then you should immediately contact the Inspector and have the matter explained to you.
If you have any questions at all or require any clarification, then contact the Inspector prior to acting on this Report.

NOTICE TO THE PURCHASER

(a) Prior to or on Exchange, and prior to the commencement of the 'Cooling-off Period', you were given an Inspection Report on the Property you intend on purchasing ("the Report"). The Purchaser is advised that this Report reflects the condition of the property existing at the time of the Inspection (Inspection Date) and may not reflect the current state. Timber Pests, particularly Termites, may have gained entry to the property since the Inspection Date. Termites can, in a relatively short period, cause significant damage to both structural and non-structural timbers within and around the buildings of the Property.

Termites (white ants) may be difficult to detect and much of the damage caused may not be readily visible. If damage exists, then it may cost thousands of dollars to repair.

It is, therefore, very strongly recommended that you urgently arrange for another Inspection and Report in accordance with AS4349.3 to be carried out prior to exchange, or prior to the expiration of any 'Cooling off Period', and prior to settlement.

(b) If the Report indicated the presence of Termites, termite damage or recommends any treatments or other Inspections and Reports, you should obtain copies of the treatment proposal, any certificates of treatments carried out, details of all repairs including copies of quotations, invoices, and any other Reports.

It is strongly recommended that you arrange for an Inspection and Report in accordance with AS 4349.3 to verify that the treatment has been successful and carried out in accordance with AS 3660.2 and a further building Inspection in accordance with AS 4349.1.

(c) If you fail to procure a further Inspection and report as recommended in (a) and (b), or fail to obtain copies of the treatment proposal, certificates of treatment carried out, details of all repairs including copies of quotations, invoices and any other reports as recommended in (b) above, then it will be deemed that you have decided not to have a further Inspection and report carried out, or to obtain copies of certificates of treatments carried out, details of all repairs including copies of quotations, invoices and any other reports.

It will be deemed that you have relied upon your own enquiries and the report, knowing the possible consequences and that the condition of the property, as stated in the report, may have changed.

(d) The person carrying out the Inspection and the company, partnership or sole trader that employs that person will have no liability to you for any damage or loss you may suffer as a result of your entering the contract to purchase the property or in connection with completing the purchase of the property as a result of your failure to heed the advice given in (a) and (b) and the warning contained in (c) above, and may use such failure in defense of any claim that you may later make against any of them.

ACT PROPERTY INSPECTIONS

Compliance Report

COMPLIANCE REPORT

This is a Compliance Report regarding any unapproved structures or alterations. ACT Property Inspections have accessed the attached Building File from ACT Planning and Land Authority (ACTPLA) and hold no responsibility for any inaccuracies in the Building File supplied by ACTPLA. The Compliance report is based solely upon the information available from the Building File which does not contain information regarding Plumbing or Electrical work that has taken place since the original construction. Information regarding the Plumbing and Electrical is available upon application from ACTPLA. Since we are not Plumbers or Electricians, we are unable to comment on those works. If structures have been noted as requiring approval, a Certifier should be engaged to assess if the structure will comply with the relevant ACT legislation. Owners must be aware that unapproved structures may not comply and may require significant repair, design change or possible removal.

Property Address: 10 Elliott St, Campbell ACT 2612
Block & Section: Block 38 Section 32 CAMPBELL
Inspection Date: Friday, April 10th 2026

APPROVAL STATUS

Description	Plan number	Certificate of occupancy date	Approval status
Demolition of Residence	044117/A	14/04/2026	Approved.
New Residence	054531/A/B	29/11/2007	Approved.
Fireplace	B2012414/A	19/01/2017	Approved.
Additions & Alterations	B20142365/A/B	19/10/2015	Approved.
Creation of opening/doorway into void area (lower level)	-	-	This work is unapproved as structural changes have occurred. Building approval is required.
Vergola (to rear)	-	-	This structure is unapproved as the roof is higher than 3.0m. Building approval is required.
External structures: - Rotunda (to the rear left side) - Chicken enclosure	-	-	These structures are built inside a service easement. Should access be required to the easement by the service provider, these structures may need to be removed at the owner's expense.
Pergola over external entrance to void area	-	-	This structure is exempt from approval. No action is required

ACTPLA COMMENTS

- No Certificate of Occupancy for 044117/A – registration acknowledgement only

SURVEY REPORT

Survey Report completed by	Date Survey report was completed	Comments
Scott D. McNiven & Associates	Thursday, 27 October 2005	There are no apparent encroachments upon this land or by this property on adjoining lands or street

ACT PROPERTY INSPECTIONS

Conveyancing File

CONVEYANCING BUILDING FILE INDEX

SUBURB: CAMPBELL **SECTION:** 32 **BLOCK:** 38 **UNIT:** N/A **EX GOV:** NO

COU ISSUED Y/N	PLAN NUMBER	FOLIO NO.	DESCRIPTION OF WORK	AMEND	DETAILS	PERMIT NUMBER	COU PLAN NO. & DATE
Y	044117/A	-	DEMOLITION OF RESIDENCE			044117/A	
		-					044117/A 14/04/2026
Y	054531/A	-	NEW RESIDENCE			054531/A	
Y	054531/B	-		Y			
		-					054531/A/B 29/11/2007
Y	B2012414/A	-	FIREPLACE			B2012414/A	
		-					B2012414/A 19/01/2017
Y	B20142365/A	-	ADDITIONS & ALTERATIONS			B20142365/A	
Y	B20142365/B	-		Y			
		-					B20142365/A/B 19/10/2015

For any incomplete approvals please email acbuildingconveyance@act.gov.au for further information on how to complete.

Drainage Plan Number: 3415

Survey: Y (01)

Comments:

ACT Government | Access Canberra

ACCESS CANBERRA TO COMPLETE

CONVEYANCING PART 2

No information is provided in respect of electrical, drainage or sewer matters and or to the location of overhead power lines or underground cables in relation to the building.

		Yes	No
1.	**(a)** Is this a government or ex government house?	☐	☒
	(b) If yes, is there a building file with approvals on it?	☐	☐
2.	Is there any record of incomplete building work on the building file? **If yes** - file copies attached	☒	☐
3.	Are there any records on the building file of current (within 5 years) housing Indemnity insurance policies for building work? **If yes** - file copies attached	☐	☒
4.	Are there any records on the building file showing building applications still being processed? (Current within 3 years) **If yes** - file copies attached	☐	☒
5.	Are there any records on the building file in relation to loose-fill asbestos insulation?	☐	☒

If available, copies of the following documents are provided:

	Yes	No
• Certificate/s of Occupancy and Use	☒	☐
• Survey Certificates	☒	☐
• Unit Plan/Unit Entitlements (if property is unit titled)	☐	☒
• Approved Building Plans	☒	☐
• Ex- government Building Plans*	☐	☒

If requested:

	Yes	No
• Drainage Plan(s)	☒	☐

ASBESTOS

The ACT Government is not able to guarantee the accuracy of the information in this report.
You should make your own enquiries and obtain reports (from a licensed Asbestos Assessor) in relation to the presence of loose fill asbestos insulation (and other forms of asbestos) on the premises. For more information go to the Asbestos Awareness Website – www.asbestos.act.gov.au

Please note: Development Approval plans will not be included in this report (We do not receive Development Approval Plans unless they are part of a Building Approval in which case they become Building Approval Plans), if development approval was granted you can request copies of the Development Approval plans from ACEPDcustomerservices@act.gov.au**.**

Please Note: Building approvals that have been generated via eDevelopment will be issued with a project number prefixed by the letter B. Initial building approval documentation will be identified with project number B20XXXXX only but will be referenced as B20XXXX/A on the Certificate of Occupancy and Use. Any amendments to the original approval will be issued with the project number and an alphanumeric digit. The first amendment will be identified as B20XXXX/B, the second amendment B20XXXX/C etc. Not all eDevelopment plans will be stamped with the plan number.

***Ex Government plans**: Plans are typical and not specific to each residence. There may be slight changes to the layout or window locations that were not required to be approved.

Search officer comments (if any?)

Search officer initials: Tony | Cost of application: $ 144.79 | Date completed: 07/04/2026

SCOTT D McNIVEN & ASSOCIATES Pty Ltd

CONSULTING LAND & ENGINEERING SURVEYORS ACN 052 870 747

OUR REF: 04433

Tanya Ballat
96 Hopetoun Cct.
Yarralumla, ACT 2600

Dear Madam,

As instructed by you we have surveyed for identification purposes, the land being Block 38, Section 32, Campbell with a frontage to Elliot Street, Campbell in the District of Canberra Central of the Australian Capital Territory.

- The subject land is shown by red edging on the diagram.
- Standing upon and wholly within the boundaries of the subject land is a brick residence.
- The relationship of the brick residence with respect to the boundaries is as indicated on the diagram.
- Proposed easements affect the subject land.
- This survey report is with respect to the brick residence only.
- This survey report is for the purpose of obtaining a Building Certificate only and should not be used to set out future additions.



Yours Faithfully

Scott D. McNiven
Registered Surveyor
27 October, 2005

8 SHOUT PLACE, PEARCE ACT 2607 T (02) 6290 2369 F (02) 62868148 survey@sdma.com.au

Access Canberra Building Services
GPO Box 158, Canberra ACT 2601

Certificate of Completion of Demolition

Certificate No. **044117N1C1**

This Certificate is issued in accordance with Section 71 (2) of the Building Act.

The demolition of building work listed on this certificate has been completed in accordance with the prescribed requirements.

Builder	*Suburb*	*Section*	*Block*
GINO ROSO	CAMPBELL	32	38

Notice of Intention to Start Work Number	Plans
044117N1	044117/A

Building Work

Nature of Work	Project Item Description	Unit	Other Description	Class of Occupancy	Type of Construction
DEMOLITION	RESIDENCE			1a (i)	NA

Comments

Important note:

The issue, under this Part, of a certificate in respect of a building or portion of a building does not affect the liability of a person to comply with the provisions of a law of the Territory (including this Act) relating to the building or portion of the building.

.....

SIAN OSULLIVAN
Delegate of the Registrar

Date 14/04/2026

ALL DIMENSIONS IN MILLIMETERS. DO NOT SCALE
DRAWING PRACTICE TO AS1100
BUILDER TO CONFIRM ALL DIMENSIONS ON SITE
PRIOR TO COMMENCEMENT OF WORK
ALL WORK TO BCA AND RELEVANT SAA CODES



Plan No: 044117B
06 DEC 2004
RECEIVED
ACT Planning & Land Authority

Plan No: 05453/A
18 NOV 2005
RECEIVED
ACT Planning & Land Authority

SUBJECT TO CONDITIONS SET OUT IN THE NOTICE OF DECISION
Land (Planning and Environment Act 1991)
APPROVAL GRANTED
Pursuant to Section 230 or 245
06 OCT 2004
Delegate of the Authority

BUILDING APPROVAL
Approved under s.28 of the Building Act 2004.
JOHN BATES
Name
B25 25/10/04
Licence Number Date
Signature

DEMOLITION NOTES

1 ALL DEMOLITION WORK TO BE CARRIED OUT IN ACCORDANCE WITH ACT WORKCOVER REQUIREMENTS USING NON EXPLOSIVE METHODS
2 ALL DEMOLITION MATERIALS TO BE SALVAGED FOR SALE AND/OR RECYCLING UNLESS STATED OTHERWISE
3 ANY ASBESTOS MATERIALS TO BE REMOVED FROM SITE IN ACCORDANCE WITH ACT WORKCOVER REGULATIONS AND DISPOSED OF AT AN AUTHORISED TIP

VERGE MANAGEMENT

1 NATURE STRIP TO BE FENCED OFF AND PROTECTED
2 ALL MATERIALS TO BE STORED ON SITE
MATERIALS SHOULD NOT BE STORED ON NATURE STRIP
3 PROVIDE TEMPORARY WET WEATHER VEHICULAR ACCESS TO SITE

TREE PROTECTION NOTES

1 NO SITE SHEDS, BUILDINGS OR VEHICULAR PARKING WITHIN THE ROOT ZONE (DRIP ZONE + 2m)
2 TEMPORARY PROTECTIVE ENCLOSURE IS REQUIRED AROUND THE ROOT ZONE OF THE TREE GROUPS AND SHOULD CONSIST OF STAR PICKETS WITH ORANGE PLASTIC WOVEN FENCING MATERIALS
3 WHERE PLANT OPERATION IN CLOSE PROXIMITY TO TREES IS UNAVOIDABLE PROTECTIVE LASHING WITH TIMBER BATTENS SHOULD BE PLACED AROUND TRUNK OF TREES
4 THERE SHOULD BE NO EXCAVATION OF SERVICES OR FOOTINGS WITHIN 3m OF THE TREE TRUNK
5 EXCAVATION REQUIRED WITHIN THE DROP ZONE OF TREES MUST BE DONE BY HAND

DEMOLITION PLAN

Amendments

No	Description - 28.09.2004
A1	W23 & W25 made obscure
A2	Section 2 added

PROJECT

PROPOSED RESIDENCE

CLIENT NAME

M & T BALLAT

Date:	20.07.2004
Drawn By:	CAD
Scale:	1:200
Sheet:	9 of 9
Dwg No:	WE140A9A
CAD Ref:	WE140MA

DEMOLITION PLAN

BLOCK	SECTION
38	32

CAMPBELL

ACT Planning and Land Authority

ACT Building, Electrical and Plumbing Control

GPO Box 1908, Canberra ACT 2601

Certificate of Occupancy and Use

Certificate No. **054531N1C1**

This Certificate is issued in accordance with Section 69 (2) of the Building Act.

The building work listed on this certificate has been completed substantially in accordance with the prescribed requirements and is considered fit for occupation and use.

Builder	Suburb	Section	Block
MICHAEL BALLAT	CAMPBELL	32	38
Notice of Intention to Start Work Number	**Plans**		
054531N1	054531/A /B		

Building Work

Nature of Work	Project Item Description	Unit	Other Description	Class of Occupancy	Type of Construction
NEW STANDARD	RESIDENCE			1a (i)	NA

Comments

Important note:

1. Residential building statutory warranties and residential insurance apply in relation to building work.

2. The issue, under this Part, of a certificate in respect of a building or portion of a building does not affect the liability of a person to comply with the provisions of a law of the Territory (including this Act) relating to the building or portion of the building.

nmarquette

NATALIE MARQUETTE
Delegate of the Registrar

29 / 11 / 2007

Date

ALL DIMENSIONS IN MILLIMETERS. DO NOT SCALE
DRAWING PRACTICE TO AS1100
BUILDER TO CONFIRM ALL DIMENSIONS ON SITE
PRIOR TO COMMENCEMENT OF WORK
ALL WORK TO BCA AND RELEVANT SAA CODES

BUILDING APPROVAL
Approved under s.28 of the Building Act 2004.
JOHN BATES
Name
B25 25/10/04
Licence Number Date
Signature

Plan No: 044117B
06 DEC 2004
RECEIVED
ACT Planning & Land Authority

Application No. 200401215A

Plan No: 054531/A
18 NOV 2005
RECEIVED
ACT Planning & Land Authority

NOTE

GROUND LEVELS SHOWN ARE TRUE AND ACCURATE AND MEASURED ON SITE

RECOMMENDATIONS

IT IS RECOMMENDED THAT MULCHING AND IRRIGATION WITHIN THE TREE PROTECTION ZONE IS UNDERTAKEN DURING THE PERIOD OF DEVELOPMENT TO SUSTAIN THE TREE, PARTICULARLY OVER SUMMER.

TREE PROTECTION NOTES

THE TREE SHALL BE FENCED OFF BY AN 1800 HIGH CHAIN WIRE FENCE, NO CLOSER THAN A MINIUMUM DISTANCE OF 2600 FROM TRUNK.

THE FENCE SHALL BE ERECTED PRIOR TO THE COMMENCEMENT OF ANY CONSTRUCTION WORKS ON ANY PART/STAGE OF THAT DEVELOPMENT AND IS TO REMAIN IN PLACE UNTIL ALL CONSTRUCTION WORKS ARE COMPLETED. NO WORK IS TO OCCUR WITHIN THE FENCED OFF AREA AND NO SITE SHEDS, BUILDING MATERIALS, EQUIPMENT, FILL OR VEHICLES ARE TO BE PLACED WITHIN THE FENCED OFF AREA.

THE FENCE WILL BE REMOVED FOLLOWING COMPLETION OF THE CONSTRUCTION OF THE RETAINING WALL TO ALLOW FOR MINOR LANDSCAPE WORKS TO PROCEED. THESE DO NOT INCLUDE EXCAVATION WITHIN THE TREE PROTECTION ZONE.

NO EXCAVATION (E.G. FOR SERVICES, FOOTINGS AND IRRIGATION) OR MODIFICATION OF EXISTING GROUND LEVELS WITHIN THE TREE PROTECTION ZONE OR WITHIN 2.6m OF THE CLOSEST POINT OF THE TRUNK AS SPECIFIED ON DWG: WE140A1

IF ROOT PRUNING/REMOVAL IS REQUIRED, ROOTS SHALL BE CUT CLEANLY (NOT PULLED OR RIPPED)

EXPOSED ROOTS SHALL BE KEPT DAMP AND BACKFILLED AS SOON AS POSSIBLE

CONSTRUCTION OF A LOW IMPACT FOOTING AS INDICATED ON DWG: WE140A1 WITH A SUSPENDED FLOOR WITHIN THE TREE PROTECTION ZONE. A LOW IMPACT FOOTING DOES NOT CUT INTO THE ROOT SYSTEM, EXCEPT FOR ISOLATED PIERS.

CONSTRUCTION OF THE DRIVEWAY/PAVING WITHIN THE TREE PROTECTION ZONE SHALL NOT RESULT IN ROOTS GREATER THAN 20mm IN DIA BEING SEVERED AND INVOLVE SIDE CUTS THAT DO NOT EXCEED 100mm.





TYPICAL DETAIL

LOW IMPACT FOOTING

LOCATION ZONE FOR STORMWATER AND SEWERAGE TRENCHING

LEGEND

TREE TO BE REMOVED

AREA

LOWER FLOOR	- 60.9m²
GROUND FLOOR	- 157.8m²
DECKS	- 35.7m²
PATIO	- 16.0m²
UPPER FLOOR	- 79.7m²
BALCONY	- 16.0m²
GFA	- 330.4m²
PLOT RATIO	- 46.5%
BLOCK AREA	- 711.0m²

SITE PLAN

Amendments

No	Description - 28.09.2004
A1	W23 & W25 made obscure
A2	Section 2 added

SUBJECT TO THE CONDITIONS SET OUT IN THE NOTICE OF DECISION
Land (Planning and Environment Act 1991)
APPROVAL GRANTED
Pursuant to Section 230 or 245
06 OCT 2004
Delegate of the Authority

PROJECT

PROPOSED RESIDENCE

CLIENT NAME

M & T BALLAT

Date:	24.05.2004
Drawn By:	CAD
Scale:	1:200
Sheet:	1 of 9
Dwg No:	WE140A1A
CAD Ref:	WE140MA

SITE PLAN

BLOCK	SECTION
38	32

CAMPBELL



NOTE

CONCRETE SLAB TO LOWER FLOOR

LOWER FLOOR PLAN

Plan No: 05453/A
18 NOV 2005
RECEIVED
ACT Planning & Land Authority

Plan No: 04411/B
06 DEC 2004
RECEIVED
ACT Planning & Land Authority

BUILDING APPROVAL
Approved under s.28 of the Building Act 2004.
JOHN BATES
Name
B25
Licence Number
25/10/04
Date
Signature

SUBJECT TO THE CONDITIONS SET OUT IN THE NOTICE OF DECISION
Land (Planning and Environment Act 199)
APPROVAL GRANTED
Pursuant to Section 230 or 245
06 OCT 2004
Delegate of the Authority

ALL DIMENSIONS IN MILLMETERS. DO NOT SCALE
DRAWING PRACTICE TO AS1100
BUILDER TO CONFIRM DIMENSIONS ON SITE PRIOR TO COMMENCEMENT OF WORK
ALL WORK TO BCA AND RELEVANT SAA CODES

Amendments		PROJECT	CLIENT NAME	Date: 20.07.2004	Scale: 1:100	
No	Description - 28.09.2004	PROPOSED RESIDENCE	M & T BALLAT	Drawn By: CAD	BLOCK	SECTION
A1	W23 & W25 made obscure		DWG NAME	Sheet: 2 of 9	38	32
A2	Section 2 added		LOWER FLOOR PLAN	Dwg No: WE140A2A	CAMPBELL	
				CAD Ref: WE140MA		



GROUND FLOOR PLAN

ALL DIMENSIONS IN MILLMETERS. DO NOT SCALE
DRAWING PRACTICE TO AS1100
BUILDER TO CONFIRM DIMENSIONS ON SITE PRIOR TO COMMENCEMENT OF WORK
ALL WORK TO BCA AND RELEVANT SAA CODES

NOTE
BONDEK SLAB TO GROUND FLOOR

Plan No: 044718
06 DEC 2004
ACT Planning & Land Authority
RECEIVED

BUILDING APPROVAL
Approved under s.28 of the Building Act 2004.
JOHN BATES
Name
B25
Licence Number
25/10/04
Date
Signature

Plan No: 054531 A
18 NOV 2005
SUBJECT TO THE CONDITIONS SET OUT IN DECISION
RECEIVED
ACT Planning & Land Authority
Land (Planning and Environment) Act 1991
APPROVAL GRANTED
Pursuant to Section 230 of the
06 OCT 2004
Delegate of the Authority

Amendments		PROJECT	CLIENT NAME	Date: 20.07.2004	Scale: 1:100	
No	Description - 28.09.2004	PROPOSED RESIDENCE	M & T BALLAT	Drawn By: CAD	BLOCK	SECTION
A1	W23 & W25 made obscure		DWG NAME	Sheet: 3 of 9	38	32
A2	Section 2 added		GROUND FLOOR PLAN	Dwg No: WE140A3A	CAMPBELL	
				CAD Ref: WE140MA		



UPPER FLOOR PLAN

NOTE

TIMBER FLOOR SYSTEM
TO UPPER FLOOR

BUILDING APPROVAL
Approved under s.28 of the Building Act 2004.
JOHN BATES
Name
B25
Licence Number
25/10/04
Date
Signature

RECEIVED
ACT Planning & Land Authority
06 DEC 2004

Plan No: 05453/A
18 NOV 2005
RECEIVED
ACT Planning & Land Authority
SUBJECT TO CONDITIONS SET OUT IN THE NOTICE OF DECISION
APPROVAL GRANTED
Pursuant to Section 230 or 245 (1991)
06 OCT 2004
Delegate of the Authority

ALL DIMENSIONS IN MILLMETERS. DO NOT SCALE
DRAWING PRACTICE TO AS1100
BUILDER TO CONFIRM DIMENSIONS ON SITE PRIOR TO COMMENCEMENT OF WORK
ALL WORK TO BCA AND RELEVANT SAA CODES

Amendments	PROJECT	CLIENT NAME	Date: 20.07.2004	Scale: 1:100	
No Description - 28.09.2004	PROPOSED RESIDENCE	M & T BALLAT	Drawn By: CAD	BLOCK	SECTION
A1 W23 & W25 made obscure		DWG NAME	Sheet: 4 of 9	38	32
A2 Section 2 added		UPPER FLOOR PLAN	Dwg No: WE140A4A	CAMPBELL	
			CAD Ref: WE140MA		

ALL DIMENSIONS IN MILLIMETERS. DO NOT SCALE
DRAWING PRACTICE TO AS1100
BUILDER TO CONFIRM ALL DIMENSIONS ON SITE
PRIOR TO COMMENCEMENT OF WORK
ALL WORK TO BCA AND RELEVANT SAA CODES



ELEVATION A



ELEVATION B

Plan No: 044417B
06 DEC 2004
RECEIVED
ACT Planning & Land Authority

Plan No: 054531/A
18 NOV 2005
RECEIVED
ACT Planning & Land Authority

SUBJECT TO THE CONDITIONS SET OUT IN THE NOTICE OF DECISION
Land (Planning and Environment Act 1991)
APPROVAL GRANTED
Pursuant to Section 230 or 245
06 OCT 2004
Delegate of the Authority

BUILDING APPROVAL
Approved under s.28 of the Building Act 2004.
JOHN BATES
Name
B25 25.10.04
Licence Number Date
Signature

Amendments

No	Description - 28.09.2004
A1	W23 & W25 made obscure
A2	Section 2 added

PROJECT

PROPOSED RESIDENCE

CLIENT NAME

M & T BALLAT

Date:	20.07.2004
Drawn By:	CAD
Scale:	1:100
Sheet:	5 of 9
Dwg No:	WE140A5A
CAD Ref:	WE140MA

ELEVATIONS

BLOCK	SECTION
38	32

CAMPBELL

ALL DIMENSIONS IN MILLIMETERS. DO NOT SCALE
DRAWING PRACTICE TO AS1100
BUILDER TO CONFIRM ALL DIMENSIONS ON SITE
PRIOR TO COMMENCEMENT OF WORK
ALL WORK TO BCA AND RELEVANT SAA CODES



ELEVATION C



ELEVATION D

Plan No: 044171B
06 DEC 2004
RECEIVED
ACT Planning & Land Authority

BUILDING APPROVAL
Approved under s.28 of the Building Act 2004.
JOHN BATES
Name
B25 25/10/04
Licence Number Date
Signature

Plan No: 054581/A
18 NOV 2005
RECEIVED
ACT Planning & Land Authority

SUBJECT TO THE CONDITIONS SET OUT IN THE NOTICE OF DECISION
Land (Planning and Environment Act 1991)
APPROVAL GRANTED
Pursuant to Section 230 or 245
06 OCT 2004
Delegate of the Authority

Amendments

No	Description - 28.09.2004
A1	W23 & W25 made obscure
A2	Section 2 added

PROJECT

PROPOSED RESIDENCE

CLIENT NAME

M & T BALLAT

Date:	20.07.2004
Drawn By:	CAD
Scale:	1:100
Sheet:	6 of 9
Dwg No:	WE140A6A
CAD Ref:	WE140MA

ELEVATIONS

BLOCK	SECTION
38	32

CAMPBELL

ALL DIMENSIONS IN MILLIMETERS. DO NOT SCALE
DRAWING PRACTICE TO AS1100
BUILDER TO CONFIRM ALL DIMENSIONS ON SITE
PRIOR TO COMMENCEMENT OF WORK
ALL WORK TO BCA AND RELEVANT SAA CODES



SECTION 1



SECTION 2

BUILDING APPROVAL
Approved under s.28 of the Building Act 2004.
JOHN BATES
Name
B25 25/10/04
Licence Number Date
Signature

SUBJECT TO THE CONDITIONS SET OUT IN THE NOTICE OF DECISION
Land (Planning and Environment Act 1991)
APPROVAL GRANTED
Pursuant to Section 230 or 245
06 OCT 2004
Delegate of the Authority

Plan No: 044117/B
06 DEC 2004
RECEIVED
ACT Planning & Land Authority

Amendments

No	Description - 28.09.2004
A1	W23 & W25 made obscure
A2	Section 2 added

Plan No: 054531/A
18 NOV 2005
RECEIVED
ACT Planning & Land Authority

PROJECT

PROPOSED RESIDENCE

CLIENT NAME

M & T BALLAT

Date:	20.07.2004
Drawn By:	CAD
Scale:	1:100
Sheet:	7 of 9
Dwg No:	WE140A7A
CAD Ref:	WE140MA

SECTIONS

BLOCK	SECTION
38	32

CAMPBELL

ALL DIMENSIONS IN MILLIMETERS. DO NOT SCALE
DRAWING PRACTICE TO AS1100
BUILDER TO CONFIRM ALL DIMENSIONS ON SITE PRIOR TO COMMENCEMENT OF WORK
ALL WORK TO BCA AND RELEVANT SAA CODES



10 ELLIOTT STREET

VERGE MANAGEMENT PLAN

Plan No. 044117/B
06 DEC 2004
RECEIVED
ACT Planning & Land Authority

BUILDING APPROVAL
Approved under s.28 of the Building Act 2004.
JOHN BATES
Name
B25 (Licence Number) 25/10/04 (Date)
Signature

PROTECTION OF EXISTING TREES

ALL VERGE TREES ARE TO BE RETAINED AND KEPT UNDAMAGED
MAINTAIN PROTECTIVE ENCLOSURE CONSISTING OF CHAIN MESH PANELS AS COMPLETE ENCLOSURE AROUND EXISTING TREES

VERGE MANAGEMENT

NO STOREAGE OF CONSTRUCTION MATERIALS EQUIPMENT OR CARPARKING PERMITTED ON THE VERGE
EXISTING DRIVEWAY ACCESS POINT TO BE USED FOR ALL SITE ACCESS
COORDINATE ALL SERVICE APPROVALS, PERMISSION MUST BE SOUGHT FROM CANBERRA URBAN PARKS BEFORE EXCAVATING WITHIN VERGE

VERGE RESTORATION

PROTECT EXISTING GRASS COVER, AT COMPLETION OF CONSTRUCTION VERGE SHOULD STILL HAVE ESTABLISHED GRASS COVER
SHOULD RESTORATION BE REQUIRED, LIGHTLY CULTIVATE AND SOW WITH SIMILAR SEED SPECIES

NOTE

THE DEVELOPER IS RESPONSIBLE FOR THE REINSTATEMENT OF ALL DAMAGE INCURRED TO LAND, VEGETATION, SERVICES, PATHS AND ROADS AS A RESULT OF THIS CONSTRUCTION WORK

1800 HIGH CONTINUOUS CHAIN MESH FENCE PANELS SUPPORTED BY 2400 HIGH STAS STEEL POSTS
FENCE TO BE ERECTED AT COMMENCEMENT OF WORK AND REMOVED AT COMPLETION
FENCE TO REMAIN CONTINUOUS THROUGHOUT THE PROJECT EXCEPT WHERE SERVICES INSTALLATION OCCURS SEEK APPROVAL FROM CANBERRA URBAN PARKS FOR TRENCH LOCATIONS

SUBJECT TO THE CONDITIONS SET OUT IN THE NOTICE OF DECISION
Land Planning and Environment Act 1991)
APPROVAL GRANTED
Pursuant to Section 230 or 245
06 OCT 2004
Delegate of the Authority

N

Amendments

No	Description - 28.09.2004
A1	W23 & W25 made obscure
A2	Section 2 added

Plan No: 054531/A
18 NOV 2005
RECEIVED
ACT Planning & Land Authority

PROJECT

PROPOSED RESIDENCE

CLIENT NAME

M & T BALLAT

Date:	20.07.2004
Drawn By:	CAD
Scale:	1:200
Sheet:	8 of 9
Dwg No:	WE140A8A
CAD Ref:	WE140MA

VERGE MANAGEMENT PLAN

BLOCK	SECTION
38	32

CAMPBELL

DO NOT SCALE



FOUNDATION PLAN

SLAB THICKNESS 100 UNO
SLAB REINFORCEMENT SL82 TOP UNO
PROVIDE VAPOUR BARRIER UNDER SLAB
REFER TO ARCHITECTS DRAWINGS FOR SLAB RL'S
ALL FOOTINGS 300 WIDE x 500 DEEP UNO

SHRINKAGE
S1 Where brittle floor covering are to be used over an area greater than 16m², one of the following measures to control the effect of shrinkage shall be used.
(i) In the affected slab panel/s, shrinkage reinforcement shall be increased to SL92 or equivalent, or an additional sheet of mesh shall be placed over the affected area
(ii) The bedding system for brittle coverings shall be selected on the basis of the expected slab movement and the characteristics of the floor covering
(iii) The placement of floor coverings shall be delayed
NOTE: A minimum period of three months drying time is usually required before placement of brittle floor coverings
S2 At re-entrant corners, two strips of 3-L8TM, or one strip of 3-L11TM or 3N12 bars, shall be placed diagonally across a potential crack. All bars shall be minimum 2m in length

Plan No: 044117B
06 DEC 2004
RECEIVED
ACT Planning & Land Authority



SECTION 1 -

Plan No: 054531/A
18 NOV 2005
RECEIVED
ACT Planning & Land Authority

0 50 100
DRAWING PRACTICE TO AS 1100 ALL DIMENSIONS IN MILLIMETRES

CADD REF: WE140ME | CERTIFIED

No	AMENDMENTS	Date	App'd

PROPOSED RESIDENCE
FOR MR & MRS BALLAT
BLOCK 38 SECTION 32
CAMPBELL ACT

morgan.engineers.act
PO BOX 3560 MANUKA ACT 2603
Phone 02 6239 5300 Fax 02 6239 5201

FOUNDATION PLAN
CLASS S SITE

DESIGNED JMHM	DRAWN MG	DATE OCT 04	No in SET 3	DRAWING No WE140-S01	A3

DO NOT SCALE



FOOTING SYSTEM

ARTICULATED MASONRY VENEER
SLAB FABRIC SL72 TOP FOR SLAB LENGTH <18m
SLAB FABRIC SL82 TOP FOR SLAB LENGTH ≥18m & <25m
SLAB FABRIC SL92 TOP FOR SLAB LENGTH ≥25m & <30m

Plan No: 044117B
06 DEC 2004
RECEIVED
ACT Planning & Land Authority

ALTERNATE DETAIL
DEEP EDGE REBATE



TYPICAL DETAIL
STEP IN SLAB



TYPICAL DETAIL
STEP IN STRIP FOOTING



TYPICAL DETAIL
STEP IN SLAB



TYPICAL DETAIL
RECESS IN SLAB

GENERAL NOTES
G1 These drawings shall be read in conjunction with all architectural and other consultants documents and other written instructions issued during the course of construction and all discrepancies shall be referred to the engineer for decision prior to work proceeding
G2 Dimensions shall not be obtained by scaling

FOUNDATIONS
F1 All footing shall be taken down to undisturbed ground below the root zone. Footing have been designed for an allowable bearing pressure of 100 kPa. The builder shall obtain approval of the foundation material
F2 The site classification and or footing design assumes that the recommendations for design requirements, site maintenance and performance expectations as set out in AS2870 are followed and acceptable
F3 Slab filling shall consist of controlled or rolled material as set out in AS2870 - 6.4.2
F4 Walls and columns shall be placed directly over footings unless noted otherwise
F5 Services trenches or the like near the edge of footing should not extend below a line drawn at 30° to horizontal for sand (45° for clay) from the footing edge
F7 Any permanent excavation around the building and deeper than 600 shall be adequately retained or battered Details to be provided if required

CONCRETE
C1 All workmanship and materials in accordance with AS2870 unless noted otherwise
C2 Concrete quality - Footing/slab f'c 20 MPa
The workability may be adjusted under controlled conditions to suit site and climate conditions
C3 Minimum clear cover to reinforcement uno shall be
Footings 40
Slab 30 Bot with membrane 20 internal surface
C4 Construction joints to be used only where shown or specifically approved by the engineer
C5 Reinforcement is represented diagramatically and not shown in true projection. Splices in reinforcement shall only be made in the position shown or as otherwise approved by the engineer
C6 Trench mesh reinforcement can be replaced with equivalent reinforcing bars

MASONRY
M1 All workmanship and materials in accordance with AS 3700
M2 Mortar shall comply with min classification requirement given in AS3700 - Table 5.1
M3 Masonry supporting slabs and/or beams shall have a mortar layer on top troweled smooth with 2 layers of dpc separating the components
M4 No cutting chasing or raking of joints in excess of 5 unless authorised by the engineer
M5 Masonry walls shall be articulated and non masonry infills should be used over all openings

SUPERVISION
S1 Verification of site conditions & compliance of work with the BCA & relevant standards should only be done by a suitably qualified person prior to work proceeding
It is recommeneded that the ENGINEER be engaged to inspect progressively the construction of the structural elements of the work
S2 The owner's attention is directed to the CSIRO Publict'n BTF 18 'Foundation maintenance & footing performance'

Plan No: 054531/A
18 NOV 2005
RECEIVED
ACT Planning & Land Authority

0 50 100
DRAWING PRACTICE TO AS 1100 ALL DIMENSIONS IN MILLIMETRES

CADD REF: 1fots02G—sheet | CERTIFIED

No	AMENDMENTS	Date	App'd

PROPOSED ADDITIONS FOR S & J SAMPSON BLOCK 1 SECTION 1 SPENCE ACT

DESIGNED SAA	DRAWN CADD	DATE OCT 04	No in SET 2	DRAWING No WDP37-S02	A3

FOUNDATION LEVEL FOOTING SYSTEM CLASS S SITE

DO NOT SCALE



GROUND FLOOR SLAB PLAN

Plan No: 054531A
18 NOV 2005
RECEIVED
ACT Planning & Land Authority

GENERAL NOTES
G1 These notes shall be read in conjunction with all architectural and other consultants drawings specifications and with other written instructions as may be issued during the course of construction and all discrepancies shall be referred to the engineer for decision before proceeding with the work
G2 Dimensions shall not be obtained by scaling
G3 Setting out dimensions shown on the drawing shall be verified by the builder
G4 During construction the structure shall be maintained in a stable condition and no part shall be overstressed

STEELWORK
S1 All workmanship and materials shall be in accordance with AS4100 and relevant associated standards unless noted otherwise
S2 The builder shall provide holes cleats and fixings for all steel framing including that shown on the architectural drawings
S3 Unless noted otherwise use
(i) 10 gusset fin or end plate
(ii) 4.6/S Commercial grade bolts
(iii) 6 continuous fillet welds for full periphery of connecting members made with E48XX or E41XX mild steel electrodes
S4 Surface treatment unless noted otherwise
Exposed to weather Class 2.5 clean with 75 micron inorganic zinc primer
All others Class 2 with 70 microns inorganic zinc primer
all surface treatments to be compatible with Architectural finishes
S5 Provide temporary bracing as required to maintain stability at all times
S6 Bolts to be installed with one hardened washer under the turned part
S7 Cold formed sections to conform with AS1538 AS1163 and relevant associated standards
S8 Unless noted otherwise all rolled steel sections to be grade 250 and steel hollow sections to be to be grade 350
S9 All steelwork erection to be in accordance AISC code of practice for low rise construction

Plan No 044417B
06 DEC 04
RECEIVED
ACT Planning & Land Authority

CONCRETE-BONDEK
CB1 All workmanship and materials in accordance with AS3600 unless noted otherwise
CB2 Concrete quality
Slab topping - f'c 25 MPa
Exposure classification A1
Cover 20
CB3 Design loading
Live load 1.5kPa
Additional dead load 0.5kPa
CB4 Panels are to be securely fixed or held down to prevent displacement due to construction loading or uplift prior to concreteing. Fixing is not necessary provided concrete is placed immediately after panels are laid
CB5 Where panels are laid on brickwork the brickwork is to be straight and level. If required provide a layer of smooth hard mortar. Slip joints shall be provided at all masonry supports unless noted otherwise

SUPERVISION
S1 Verification of site conditions & compliance of work with the BCA & relevant standards should only be done by a suitably qualified person prior to work proceeding
It is recommended that the ENGINEER inspect progressively the construction of the structural elements of the work
S2 It is recommended that the ENGINEER inspect proressively the construction of the structural elements of the work



SECTION 2 / -



SECTION 3 / -

ALTERNATE DETAIL FOR FB2

MEMBER SHEDULE		
MARK	SIZE	REMARK
FB1	360UB44.7	
FB2	250PFC+100x100x6EA	
FB3-4	310UB40.4	
C1-C4	90x5SHS	

WHERE STRUCTURAL MEMBERS ARE SUPPORTED ON MASONRY CONSTRUCTION
PROVIDE MINIMUM 150 BEARING LENGTH
FOR OTHER SUPPORT PROVIDE MINIMUM 2/90x45 MGP10 STUDS
OR 75x75x4.0 SHS UNLESS NOTED OTHERWISE

0 50 100
DRAWING PRACTICE TO AS 1100 ALL DIMENSIONS IN MILLIMETRES

CADD REF: WE140ME | CERTIFIED

No	AMENDMENTS	Date	App'd

PROPOSED RESIDENCE
FOR MR & MRS BALLAT
BLOCK 38 SECTION 32
CAMPBELL ACT

morgan.engineers.act
PO BOX 3560 MANUKA ACT 2603
Phone 02 6239 5300 Fax 02 6239 5201

GROUND FLOOR SLAB PLAN

DESIGNED JMHM | DRAWN MG | DATE OCT 04 | No in SET 3 | DRAWING No WE140-S03 | A3

Class 1a(i), 10a & 10b
1 of 9
AMENDED

Land (Planning and Environment) Act 1991
APPROVAL AMENDED
Pursuant to Section 247 in respect of the nominated amendments only
08 OCT 2007
Delegate of the Authority

BUILDING APPROVAL
Approved under s.26 of the Building Act 2004. 32
JOHN BATES
Name
988
4388
Licence Number
19/10/07
Date
Signature

Plan No: 054531/B
22 OCT 2007
RECEIVED
ACT Planning & Land Authority

LL DIMENSIONS IN MILLIMETERS. DO NOT SCALE
RAWING PRACTICE TO AS1100
UILDER TO CONFIRM ALL DIMENSIONS ON SITE
RIOR TO COMMENCEMENT OF WORK
LL WORK TO BCA AND RELEVANT SAA CODES

OTE
ROUND LEVELS SHOWN ARE
RUE AND ACCURATE AND
EASURED ON SITE

RECOMMENDATIONS

IT IS RECOMMENDED THAT MULCHING AND IRRIGATION WITHIN THE TREE PROTECTION ZONE IS UNDERTAKEN DURING THE PERIOD OF DEVELOPMENT TO SUSTAIN THE TREE, PARTICULARLY OVER SUMMER.

TREE PROTECTION NOTES

THE TREE SHALL BE FENCED OFF BY AN 1800 HIGH CHAIN WIRE FENCE, NO CLOSER THAN A MINIUMUM DISTANCE OF 2600 FROM TRUNK.

THE FENCE SHALL BE ERECTED PRIOR TO THE COMMENCEMENT OF ANY CONSTRUCTION WORKS ON ANY PART/STAGE OF THAT DEVELOPMENT AND IS TO REMAIN IN PLACE UNTIL ALL CONSTRUCTION WORKS ARE COMPLETED. NO WORK IS TO OCCUR WITHIN THE FENCED OFF AREA AND NO SITE SHEDS, BUILDING MATERIALS, EQUIPMENT, FILL OR VEHICLES ARE TO BE PLACED WITHIN THE FENCED OFF AREA.

THE FENCE WILL BE REMOVED FOLLOWING COMPLETION OF THE CONSTRUCTION OF THE RETAINING WALL TO ALLOW FOR MINOR LANDSCAPE WORKS TO PROCEED. THESE DO NOT INCLUDE EXCAVATION WITHIN THE TREE PROTECTION ZONE.

NO EXCAVATION (E.G. FOR SERVICES, FOOTINGS AND IRRIGATION) OR MODIFICATION OF EXISTING GROUND LEVELS WITHIN THE TREE PROTECTION ZONE OR WITHIN 2.6m OF THE CLOSEST POINT OF THE TRUNK AS SPECIFIED ON DWG: WE140A1

IF ROOT PRUNING/REMOVAL IS REQUIRED, ROOTS SHALL BE CUT CLEANLY (NOT PULLED OR RIPPED)

EXPOSED ROOTS SHALL BE KEPT DAMP AND BACKFILLED AS SOON AS POSSIBLE

CONSTRUCTION OF A LOW IMPACT FOOTING AS INDICATED ON DWG: WE140A1 WITH A SUSPENDED FLOOR WITHIN THE TREE PROTECTION ZONE. A LOW IMPACT FOOTING DOES NOT CUT INTO THE ROOT SYSTEM, EXCEPT FOR ISOLATED PIERS.

CONSTRUCTION OF THE DRIVEWAY/PAVING WITHIN THE TREE PROTECTION ZONE SHALL NOT RESULT IN ROOTS GREATER THAN 20mm IN DIA BEING SEVERED AND INVOLVE SIDE CUTS THAT DO NOT EXCEED 100mm.





1.69 by survey

TYPICAL DETAIL

LOW IMPACT FOOTING

LOCATION ZONE FOR STORMWATER AND SEWERAGE TRENCHING

LEGEND

TREE TO BE REMOVED

AREA

LOWER FLOOR	- 60.9m²
GROUND FLOOR	- 157.8m²
DECKS	- 35.7m²
PATIO	- 16.0m²
UPPER FLOOR	- 79.7m²
BALCONY	- 16.0m²
GFA	- 330.4m²
PLOT RATIO	- 46.5%
BLOCK AREA	- 711.0m²

SITE PLAN

Amendments
No. Description - 28.09.2004
A1 W23 & W25 made obscure
A2 Section 2 added

AMENDMENTS OCTOBER 2007

PROJECT

PROPOSED RESIDENCE

CLIENT NAME

M & T BALLAT

Date:	24.05.2004
Drawn By:	CAD
Scale:	1:200
Sheet:	1 of 9
Dwg No:	WE140A1A
CAD Ref:	WE140MA

SITE PLAN

BLOCK	SECTION
38	32

CAMPBELL



LOWER FLOOR PLAN

NOTE

CONCRETE SLAB TO LOWER FLOOR

Land (Planning and Environment) Act 1991
APPROVAL AMENDED
Pursuant to Section 247 in respect of the nominated amendments only
08 OCT 2007
Delegate of the Authority

Plan No: 05453/B
22 OCT 2007
RECEIVED
ACT Planning & Land Authority

BUILDING APPROVAL
Approved under s.26 of the Building Act 2004.
JOHN BATES
Name
1988 4383
Licence Number
19/10/07
Date
Signature

2 of 9

ALL DIMENSIONS IN MILLMETERS. DO NOT SCALE
DRAWING PRACTICE TO AS1100
BUILDER TO CONFIRM DIMENSIONS ON SITE PRIOR TO COMMENCEMENT OF WORK
ALL WORK TO BCA AND RELEVANT SAA CODES

AMENDMENTS OCTOBER 2007

Amendments		PROJECT	CLIENT NAME	Date: 20.07.2004	Scale: 1:100	
No	Description - 28.09.2004	PROPOSED RESIDENCE	M & T BALLAT	Drawn By: CAD	BLOCK	SECTION
A1	W23 & W25 made obscure		DWG NAME	Sheet: 2 of 9	38	32
A2	Section 2 added		LOWER FLOOR PLAN	Dwg No: WE140A2A	CAMPBELL	
				CAD Ref: WE140MA		



GROUND FLOOR PLAN

3 of 9
AMDD

BUILDING APPROVAL
Approved under s.28 of the Building Act 2004. 32
JOHN BATES
Name
1988
4388
Licence Number
19/10/07
Date
Signature

Land (Planning and Environment) Act 1991
APPROVAL AMENDED
Pursuant to Section 247 in respect of the nominated amendments only
08 OCT 2007
Delegate of the Authority

Plan No: 054531/B
RECEIVED
22 OCT 2007
Planning & Land Authority

ALL DIMENSIONS IN MILLMETERS. DO NOT SCALE
DRAWING PRACTICE TO AS1100
BUILDER TO CONFIRM DIMENSIONS ON SITE PRIOR TO COMMENCEMENT OF WORK
ALL WORK TO BCA AND RELEVANT SAA CODES

AMENDMENTS OCTOBER 2007

Amendments	PROJECT	CLIENT NAME	Date: 20.07.2004	Scale: 1:100	
No Description - 28.09.2004	PROPOSED RESIDENCE	M & T BALLAT	Drawn By: CAD	BLOCK	SECTION
A1 W23 & W25 made obscure		DWG NAME	Sheet: 3 of 9	38	32
A2 Section 2 added		GROUND FLOOR PLAN	Dwg No: WE140A3A	CAMPBELL	
			CAD Ref: WE140MA		



UPPER FLOOR PLAN

ALL DIMENSIONS IN MILLMETERS. DO NOT SCALE
DRAWING PRACTICE TO AS1100
BUILDER TO CONFIRM DIMENSIONS ON SITE PRIOR TO COMMENCEMENT OF WORK
ALL WORK TO BCA AND RELEVANT SAA CODES

AMENDMENTS OCTOBER 2007

Land (Planning and Environment) Act 1991
APPROVAL AMENDED
Pursuant to Section 247 in respect of the nominated amendments only
08 OCT 2007
Delegate of the Authority

ACT Planning & Land Authority
RECEIVED
12 OCT 2007
Plan No: 05453/B

BUILDING APPROVAL
Approved under s.26 of the Building Act 2004. 32
JOHN BATES
Name
1988 4383
Licence Number
12/10/07
Date
Signature

4 of 9 AMENDED

Amendments	PROJECT	CLIENT NAME	Date: 20.07.2004	Scale: 1:100	
No Description - 28.09.2004	PROPOSED RESIDENCE	M & T BALLAT	Drawn By: CAD	BLOCK	SECTION
A1 W23 & W25 made obscure		DWG NAME	Sheet: 4 of 9	38	32
A2 Section 2 added		UPPER FLOOR PLAN	Dwg No: WE140A4A	CAMPBELL	
			CAD Ref: WE140MA		

LL DIMENSIONS IN MILLIMETERS. DO NOT SCALE
RAWING PRACTICE TO AS1100
UILDER TO CONFIRM ALL DIMENSIONS ON SITE
RIOR TO COMMENCEMENT OF WORK
LL WORK TO BCA AND RELEVANT SAA CODES

AMENDMENTS OCTOBER 2007

5 of 9
AMENDED

BUILDING APPROVAL
Approved under s.26 of the Building Act 2004. JZ
JOHN BATES
Name
1988 4388 19/10/07
Licence Number Date
Signature

Plan No: 054531/B
22 OCT 2007
RECEIVED
ACT Planning & Land Authority

Land (Planning and Environment) Act 1991
APPROVAL AMENDED
Pursuant to Section 247 in respect of the nominated amendments only
08 OCT 2007
Delegate of the Authority



ELEVATION A



ELEVATION B

Amendments

No	Description - 28.09.2004
A1	W23 & W25 made obscure
A2	Section 2 added

PROJECT

PROPOSED RESIDENCE

CLIENT NAME

M & T BALLAT

Date:	20.07.2004
Drawn By:	CAD
Scale:	1:100
Sheet:	5 of 9
Dwg No:	WE140A5A
CAD Ref:	WE140MA

ELEVATIONS

BLOCK	SECTION
38	32

CAMPBELL

LL DIMENSIONS IN MILLIMETERS. DO NOT SCALE
RAWING PRACTICE TO AS1100
UILDER TO CONFIRM ALL DIMENSIONS ON SITE
RIOR TO COMMENCEMENT OF WORK
LL WORK TO BCA AND RELEVANT SAA CODES

6 of 9
AMENDED

BUILDING APPROVAL
Approved under s.28 of the Building Act 2004. 32
JOHN BATES
Name
1988 4388 19/10/07
Licence Number Date
Signature



ELEVATION C

AMENDMENTS OCTOBER 2007

LOWER FLOOR:
- A DELETE GARAGE DOOR
- B PROVIDE R'DOOR ACCESS TO SUBFLOOR AS SHOWN
- C MODIFY WSH AS SHOWN

GROUND FLOOR:
- D MODIFY RETAINING WALL AS SHOWN
- E DELETE WALL
- F REPLACE BIFOLD DOOR UNIT WITH DOUBLE SLIDING DOOR UNIT
- G MODIFY FRONT DOOR UNIT AS SHOWN
- H MODIFY BED 4 ROBE AS SHOWN
- i MODIFY POWDER ROM - DOOR TO BE HINGED AND DELETE WALL ADJACENT TO WC AS SHOWN
- J REDUCE BED 4 WINDOWS

UPPER FLOOR:
- K MODIFY ENSUITE/WIR AS SHOWN

Land (Planning and Environment) Act 1991
APPROVAL AMENDED
Pursuant to Section 247 in respect of the nominated amendments only
08 OCT 2007
Delegate of the Authority



ELEVATION D

Amendments

No	Description - 28.09.2004
A1	W23 & W25 made obscure
A2	Section 2 added

Plan No: 054531/B
22 OCT 2007
RECEIVED
ACT Planning & Land Authority

PROJECT

PROPOSED RESIDENCE

CLIENT NAME

M & T BALLAT

Date:	20.07.2004
Drawn By:	CAD
Scale:	1:100
Sheet:	6 of 9
Dwg No:	WE140A6A
CAD Ref:	WE140MA

ELEVATIONS

BLOCK	SECTION
38	32

CAMPBELL

AMENDMENTS OCTOBER 2007

L DIMENSIONS IN MILLIMETERS. DO NOT SCALE
RAWING PRACTICE TO AS1100
JILDER TO CONFIRM ALL DIMENSIONS ON SITE
RIOR TO COMMENCEMENT OF WORK
L WORK TO BCA AND RELEVANT SAA CODES



SECTION 1

Land (Planning and Environment) Act 1991
APPROVAL AMENDED
Pursuant to Section 247 in respect of the nominated amendments only
08 OCT 2007
Delegate of the Authority



SECTION 2

7 OF 9
AMENDED

BUILDING APPROVAL
Approved under s.28 of the Building Act 2004.
JOHN BATES
Name
1988
4388
Licence Number
19/10/07
Date
Signature

Plan No: 054531/B
22 OCT 2007
RECEIVED
ACT Planning & Land Authority

Amendments

No	Description - 28.09.2004
A1	W23 & W25 made obscure
A2	Section 2 added

PROJECT

PROPOSED RESIDENCE

CLIENT NAME

M & T BALLAT

Date:	20.07.2004
Drawn By:	CAD
Scale:	1:100
Sheet:	7 of 9
Dwg No:	WE140A7A
CAD Ref:	WE140MA

SECTIONS

BLOCK	SECTION
38	32

CAMPBELL

ALL DIMENSIONS IN MILLIMETERS. DO NOT SCALE
DRAWING PRACTICE TO AS1100
BUILDER TO CONFIRM ALL DIMENSIONS ON SITE PRIOR TO COMMENCEMENT OF WORK
ALL WORK TO BCA AND RELEVANT SAA CODES



10 ELLIOTT STREET

VERGE MANAGEMENT PLAN

62 of 91

AMENDMENTS OCTOBER 2007

LOWER FLOOR:

A DELETE GARAGE DOOR
B PROVIDE R'DOOR ACCESS TO SUBFLOOR AS SHOWN
C MODIFY WSH AS SHOWN

GROUND FLOOR:

D MODIFY RETAINING WALL AS SHOWN
E DELETE WALL
F REPLACE BIFOLD DOOR UNIT WITH DOUBLE SLIDING DOOR UNIT
G MODIFY FRONT DOOR UNIT AS SHOWN
H MODIFY BED 4 ROBE AS SHOWN
i MODIFY POWDER ROM - DOOR TO BE HINGED AND DELETE WALL ADJACENT TO WC AS SHOWN
J REDUCE BED 4 WINDOWS

UPPER FLOOR:

K MODIFY ENSUITE/WIR AS SHOWN

PROTECTION OF EXISTING TREES

ALL VERGE TREES ARE TO BE RETAINED AND KEPT UNDAMAGED
MAINTAIN PROTECTIVE ENCLOSURE CONSISTING OF CHAIN MESH PANELS AS COMPLETE ENCLOSURE AROUND EXISTING TREES

VERGE MANAGEMENT

NO STOREAGE OF CONSTRUCTION MATERIALS EQUIPMENT OR CARPARKING PERMITTED ON THE VERGE
EXISTING DRIVEWAY ACCESS POINT TO BE USED FOR ALL SITE ACCESS
COORDINATE ALL SERVICE APPROVALS, PERMISSION MUST BE SOUGHT FROM CANBERRA URBAN PARKS BEFORE EXCAVATING WITHIN VERGE

8 of 9
AMENDED

VERGE RESTORATION

PROTECT EXISTING GRASS COVER, AT COMPLETION OF CONSTRUCTION VERGE SHOULD STILL HAVE ESTABLISHED GRASS COVER
SHOULD RESTORATION BE REQUIRED, LIGHTLY CULTIVATE AND SOW WITH SIMILAR SEED SPECIES

NOTE

THE DEVELOPER IS RESPONSIBLE FOR THE REINSTATEMENT OF ALL DAMAGE INCURRED TO LAND, VEGETATION, SERVICES, PATHS AND ROADS AS A RESULT OF THIS CONSTRUCTION WORK

BUILDING APPROVAL
Approved under s.28 of the Building Act 2004. 32
JOHN BATES
Name
1988 4388
Licence Number
19/10/07
Date
Signature

Land (Planning and Environment) Act 1991
APPROVAL AMENDED
Pursuant to Section 247 in respect of the nominated amendments only
08 OCT 2007
Delegate of the Authority

1800 HIGH CONTINUOUS CHAIN MESH FENCE PANELS SUPPORTED BY 2400 HIGH STAS STEEL POSTS
FENCE TO BE ERECTED AT COMMENCEMENT OF WORK AND REMOVED AT COMPLETION
FENCE TO REMAIN CONTINUOUS THROUGHOUT THE PROJECT EXCEPT WHERE SERVICES INSTALLATION OCCURS SEEK APPROVAL FROM CANBERRA URBAN PARKS FOR TRENCH LOCATIONS

AMENDMENTS OCTOBER 2007

N

Amendments

No	Description - 28.09.2004
A1	W23 & W25 made obscure
A2	Section 2 added

Plan No: 054531/B
22 OCT 2007
RECEIVED
ACT Planning & Land Authority

PROJECT

PROPOSED RESIDENCE

CLIENT NAME

M & T BALLAT

Date:	20.07.2004
Drawn By:	CAD
Scale:	1:200
Sheet:	8 of 9
Dwg No:	WE140A8A
CAD Ref:	WE140MA

VERGE MANAGEMENT PLAN

BLOCK	SECTION
38	32

CAMPBELL

ALL DIMENSIONS IN MILLIMETERS. DO NOT SCALE
DRAWING PRACTICE TO AS1100
BUILDER TO CONFIRM ALL DIMENSIONS ON SITE
PRIOR TO COMMENCEMENT OF WORK
ALL WORK TO BCA AND RELEVANT SAA CODES

9 OF 9
AMENDED

BUILDING APPROVAL
Approved under s.26 of the Building Act 2004. 32
JOHN BATES
Name
1988 4388 Licence Number
19/10/07 Date
Signature

Land (Planning and Environment) Act 1991
APPROVAL AMENDED
Pursuant to Section 247 in respect of the nominated amendments only
08 OCT 2007
Delegate of the Authority

DEMOLITION NOTES

1 ALL DEMOLITION WORK TO BE CARRIED OUT IN ACCORDANCE WITH ACT WORKCOVER REQUIREMENTS USING NON EXPLOSIVE METHODS
2 ALL DEMOLITION MATERIALS TO BE SALVAGED FOR SALE AND/OR RECYCLING UNLESS STATED OTHERWISE
3 ANY ASBESTOS MATERIALS TO BE REMOVED FROM SITE IN ACCORDANCE WITH ACT WORKCOVER REGULATIONS AND DISPOSED OF AT AN AUTHORISED TIP

VERGE MANAGEMENT

1 NATURE STRIP TO BE FENCED OFF AND PROTECTED
2 ALL MATERIALS TO BE STORED ON SITE MATERIALS SHOULD NOT BE STORED ON NATURE STRIP
3 PROVIDE TEMPORARY WET WEATHER VEHICULAR ACCESS TO SITE

TREE PROTECTION NOTES

1 NO SITE SHEDS, BUILDINGS OR VEHICULAR PARKING WITHIN THE ROOT ZONE (DRIP ZONE + 2m)
2 TEMPORARY PROTECTIVE ENCLOSURE IS REQUIRED AROUND THE ROOT ZONE OF THE TREE GROUPS AND SHOULD CONSIST OF STAR PICKETS WITH ORANGE PLASTIC WOVEN FENCING MATERIALS
3 WHERE PLANT OPERATION IN CLOSE PROXIMITY TO TREES IS UNAVOIDABLE PROTECTIVE LASHING WITH TIMBER BATTENS SHOULD BE PLACED AROUND TRUNK OF TREES
4 THERE SHOULD BE NO EXCAVATION OF SERVICES OR FOOTINGS WITHIN 3m OF THE TREE TRUNK
5 EXCAVATION REQUIRED WITHIN THE DROP ZONE OF TREES MUST BE DONE BY HAND

DEMOLITION PLAN



AMENDMENTS OCTOBER 2007

N

Amendments

No	Description - 28.09.2004
A1	W23 & W25 made obscure
A2	Section 2 added

Plan No: 054531/B
22 OCT 2007
RECEIVED
ACT Planning & Land Authority

PROJECT

PROPOSED RESIDENCE

CLIENT NAME

M & T BALLAT

Date:	20.07.2004
Drawn By:	CAD
Scale:	1:200
Sheet:	9 of 9
Dwg No:	WE140A9A
CAD Ref:	WE140MA

DEMOLITION PLAN

BLOCK	SECTION
38	32

CAMPBELL

Certificate of Occupancy and Use

Certificate No.: **B2012414C1**

Access Canberra Building Services

ABN 16 479 763 216
8 Darling Street Mitchell
GPO Box 158 ACT 2601
www.act.gov.au/accesscbr

This Certificate is issued in accordance with Section 69 (2) of the Building Act 2004.

The building work listed on this certificate has been completed substantially in accordance with the prescribed requirements and is considered fit for occupation and use.

Unit	Block	Section	Division (Suburb)	District	Jurisdiction
	38	32	CAMPBELL	CANBERRA CENTRAL	Australian Capital Territory

Plans
B2012414/A

Building Works

Class of Occupancy	Nature of Work	Project Item Description	Other Description	Type Of Const.	Unit	BCN ID	Builder
1a(I)	Other	SEE DESCRIPTION	Fire place	NA		B2012414N1	MARK BALLAT

Comments **Important Note:**

1. Residential building statutory warranties and residential insurance do not apply in relation to building work.

2. The issue, under this Part, of a certificate in respect of a building or portion of a building does not affect the liability of a person to comply with the provisions of a law of the territory (including this Act) relating to the building or portion of the building.

Issued by: Anna Musgrove

Delegate of the ACT Construction Occupations Registrar.

Issued on: 19/01/2017

TECHNICAL DATA & INSTALLATION INSTRUCTIONS

Installation shall comply with building AS 2918/2001

It is recommended that a Cheminees Philippe specialist build your fireplace or install firebox and flues
Contact Cheminee for details (02 9564 2694)

1-Fireplace structure & finishes shall be to your own design, providing the exact & minimum dimensions are maintained.

2- Firebox dimensions means the overall dimension of the firebox from Extremity to Extremity.

3- Exact dimension means a dimension between two finished surfaces.

4- Minimum dimension means a dimension equal to or greater than specified.

5- The floor must have adequate strength to support the fireplace structure, floor may require additional reinforcing.

6- Construction of the fireplace structure, from floor to ceiling shall be solid brick (not with holes) or Hebel 150mm minimum thickness (use Hebel lintel only). Rendering Hebel NOT recommended).
FIREBOX MUST SIT ON SOLID MASONARY BASE.
NB: CHECK HEARTH REQUIREMENTS FOR INSTALATION COMBUSTIBLE FLOOR

7- Double skin wall with a 50mm cavity is required at the back of the firebox, when it forms a part of external wall.

8- Deflector shall be steel metal sheet: 20 gauge minimum, and must be fitted with a minimum clearance of 300mm from lowest ceiling to heat release grilles.

9- Thermal insulation (Les Radiantes Rockwool) shall be heat resistant with minimum thermal of rating of R.0.75 kw/m^2 with aluminium foil adhered to one side, aluminium foil to face down directly on top of deflector.

10- Seal around the perimeter of the deflector & stainless steel flue with heat proof silicone or putty & Rockwool (steel deflector)

11- 2 Ventilation grilles of not less than 500cm^2 shall be fitted below the deflector to allow the release of heat into the room. One large grille in front or two smaller grilles on either side of the brickwork are permitted.

12- Radiantes - 600/692/693/700/705 air intake is via mesh vents adjacent to the front glass door.
Radiantes - 600/ 800/821/842/843/845/845.6/846/930/1000/2000/2001/Quadra air intake will be provided through grilles situated on both sides of the fireplace structure, the base of these grilles shall be located at the level of the base of firebox and shall be not less than 500cm^2 in size.

13- Allow a minimum clearance of 5.0mm between the firebox mesh vents & the Finished fireplace opening.

14- Allow a minimum clearance of 200mm between the firebox cast iron sides & the internal structural walls.

15- Single skin flue stainless steel(mini 0.5mm thickness) shall only be used when the fireplace & the chimney structure continue through ceiling and above roof level and must be pop riveted with stainless steel rivets

16- *Triple skin flue with stainless steel active flue (modular air flow type) shall be used when the masonry fireplace* structure terminates at ceiling level 9" -13" flues to be riveted with stainless steel rivets.

17- Wood mantelpieces shall be installed a minimum distance of 300mm from the top of the finished opening depending on shelf depth & 200mm from the sides of the finished opening.

18- Allow the fireplace structural work to cure for a minimum 21 days prior to use.

All information subject to change without prior notice

CHEMINÉES PHILIPPE

Proudly heating Australian Homes Since 1982

118 Stanmore Road Stanmore NSW 2048 Ph: 02 9564 2694

www.chemince.com.au

The French Fire Place Specialists

NSW
CHEMINEE P/L
118 Stanmore Rd
Stanmore NSW 2048
Ph: 9564 2694
Fax: 9569 8802



FIREBOX

RADIANTE 600

EXAMPLE OF INSTALLATION ONLY

Legend

- ● Firebox Dimension
- ▲ Exact Dimension
- ■ Minimum Dimension
- Air Intake
- Air Outlet

✻ **Before building base confirm with cheminee**





PLAN

SECTION

Cheminees Philippe Australia



1. Place flue adaptor inside cast iron spigot tap down gently and pop rivet
2. crimpled end of st/st flue to face downwards, the starter flue with gussets has no crimp.
3. Deflector plate to installed at 1800mm above the base of the firebox.
4. Deflector (steel gal supplied with Rockwool panels) to be set into course of brickwork by approx 30mm to ensure a good seal.
5. Any part of the brickwork forming part of an outside wall to be double brick construction with a cavity to avoid heat loss.
6. All flues to secured with 3 st/st rivets.

Sketch example: simulated chimney installation.

Flue Installation for Cheminees Phillippe Fireplaces

(Using brickwork from floor to ceiling)



1. Determine height of deflector assy and cut starter flue to achieve setup as per drawing. Ventilation slots of triple flue must be approx 30mm above top of Rockwool insulation
2. Fit starter flue (with Gussets) over outside of cast iron collar of firebox. Drill thru collar and secure with stainless steel screws or rivets (x3) Gussets to under side deflector
3. All stainless steel inner flues must be joined using stainless steel pop rivits
4. Set deflector plate into course of brickwork by 30mm to ensure a good seal
5. Place rockwool blanket(aluminium side down) on top of deflector plate ensuring complete coverage up to sides of brick enclosure and a neat fit around triple flue
6. 50mm clearance is required from outer casing to timbers and other combustible material
7. Pick up weight off outer casing in roof space
8. At the termination height of the triple flue the active stainless steel inner must be 30mm higher than the middle and outer gal casing. The stainless steel skirt is screwed to the crimp of the outer casing the stainless steel cowl slides into the neck of the skirt and must locate inside the active flue below.

Sketch Example of a Cheminees Phillippe Simulated Chimney Installation



NOTE

BONDEK SLAB TO GROUND FLOOR

BUILDING APPROVAL
Issued under section 28 of the *Building Act 2004*
Certified Building Solutions Pty Ltd
- 3 FEB 2012
Licence No: 200426203

GROUND FLOOR PLAN

ALL DIMENSIONS IN MILLMETERS. DO NOT SCALE
DRAWING PRACTICE TO AS1100
BUILDER TO CONFIRM DIMENSIONS ON SITE PRIOR TO COMMENCEMENT OF WORK
ALL WORK TO BCA AND RELEVANT SAA CODES

Amendments	PROJECT	CLIENT NAME	Date: 20.07.2004	Scale: 1:100	
	PROPOSED FIREPLACE	M & T BALLAT	Drawn By: CAD	BLOCK	SECTION
		DWG NAME	Sheet: 3 of 8	38	32
		GROUND FLOOR PLAN	Dwg No: WE140A3	CAMPBELL	
			CAD Ref: WE140MA		

Certificate of Occupancy and Use

Certificate No.: **B20142365C1**

Access Canberra Building Services

ABN 16 479 763 216
8 Darling Street Mitchell
GPO Box 158 ACT 2601
www.act.gov.au/accesscbr

This Certificate is issued in accordance with Section 69 (2) of the Building Act 2004.

The building work listed on this certificate has been completed substantially in accordance with the prescribed requirements and is considered fit for occupation and use.

Unit	Block	Section	Division (Suburb)	District	Jurisdiction
	38	32	CAMPBELL	CANBERRA CENTRAL	Australian Capital Territory

Plans
B20142365/A
B20142365/B

Building Works

Class of Occupancy	Nature of Work	Project Item Description	Other Description	Type Of Const.	Unit	BCN ID	Builder
1a(I)	Additions	DA EXEMPT-RESIDENCE	Additions and Alterations (non-habitable)	NA		B20142365N1	MICHAEL BALLAT

Comments **Important Note:**

1. Residential building statutory warranties and residential insurance do not apply in relation to building work.

2. The issue, under this Part, of a certificate in respect of a building or portion of a building does not affect the liability of a person to comply with the provisions of a law of the territory (including this Act) relating to the building or portion of the building.

Issued by: Tina Gioffre

Delegate of the ACT Construction Occupations Registrar.

Issued on: 19/10/2015



RL 599.30

PROPOSED ALTERATIONS

(CONVERT EXISTING SUBFLOOR INTO STUDIO/BATHROOM)

Class 1a(;)

BUILDING APPROVAL
Issued under section 28 of the *Building Act 2004*
Certified Building Solutions Pty Ltd
2 2 MAY 2014
Licence No: 200426203

23444

N

SITE PLAN

1:200

BLOCK: 38
SECTION: 32
CAMPBELL

SCALE 1:200
0 5 10 15

AREAS	
BLOCK AREA:	711m²
EX. GARAGE:	60.9m²
EX. GROUND FLOOR:	157.8m²
EX. UPPER FLOOR:	75.0m²
EX. PATIO:	16.0m²
EX. DECK:	19.5m²
EX. FRONT PORCH:	16.0m²
TOTAL EX. GFA:	309.7m²
NEW STUDIO/BATH:	38.5m²
NEW TOTAL GFA:	348.2m²
PLOT RATIO:	48.97%

NOT IN GFA

8m² EXTENSION AND 30.5m² BASEMENT

NO CHANGE TO EXISTING VERGE CROSSING

AKDESIGN
ARCHITECTURAL DRAFTING
Alex Kwong
35 Marungul Avenue Ngunnawal ACT 2913
MOBILE: 0414 227 079
EMAIL: akdesign@ozemail.com.au

PROPOSED ALTERATIONS

BLOCK: 38
SECTION: 32 CAMPBELL
CLIENT: T & M BALLAT of 10 Elliott Street Campbell

DWN: A.KWONG

SCALE: 1:200	DATE: 8/5/14
DWG No.: 1425	SHEET: 1 OF 4

BUILDING APPROVAL
Issued under section 28 of the *Building Act 2004*
Certified Building Solutions Pty Ltd
2 2 MAY 2014
Licence No: 200426203

23444



GARAGE FLOOR PLAN



SECTION A-A

ALTERATIONS

1. PROVIDE STUDFRAMING TO CONVERT PART OF EXISTING SUBFLOOR SPACE INTO STUDIO/WORKSHOP (WITH BATHROOM) AS SHOWN AND AS PER SECTION A
2. BATTEN OUT EXISTING EXTERNAL WALL AND LINE INTERNALLY WITH PB LINING. PROVIDE POLYSTYRENE INSULATION AS POSSIBLE TO MAN. SPEC.
3. INSTALL GLAZED BIFOLD DOORS (SUPPLIED BY CLIENTS) AS SHOWN AND TO CLIENTS DIRECTION
4. NEW BATHROOM FITOUT AS SHOWN. ENSURE MECH. VENTILATION TO CLIENTS DIRECTION AND BCA.
5. DEMOLISH EXTERNAL WALL TO INSTALL NEW SLIDING DOOR UNIT AS SHOWN. MAKE GOOD AND PROVIDE NEW LINTEL OVER TO ENG. SPEC.
6. DEMOLISH EXTERNAL WALL TO INSTALL NEW WINDOW UNIT AS SHOWN. MAKE GOOD AND PROVIDE NEW LINTEL OVER TO ENG. SPEC.
7. PROVIDE NEW NRG SUNHOOD (OR SIMILAR) OVER NEW SLIDING DOOR TO CLIENTS SELECTION AND MAN. SPEC.
8. EXCAVATE EXISTING GROUND LINE AND PROVIDE NEW MASONRY RETAINING WALL TO ENGINEER'S SPEC. ENSURE WATERPROOFING AND AG. DRAIN TO SW TIE. PROVIDE NEW FENCE OVER AS NOTED
9. PROVIDE NEW FENCE AND GATE TO CLIENTS DIRECTION
10. PROVIDE NEW SUMP TO CLIENTS DIRECTION AND CONNECTED TO SW TIE

SECTION NOTES:

ALL STRUCTURAL AND NON-STRUCTURAL TIMBER TO BE IN ACCORDANCE WITH THE TIMBER FRAMING CODE AS1684

ALL STRUCTURAL STEEL COLUMNS, POST, BEAMS ALL TO BE CERTIFIED AND DESIGNED BY STRUCTURAL ENGINEER.

PROVIDE 90x35 MGP OR 90x45 MGP STUDS AS REQUIRED TO AS1684 AND/OR TO MAN. SPECIFICATIONS.

BRACING AS PER BCA AND ENGINEER'S SPECIFICATIONS

PLASTERBOARD AND FC LININGS TO INTERNAL WALLS AND CEILINGS AS REQUIRED

LINTELS AS PER TRUSS MANUFACTURERS CHARTS AND ENGINEER'S SPECIFICATIONS

ALL EXTERNAL SWING DOORS AND INTERNAL ACCESS DOORS TO BE FULLY SEALED

50mm CAVITY DIMENSION TO EXTERNAL B/V WALL

MECHANICAL VENTILATION DUCTED TO EXTERIOR TO COMPLY WITH BCA 3.8.5.2(c)

SHOWER SCREENS AND WET AREA GLAZING TOUGHENED GLASS AS PER BCA 3.6.4

AKDESIGN
ARCHITECTURAL DRAFTING
Alex Kwong
35 Marungul Avenue Ngunnawal ACT 2913
MOBILE: 0414 227 079
EMAIL: akdesign@ozemail.com.au

PROPOSED ALTERATIONS

BLOCK: 38
SECTION: 32 CAMPBELL
CLIENT: T & M BALLAT of
10 Elliott Street Campbell

DWN: A.KWONG	
SCALE: 1:100	DATE: 8/5/14
DWG No.: 1425	SHEET: 2 OF 4



NORTH-EAST ELEVATION

SOUTH-WEST (STREET) ELEVATION

BUILDING APPROVAL
Issued under section 28 of the *Building Act 2004*
Certified Building Solutions Pty Ltd
2 2 MAY 2014
Licence No: 200426203



23444

NORTH-WEST ELEVATION

AKDESIGN
ARCHITECTURAL DRAFTING
Alex Kwong
35 Marungul Avenue Ngunnawal ACT 2913
MOBILE: 0414 227 079
EMAIL: akdesign@ozemail.com.au

PROPOSED ALTERATIONS

BLOCK: 38
SECTION: 32 CAMPBELL
CLIENT: T & M BALLAT of 10 Elliott Street Campbell

DWN: A.KWONG
SCALE: 1:100 | DATE: 8/5/14
DWG No.: 1425 | SHEET: 3 OF 4

BUILDING APPROVAL
Issued under section 28 of the *Building Act 2004*
Certified Building Solutions Pty Ltd
2 2 MAY 2014
Licence No: 200426203

23444



GARAGE FLOOR PLAN



SECTION A-A

ALTERATIONS

1. PROVIDE STUDFRAMING TO CONVERT PART OF EXISTING SUBFLOOR SPACE INTO STUDIO/WORKSHOP (WITH BATHROOM) AS SHOWN AND AS PER SECTION A
2. BATTEN OUT EXISTING EXTERNAL WALL AND LINE INTERNALLY WITH PB LINING. PROVIDE POLYSTYRENE INSULATION AS POSSIBLE TO MAN. SPEC.
3. INSTALL GLAZED BIFOLD DOORS (SUPPLIED BY CLIENTS) AS SHOWN AND TO CLIENTS DIRECTION
4. NEW BATHROOM FITOUT AS SHOWN. ENSURE MECH. VENTILATION TO CLIENTS DIRECTION AND BCA.
5. DEMOLISH EXTERNAL WALL TO INSTALL NEW SLIDING DOOR UNIT AS SHOWN. MAKE GOOD AND PROVIDE NEW LINTEL OVER TO ENG. SPEC.
6. DEMOLISH EXTERNAL WALL TO INSTALL NEW WINDOW UNIT AS SHOWN. MAKE GOOD AND PROVIDE NEW LINTEL OVER TO ENG. SPEC.
7. PROVIDE NEW NRG SUNHOOD (OR SIMILAR) OVER NEW SLIDING DOOR TO CLIENTS SELECTION AND MAN. SPEC.
8. EXCAVATE EXISTING GROUND LINE AND PROVIDE NEW MASONRY RETAINING WALL TO ENGINEER'S SPEC. ENSURE WATERPROOFING AND AG. DRAIN TO SW TIE. PROVIDE NEW FENCE OVER AS NOTED
9. PROVIDE NEW FENCE AND GATE TO CLIENTS DIRECTION
10. PROVIDE NEW SUMP TO CLIENTS DIRECTION AND CONNECTED TO SW TIE

SECTION NOTES:

ALL STRUCTURAL AND NON-STRUCTURAL TIMBER TO BE IN ACCORDANCE WITH THE TIMBER FRAMING CODE AS1684

ALL STRUCTURAL STEEL COLUMNS, POST, BEAMS ALL TO BE CERTIFIED AND DESIGNED BY STRUCTURAL ENGINEER.

PROVIDE 90x35 MGP OR 90x45 MGP STUDS AS REQUIRED TO AS1684 AND/OR TO MAN. SPECIFICATIONS.

BRACING AS PER BCA AND ENGINEER'S SPECIFICATIONS

PLASTERBOARD AND FC LININGS TO INTERNAL WALLS AND CEILINGS AS REQUIRED

LINTELS AS PER TRUSS MANUFACTURERS CHARTS AND ENGINEER'S SPECIFICATIONS

ALL EXTERNAL SWING DOORS AND INTERNAL ACCESS DOORS TO BE FULLY SEALED

50mm CAVITY DIMENSION TO EXTERNAL B/V WALL

MECHANICAL VENTILATION DUCTED TO EXTERIOR TO COMPLY WITH BCA 3.8.5.2(c)

SHOWER SCREENS AND WET AREA GLAZING TOUGHENED GLASS AS PER BCA 3.6.4

AKDESIGN
ARCHITECTURAL DRAFTING
Alex Kwong
35 Marungul Avenue Ngunnawal ACT 2913
MOBILE: 0414 227 079
EMAIL: akdesign@ozemail.com.au

PROPOSED ALTERATIONS

BLOCK: 38
SECTION: 32 CAMPBELL
CLIENT: T & M BALLAT of
10 Elliott Street Campbell

DWN: A.KWONG	
SCALE: 1:100	DATE: 8/5/14
DWG No.: 1425	SHEET: 2 OF 4

GENERAL NOTES: (WHERE APPLICABLE)

ALL LEVELS, SITE CUTS, GROUND LEVELS, FFL'S TO BE CONFIRMED ON SITE PRIOR TO THE COMMENCEMENT OF ANY WORKS (INCLUDING DRIVEWAY LEVELS)

ANY DISCREPANCIES TO BE DIRECTED TO BUILDER AND/OR DESIGNER IMMEDIATELY

INCLUSIONS LIST TO TAKE PRECEDENCE OVER DRAWINGS

CARRY OUT ALL WORK IN COMPLIANCE WITH THE RELEVANT SAA CODES OF PRACTICE IN THE BEST TADESMAN-LIKE MANNER TO THE APPROVAL OF THE BUILDING CERTIFIER AND AUTHORITIES HAVING JURISDICTION OVER THE WORKS INCLUDING BUT NOT RESTRICTED TO:
A) ACT GOVERNMENT
B) BUILDING CODE OF AUSTRALIA AND THE ACT APPENDIX
C) ACT ELECTRICITY AND WATER
D) AS1684 TIMBER FRAMING CODE AND AS FURTHER SPECIFIED.

ALL DIMENSIONS MUST BE VERIFIED ON SITE BEFORE COMMENCING ANY WORK OR MAKING ANY SHOP DRAWINGS. USE FIGURED DIMENSIONS ONLY AND DO NOT SCALE OFF THE DRAWING

SURVEYOR TO CONFIRM EASEMENT LOCATIONS PRIOR TO COMMENCEMENT OF ANY WORKS

MATERIALS AND WORKMANSHIP TO BE IN ACCORDANCE WITH THE BCA, ALL OTHER RELEVANT CODES AND AUSTRALIAN STANDARDS

PROVIDE SMOKE ALARMS IN ACCORDANCE WITH PART 3.7.2 OF THE BCA (REFER ELECTRICAL LAYOUT)

ALL WINDOWS/GLAZED DOORS TO BE DOUBLE GLAZED ALUMINIUM IMPROVED FRAMES (UNLESS NOTED OTHERWISE) AS PER ATTACHED EER.

LIGHTING TO COMPLY WITH 3.12.5.5 OF THE BCA

ALL TIMBER FRAMING AND CONSTRUCTION TO BE IN ACCORDANCE WITH THE LATEST TIMBER FRAMING CODE AS1684 AND BCA

EXTERNAL WALLS TO BE BRICK VENEER UNLESS STATED ON PLANS, WHEN LIGHTWEIGHT CLADDING IS USED IT IS TO BE INSTALLED TO MANUFACTURERS SPECIFICATIONS AND SARKED AND INSULATED AS PER THE BCA AND ATTACHED EER.

ALL INSULATION R VALUES AND WINDOW SHGC AND U-VALUES AS PER THE ATTACHED EER.

ALL OPENABLE WINDOWS AND SLIDING DOORS TO HAVE FLYSCREENS TO BE POWDERCOATED ALUMINIUM FRAMES TO MATCH WINDOWS. NOTE: METALLIC FLYSCREENS ARE REQUIRED IN BUSHFIRE PRONE AREAS

REFER TO STRUCTURAL ENGINEER'S ATTACHED DOCUMENTATION FOR ALL STRUCTURAL DETAILS

ALL EXTERNAL WINDOWS TO HAVE BRICK ON EDGE WINDOW SILLS WITH DAMP PROOF MEMBRANE UNDER TO BCA

PROVIDE TERMITE PROTECTION TO CODE AND AS3660-2000 PARTS 1, 2 AND 3

WATERPROOFING:

WATER PROOFING OF WET AREAS AS PER BUT NOT LIMITED TO AS 3740 WATERPROOFING NOT LESS THAN 150mm ABOVE FFL TO PENETRATIONS IN SHOWERS. WALL AND FLOOR JUNCTIONS IN SHOWERS NOT LESS THAN 180mm ABOVE FFL IN THE SHOWER AREA. WATERPROOFING NOT LESS THAN 25mm ABOVE MAXIMUM RETAINED WATER LEVEL. SHOWER FLOOR TO FULLY AS PER AS3740.

'DAVCO' WATER PROOFING SYSTEM TO MANUFACTURER'S SPECIFICATIONS AND AS3740

BUILDING APPROVAL
Issued under section 28 of the *Building Act 2004*
Certified Building Solutions Pty Ltd
2 2 MAY 2014
Licence No: 200426203

23444

SERVICES/ELECTRICAL/WASTE:

NO INTERNAL DRAINAGE FOR PROPOSED STRUCTURE TO BE LOCATED IN SEWER EASEMENT/PIPE PROTECTION ENVELOPE. ALL WORKS DONE TO ACTEW GUIDELINES/ADVICE

ALL BUILDING WASTE TO BE COLLECTED IN HOPPER LOCATED ON SITE, RESIDENTIAL WASTE TO BE COLLECTED BY ROADSIDE PICKUP AND BINS TO BE LOCATED ON SITE

METER BOX TO BE INSTALLED TO ACTEW AGL SERVICE AND INSTALLATION RULES

LIGHTING TO COMPLY WITH 3.12.5.5 OF THE BCA - REFER ELECTRICAL LAYOUT. ARTIFICIAL LIGHTING MUST NOT EXCEED 5W/M2

WATER HEATER IN HOT WATER SUPPLY SYSTEM TO COMPLY WITH 3.12.5.6 OF THE BCA

STORMWATER AND SEWER AND WATER TIES TO BE LOCATED ON HYDRAULIC/DRAINAGE PLANS

TELSTRA AND GAS TIES TO BE PROVIDED BY GAS FITTER AND ELECTRICIAN

DOWNPIPES TO ROOF PLUMBERS SPECIFICATIONS

ENSURE THAT THE DEVELOPMENT COMPLIES WITH TERRITORY AND MUNICIPAL SERVICES (TAMS) STATING THAT WASTE FACILITIES AND MANAGEMENT ASSOCIATED WITH DEVELOPMENT ARE IN ACCORDANCE WITH THE DEVELOPMENT CONTROL CODE FOR BEST PRACTICE WASTE MANAGEMENT IN THE ACT 1999

EROSION & SEDIMENT CONTROL PLAN

MAINTAIN AS MANY GRASSED AREAS AS POSSIBLE PARTICUARILY ON THE VERGES TO TRAP SOIL BEFORE IT REACHES THE ROADWAY AND STORMWATER SYSTEM, FENCE OFF UNDISTURBED AREAS

USE ONLY ONE EXIT/ENTRY TO THE SITE. BUILD A STABILISED ACCESS POINT BY USING ROAD BASE, 50mm AGGREGATE, RECYCLED CONCRETE OR SIMILAR

ASSIGN A DESIGNATED PARKING AREA

LIMIT ACCESS TO THE SITE DURING AND IMMEDIATELY AFTER WET WEATHER

KEEP STOCKPILES WITHIN THE SITE AREA AND AWAY FROM THE STORMWATER SYSTEM

INSTALL ON-SITE WASTE COLLECTION

REGULARLY REMOVE ANY SEDIMENT FROM ROADS ADJACENT TO YOUR SITE. DO NOT WASH INTO THE STORMWATER SYSTEM

INSTALL A SEDIMENT CONTROL BARRIER OF GEOTEXTILE FABRIC ON THE LOW SIDE/S OF THE BLOCK (AS NOTED ON THE SITE PLAN AND AS PER DETAIL)

DESIGNATE A BRICK CUTTING AND WASHING AREA AWAY FROM STORMWATER DRAINS.
ENSURE THE AREA IS LARGE ENOUGH TO CONTAIN ALL EXCESS WATER, RESIDUES AND WASTE

REGULARLY CHECK AND MAINTAIN POLLUTION CONTROLLS THROUGHOUT CONSTRUCTION

ENSURE THAT THE DEVELOPMENT COMPLIES WITH THE ACT ENVIRONMENT PROTECTION AUTHORITY, ENVIRONMENT PROTECTION GUIDELINES FOR CONSTRUCTION AND LAND DEVELOPMENT IN THE ACT, MARCH 2010



SEDIMENT CONTROL DETAIL

AKDESIGN
ARCHITECTURAL DRAFTING
Alex Kwong
35 Marungul Avenue Ngunnawal ACT 2913
MOBILE: 0414 227 079
EMAIL: akdesign@ozemail.com.au

PROPOSED ALTERATIONS	
BLOCK: 38	
SECTION: 32 CAMPBELL	
CLIENT: T & M BALLAT of 10 Elliott Street Campbell	
DWN: A.KWONG	
SCALE:	DATE: 8/5/14
DWG No.: 1425	SHEET: 4 OF 4

BUILDING APPROVAL
is amended under section 32 of the *Building Act 2004*
Certified Building Solutions Pty Ltd
20 AUG 2014
Licence No:
200426203



(1) AMENDED LAYOUT

GARAGE FLOOR PLAN



SECTION A-A

ALTERATIONS

1. PROVIDE STUDFRAMING TO CONVERT PART OF EXISTING SUBFLOOR SPACE INTO STUDIO/WORKSHOP (WITH BATHROOM) AS SHOWN AND AS PER SECTION A
2. BATTEN OUT EXISTING EXTERNAL WALL AND LINE INTERNALLY WITH PB LINING. PROVIDE POLYSTYRENE INSULATION AS POSSIBLE TO MAN. SPEC.
3. INSTALL GLAZED BIFOLD DOORS (SUPPLIED BY CLIENTS) AS SHOWN AND TO CLIENTS DIRECTION
4. NEW BATHROOM FITOUT AS SHOWN. ENSURE MECH. VENTILATION TO CLIENTS DIRECTION AND BCA.
5. DEMOLISH EXTERNAL WALL TO INSTALL NEW SLIDING DOOR UNIT AS SHOWN. MAKE GOOD AND PROVIDE NEW LINTEL OVER TO ENG. SPEC.
6. DEMOLISH EXTERNAL WALL TO INSTALL NEW WINDOW UNIT AS SHOWN. MAKE GOOD AND PROVIDE NEW LINTEL OVER TO ENG. SPEC.
7. PROVIDE NEW NRG SUNHOOD (OR SIMILAR) OVER NEW SLIDING DOOR TO CLIENTS SELECTION AND MAN. SPEC.
8. EXCAVATE EXISTING GROUND LINE AND PROVIDE NEW MASONRY RETAINING WALL TO ENGINEER'S SPEC. ENSURE WATERPROOFING AND AG. DRAIN TO SW TIE. PROVIDE NEW FENCE OVER AS NOTED
9. PROVIDE NEW FENCE AND GATE TO CLIENTS DIRECTION
10. PROVIDE NEW SUMP TO CLIENTS DIRECTION AND CONNECTED TO SW TIE

SECTION NOTES:

ALL STRUCTURAL AND NON-STRUCTURAL TIMBER TO BE IN ACCORDANCE WITH THE TIMBER FRAMING CODE AS1684

ALL STRUCTURAL STEEL COLUMNS, POST, BEAMS ALL TO BE CERTIFIED AND DESIGNED BY STRUCTURAL ENGINEER.

PROVIDE 90x35 MGP OR 90x45 MGP STUDS AS REQUIRED TO AS1684 AND/OR TO MAN. SPECIFICATIONS.

BRACING AS PER BCA AND ENGINEER'S SPECIFICATIONS

PLASTERBOARD AND FC LININGS TO INTERNAL WALLS AND CEILINGS AS REQUIRED

LINTELS AS PER TRUSS MANUFACTURERS CHARTS AND ENGINEER'S SPECIFICATIONS

ALL EXTERNAL SWING DOORS AND INTERNAL ACCESS DOORS TO BE FULLY SEALED

50mm CAVITY DIMENSION TO EXTERNAL B/V WALL

MECHANICAL VENTILATION DUCTED TO EXTERIOR TO COMPLY WITH BCA 3.8.5.2(c)

SHOWER SCREENS AND WET AREA GLAZING TOUGHENED GLASS AS PER BCA 3.6.4

AKDESIGN
ARCHITECTURAL DRAFTING
Alex Kwong
35 Marungui Avenue Ngunnawal ACT 2913
MOBILE: 0414 227 079
EMAIL: akdesign@ozemail.com.au

23444

PROPOSED ALTERATIONS

BLOCK: 38
SECTION: 32 CAMPBELL
CLIENT: T & M BALLAT of
10 Elliott Street Campbell

DWN: A.KWONG	
SCALE: 1:100	DATE: 18/8/14
DWG No.: 1425	SHEET: 2 OF 4

DRAWING STATUS
WORK AS EXECUTED

PLAN OF HYDRAULIC SERVICES

DRAINAGE PLAN No 3415

OWNER BALLAT

BLOCK 38 SECTION 32 CAMPBELL

© COPYRIGHT

FIXTURES

1. WATER CLOSET	(1)	7. URINAL	(0)	V.C.P	VITRIFIED CLAY PIPE	D.T	DISCONNECTOR TRAP
2. BATH	(0)	8. CLN'S SINK	(0)	S.V.P	SOIL VENT PIPE	I.O	INSPECTION OPENING
3. BASIN	(1)	9. BIDET	(0)	U.P.V.C	UNPLASTICISED POLYVINYL CHLORIDE	E.J	EXPANSION JOINT
4. SHOWER	(1)	11. DISHWASHER	(0)	A.A.V	AIR ADMITTANCE DEVICE	W.S	WATER SERVICE
5. SINK	(1)	13. WASHER	(0)			I.S	INSPECTION SHAFT
6. LAUNDRY TUB	(0)	15. COOKING OVEN	(0)	O.R.G	OVERFLOW RELIEF GULLY	H.C	HOSECOCK
				F.G.L	FINISHED GROUND LEVEL	VJU	VERTICAL JUMP UP
						S.V	STOPVALVE

REFERENCES

T.D.	TUNDISH		
G.T	GULLY TRAP		
V.P.	VENT PIPE		
F.W.	FLOOR WASTE		
E.V.	EDUCT VENT		
J.U.	JUMP UP		
S.T	SILT TRAP		
B.T.	BUCKET TRAP		

ALL WORK TO BE IN ACCORDANCE WITH THE CANBERRA SEWERAGE AND WATER SUPPLY REGULATIONS. THIS PLAN TO BE READ IN CONJUNCTION WITH APPROVED ARCHITECTURAL PLANS.THIS PLAN HAS BEEN DESIGNED IN ACCORDANCE WITH A.S 3500, NATIONAL PLUMBING AND DRAINAGE CODE. ORG TO BE A HEIGHT OF 150mm BELOW LOWEST FIXTURE TO BE DRAINED & A MINIMUM 75mm ABOVE F.G.L.(50mm IN PAVED AREAS,GRADED FROM O.R.G.)

NOTES 1. ALL NEW SEWER DRAINS ARE 100Ø UPVC UNLESS NOTED OTHERWISE.
2. ALL NEW SW IS 90Ø PVC EXCEPT 100Ø LINE FROM TIE TO FIRST JUNCTION & UNDER SLABS.



S T R E E T

SCALE 1:200

CONSTRUCTION HYDRAULICS PLAN

SEWER AND STORMWATER LAYOUT

0 2M 4M 6M 8M 10M 12M 14M 16M

1:200 SCALE REFERS TO DRAINAGE PLAN



SYMBOLS LEGEND

DP	DOWNPIPE
FW	FLOORWASTE
CO	CLEAROUT
IO	INSPECTION OPENING
IS	INSPECTION SHAFT
SV	STOPVALVE
ORG	OVERFLOW RELIEF GULLY

LOCATION PLAN above
NOT TO SCALE

DESIGN STUDIO

3 Buru Close Ngunnawal Canberra 2913 ACT Anthony 0414 244 518 ph 6241 7138 email daf@webone.com.au www.designstudiocanberra.com.au

SEWERAGE ENGINEER

NOT TO SCALE

SERVICE TIE/EXISTING HYDRAULICS

DO NOT SCALE. USE WRITTEN DIMENSIONS

PLEASE NOTE: ON THE TIE IMAGE, RED LINES INDICATE SEWERAGE, GREEN LINES INDICATE STORM WATER AND BLUE LINES INDICATE WATER SUPPLY.

LEGEND WHERE APPLICABLE

- NEW 100Ø UPVC SANITARY LINE
- SW — EXISTING STORMWATER SERVICE
- SW — SW — NEW STORMWATER SERVICE
- SW — SW — PROPOSED CHARGED STORMWATER
- EXISTING SANITARY SERVICE
- SEWER MAIN
- STORMWATER MAIN

SW NOTE:PROVIDE 100 DIAMETER PIPE TO THE FIRST JUNCTION AND UNDER BUILDINGS UNLESS NOTED OTHERWISE. GREASE LINES SHOWN IN ORANGE LINES. PROPOSED WASTE PLUMBING SHOWN IN YELLOW LINES. PROPOSED SOIL AND DRAINS TO BE LAID SHOWN IN BLUE LINES.DRAINS DELETED SHOWN BY RED "X". EXISTING DRAINS SHOWN IN GREEN LINES.PROVIDE INSPECTION OPENINGS ON EACH WC BRANCH OF INTERVALS OF NOT MORE THAN 30m SPACED EQUIDISTANT IMMEDIATELY UP & DOWNSTREAM OF ALL JUMP UPS.VITRIFIED CLAY PIPES TO BE IN ACCORDANCE WITH AS1693 & AS A164.UPVC PIPES TO BE IN ACCORDANCE WITH AS1260.PROVIDE FIRE STOP COLLARS TO ALL UPVC PENETRATIONS OF FIRE RATED FLOORS AND WALLS.THIS BASE DRAINAGE PLAN REMAINS THE PROPERTY OF THE ARCHITECTURAL DESIGN STUDIO & IS NOT TO BE COPIED WITHOUT THE EXPRESS WRITTEN PERMISSION OF ANTHONY BURR.WHILST EVERY PRECAUTION IS TAKEN TO ENSURE THE ACCURACY OF THE NOTES &/OR DRAWINGS NO RESPONSIBILITY &/OR LIABILITY WILL BE ACCEPTED FOR ANY ERRORS &/OR OMISSIONS IN THE TEXT &/OR DRAWINGS.IT IS THE CONTRACTORS RESPONSIBILITY TO ESTABLISH THE LOCATION OF ALL EXISTING SERVICES & THE SUITABILITY OF THE DESIGN PRIOR TO COMMENCING CONSTRUCTION.CHECK POSITION OF TIE PRIOR TO COMMENCING CONSTRUCTION.INSPECTION SHAFT TO BE LOCATED AT THE PROPERTY BOUNDARY IS TO BE RAISED TO GROUND LEVEL IN ACCORDANCE WITH PLUMBING NOTE 3.

1.6.2015.

DESIGN STUDIO

3 Buru Close Ngunnawal Canberra 2913 ACT email daf@webone.com.au
Anthony 0414 244 518 ph 6241 7138 www.designstudiocanberra.com.au

Scale1:200 Designed & Drawn by *Anthony Burr*

ACT PROPERTY INSPECTIONS

Energy Efficiency Rating

UNDERSTANDING YOUR ENERGY EFFICIENCY RATING (EER)

An energy efficiency rating (EER) is a rating used to identify the energy efficiency of homes in the ACT.

The Civil Law (Sale of Residential Property) Act 2003 requires all homes being sold in the ACT to carry an energy efficiency rating (EER). This enables owners and buyers to compare a home's passive energy performance characteristics with others for sale in the Territory.

In the ACT, established homes are assessed using 1st generation software, and can achieve **0 to 6 stars** in the rating scheme.

Houses with a higher EER are more cost and energy efficient, use less energy for heating and cooling, generate lower greenhouse gas emissions, and are more comfortable.

What information is taken into account when assessing my homes energy efficiency?

- Layout of the home
- Construction of its roof, walls, windows, and floor
- Wall, floor, and ceiling insulations
- Orientation of windows and shading of the sun's path and local breezes
- Influence of the local climate
- Air leakages

What information is not applicable when assessing my homes energy efficiency?

- Heating and cooling
- Hot water systems
- Lighting systems and appliances
- Solar panels

How can I improve my energy efficiency rating?

Your energy efficiency report will include a list of design options (unless it's already achieved the maximum rating of 6 stars). This will outline the improvements that can be made to gain additional points and increase the overall star rating of your home.

When I built my home, I was provided with a 10-star energy rating. Why has this decreased?

The ACT Government has two software systems in place to generate energy efficiency ratings:

1. Established homes: An on site assessment using 1st generation software. A maximum of 6 stars can be achieved.
2. Brand new homes: A computer based assessment using 2nd generation software. A maximum of 10 stars can be achieved.

If you hold an energy efficiency rating that exceeds 6 stars, it is a 2nd generation EER and would have been provided when your home was brand new.

When assessing a home's energy efficiency for the purpose of sale, property inspection companies are required to use 1st generation software, which will achieve a maximum of 6 stars.

FirstRate Report

HOUSE
ENERGY RATING

YOUR HOUSE ENERGY RATING IS: ★★★★ **4 STARS**
in Climate: 24

SCORE: -5 POINTS

Name:	McCormack & Wright	**Ref No:**	69343
House Title:	Block 38 Section 32 CAMPBELL	**Date:**	10-04-2026
Address:	10 Elliott St, Campbell ACT 2612		

ACT HOUSE ENERGY RATING SCHEME

-5 Points 4.0 Stars

Duncan Clark – 2011260

Building Assessor - Class A (Energy Efficiency)

This rating only applies to the floor plan, construction details, orientation and climate as submitted and included in the attached Rating Summary. Changes to any of these could affect the rating.

IMPROVING YOUR RATING

The table below shows the current rating of your house and its potential for improvement.

	POOR		AVERAGE		GOOD		V. GOOD
Star Rating	**0 Star**	★	★★	★★★	★★★★	★★★★★	★★★★★★
Point Score	**-71**	**-70 -46**	**-45 -26**	**-25 -11**	**-10 4**	**5 16**	**17**



Incorporating these design options will add the additional points required to achieve the potential rating shown in the table Each point represents about a 1% change in energy efficiency. This list is only a guide to the range of options that could be used.

Design options		**Additional points**
Change added floor insulation	R 2.5	5
Change curtain to	Heavy Drapes & Pelmets	18
Add northerly blinds	100 %	1
Add westerly blinds	100 %	1
Seal Internal Doors		1

ORIENTATION

Orientation is one of the key factors which influences energy efficiency. This dwelling will achieve different scores and star ratings for different orientations.

Current Rating	**-5**	★★★★

Largest windows in the dwelling;

Direction : WNW

Area : 23 m²

The table below shows the total score for the dwelling when these windows face the direction indicated.

Note that obstructions overshadowing windows have been removed from all windows in these ratings to allow better comparisons to be made between orientations.

ORIENTATION	POINT SCORE	STAR RATING
1. West	**-6**	★★★★
2. North West	**-4**	★★★★
3. North	**-1**	★★★★☆
4. North East	**-4**	★★★★
5. East	**-7**	★★★★
6. South East	**-11**	★★★☆
7. South	**-10**	★★★☆
8. South West	**-10**	★★★★

FirstRate Mode
Climate: 24

RATING SUMMARY for: **Block 38 Section 32 CAMPBELL, 10 Elliott St, Campbell ACT 2612,**

Assessor's Name:

Net Conditioned Floor Area: **206.0 m²**

Feature						Points		
						Winter	Summer	Total
CEILING						**11**	**0**	**11**
Surface Area:	3	Insulation:	8					
WALL						**0**	**0**	**0**
Surface Area:	-4	Insulation:	5	Mass:	-1			
FLOOR						**6**	**-1**	**5**
Surface Area:	1	Insulation:	2	Mass:	1			
AIR LEAKAGE (Percentage of score shown for each element)						**4**	**0**	**4**
Fire Place	21 %	Vented Skylights	0 %					
Fixed Vents	0 %	Windows	35 %					
Exhaust Fans	9 %	Doors	22 %					
Down Lights	0 %	Gaps (around frames)	14 %					
DESIGN FEATURES						**0**	**1**	**1**
Cross Ventilation	1							
ROOF GLAZING						**0**	**0**	**0**
Winter Gain	0	Winter Loss	0					
WINDOWS						**-11**	**-14**	**-25**

Window Direction	Area		Point Scores			
	m2	%NCFA	Winter* Loss	Winter Gain	Summer Gain	Total
NNE	16	8%	-14	18	-2	1
ESE	10	5%	-8	7	-3	-4
SSW	15	7%	-14	5	-3	-12
WNW	24	12%	-22	18	-6	-10
Total	64	31%	-57	47	-14	-25

* Air movement over glazing can significantly increase winter heat losses. SEAV recommends heating/cooling duct outlets be positioned to avoid air movement across glass or use deflectors to direct air away from glass.

The contribution of heavyweight materials to the window score is 1 point			Winter	Summer	Total
RATING	★★★★	**SCORE**	**10**	**-15**	**-5***

*** includes -1 points from Area Adjustment**

Detailed House Data

House Details

ClientName	McCormack & Wright
HouseTitle	Block 38 Section 32 CAMPBELL
StreetAddress	10 Elliott St, Campbell ACT 2612
FileCreated	10-04-2026

Climate Details

State	
Town	
Postcode	0
Zone	24

Floor Details

ID	Construction	Sub Floor	Upper	Shared	Foil	Carpet	Ins RValue	Area
1	Suspended Slab	Enclosed	No	No	No	Float Timb	R0.5	34.0m²
2	Suspended Slab	Enclosed	No	No	No	Carp	R0.5	121.8m²
3	Timber	NA	Yes	No	No	Tiles	R0.0	9.0m²
4	Timber	NA	Yes	No	No	Carp	R0.0	60.3m²

Wall Details

ID	Construction	Shared	Ins RValue	Length	Height
1	Framed: FC Sheet Clad	No	R2.5	34.5m	2.4m
2	Brick Veneer	No	R1.5	59.7m	2.7m

Ceiling Details

ID	Construction	Shared	Foil	Ins RValue	Area
2	Attic - Low Ventilation	No	Yes	R5.0	155.8m²

Window Details

ID	Dir	Height	Width	Utility	Glass	Frame	Curtain	Blind	Fixed & Adj Eave	Fixed Eave	Head to Eave
1	SSW	2.1m	1.5m	No	SG	ALIMPR	CW	Yes	2.1m	0.0m	0.0m
2	ESE	0.6m	1.8m	No	SG	ALIMPR	CW	No	0.0m	0.0m	0.0m
3	SSW	2.1m	1.5m	No	SG	ALIMPR	CW	Yes	2.1m	0.0m	0.0m
4	WNW	0.6m	1.8m	No	SG	ALIMPR	CW	No	0.0m	0.0m	0.0m
5	WNW	1.2m	1.2m	Yes	SG	ALIMPR	VE	No	0.0m	0.0m	0.0m
6	WNW	0.6m	1.8m	No	SG	ALIMPR	CW	No	0.0m	0.0m	0.0m
7	NNE	1.4m	1.6m	No	SG	ALIMPR	CW	No	0.0m	0.0m	0.0m
8	NNE	1.4m	1.6m	No	SG	ALIMPR	CW	No	0.0m	0.0m	0.0m
9	ESE	1.4m	0.6m	No	SG	ALIMPR	VE	No	0.0m	0.0m	0.0m
10	ESE	1.4m	0.6m	No	SG	ALIMPR	CW	No	0.0m	0.0m	0.0m
11	ESE	1.4m	0.6m	No	SG	ALIMPR	CW	No	0.0m	0.0m	0.0m
12	SSW	2.0m	0.6m	No	SG	ALIMPR	CW	No	2.0m	2.0m	0.0m
13	SSW	2.0m	0.6m	No	SG	ALIMPR	CW	No	2.0m	2.0m	0.0m
14	SSW	2.0m	0.6m	No	SG	ALIMPR	CW	No	2.0m	2.0m	0.0m
15	WNW	2.0m	1.6m	No	SG	ALIMPR	CW	Yes	2.0m	0.0m	0.0m
16	WNW	2.0m	1.6m	No	SG	ALIMPR	CW	Yes	2.0m	0.0m	0.0m
17	NNE	2.0m	1.8m	No	SG	ALIMPR	CW	No	4.2m	4.2m	0.2m
18	WNW	2.1m	3.4m	No	SG	ALIMPR	CW	No	2.7m	2.7m	0.2m
19	SSW	2.0m	1.8m	No	SG	ALIMPR	CW	No	4.2m	4.2m	0.2m
20	WNW	2.0m	1.8m	No	SG	ALIMPR	CW	Yes	2.0m	0.0m	0.0m
21	WNW	2.0m	1.8m	No	SG	ALIMPR	CW	Yes	2.0m	0.0m	0.0m
22	NNE	2.1m	3.6m	No	SG	ALIMPR	CW	Yes	4.0m	0.0m	0.6m
23	ESE	1.2m	0.6m	Yes	SG	ALIMPR	VE	No	0.0m	0.0m	0.0m

24	ESE	1.2m	2.0m	No	SG	ALIMPR	VE	No	0.0m	0.0m	0.0m
25	ESE	1.2m	0.6m	Yes	SG	ALIMPR	VE	No	0.0m	0.0m	0.0m
26	ESE	1.2m	0.6m	Yes	SG	ALIMPR	VE	No	0.0m	0.0m	0.0m
27	ESE	1.2m	0.6m	No	SG	ALIMPR	NC	No	0.0m	0.0m	0.0m
28	ESE	1.2m	0.6m	No	SG	ALIMPR	NC	No	0.0m	0.0m	0.0m
29	SSW	2.0m	0.6m	No	SG	ALIMPR	NC	No	0.0m	0.0m	0.0m

Window Shading Details

ID	Dir	Height	Width	Obst Height	Obst Dist	Obst Width	Obst Offset	LShape Left Fin	LShape Left Off	LShape Right Fin	LShape Right Off
17	NNE	2.0m	1.8m	2.7m	4.2m	2.3m	-0.4m	0.0m	0.0m	4.2m	0.0m
18	WNW	2.1m	3.4m	0.0m	0.0m	0.0m	0.0m	5.0m	0.0m	3.0m	0.2m
19	SSW	2.0m	1.8m	2.7m	4.2m	5.0m	0.0m	4.2m	0.0m	0.0m	0.0m

Zoning Details

Is there Cross Flow Ventilation ?	Good

Air Leakage Details

Location	Suburban
Is there More than One Storey ?	Yes
Is the Stairwell Separated by Doors ?	No
Is the Entry open to the Living Area ?	Yes
Is the Entry Door Weather Stripped ?	Yes
Area of Heavyweight Mass	0m²
Area of Lightweight Mass	0m²

	Sealed	UnSealed
Chimneys	1	0
Vents	0	0
Fans	2	0
Downlights	0	0
Skylights	0	0
Utility Doors	1	2
External Doors	0	0

Unflued Gas Heaters	0
Percentage of Windows Sealed	98%
Windows - Average Gap	Small
External Doors - Average Gap	Small
Gaps & Cracks Sealed	Yes

ACT PROPERTY INSPECTIONS

Insurance Certificates & Tax Invoice

If a home was built before 1990

it may contain dangerous asbestos material

ACT Government

Identify where asbestos materials might be. Five common places are:

1. Exterior

roof sheeting, gutters, downpipes, ridge capping, eaves, cladding, electrical switchboards



5. Building cavities

A small number of homes may still contain loose fill asbestos insulation in the roof cavity, wall cavities or sub-floor space

2. Wet areas - bathroom, laundry and kitchen

wall and ceiling panels, vinyl floor tiles, backing for wall tiles and splashbacks, hot water pipe insulation

3. Internal areas

wall and ceiling panels, carpet underlay, textured paints, insulation in domestic heaters

4. Backyard

fences, sheds, garages, carports, dog kennels, buried or dumped waste, letterboxes, swimming pools

Authorised by the ACT Parliamentary Counsel—also accessible at www.legislation.act.gov.au

If a home was built before 1990

it may contain dangerous asbestos material

ACT Government

Assess the risk

A licensed asbestos assessor can help identify asbestos in your home and its condition.

Asbestos materials become dangerous when:

Broken or in poor condition

Damaged accidentally

Disturbed during renovation or repairs

Loose fill asbestos insulation

Manage asbestos safely

- Monitor the condition of asbestos in your home
- Inform tradespeople of locations of asbestos in your home
- Avoid disturbing or damaging asbestos if working on your home
- Engage a licensed asbestos removalist to remove asbestos

If you suspect your home contains loose fill asbestos insulation, contact Access Canberra

For more information, visit www.worksafe.act.gov.au or call Access Canberra contact centre – 13 22 81

If you need interpreting help, telephone the Translating and Interpreting Service on 131 450

*Advice based on the Asbestos Safety and Eradication Agency's residential asbestos disclosure research.

Authorised by the ACT Parliamentary Counsel—also accessible at www.legislation.act.gov.au

Pest Controllers Combined Liability Certificate of Currency

The Policy below is current until 4.00pm on the expiry date shown below

INSURED:	ACT Property Inspections Pty Ltd
BUSINESS DESCRIPTION:	General Pest & Weed Control Timber Pest Inspections Termite Barrier Installations Pre-Purchase House Pest Inspections Building Inspections (Non Pest Related) Energy Efficiency Ratings Compliance Reports
POLICY REFERENCE:	09A349653PLB
PERIOD OF INSURANCE:	From: 4.00pm on 30/03/2025 To: 4.00pm on 30/03/2026
POLICY CLASS:	Pest Controllers Combined Liability
SUMS INSURED:	**Section 1: General Public & Products Liability** **$20,000,000** Our maximum liability in respect of any claim or series of claims for Personal Injury, Property Damage or Advertising Liability caused by or arising out of any one occurrence; and **$20,000,000** Our total aggregate liability during any one period of insurance for all claims arising out of Your Product **Section 2: Professional Indemnity** **$5,000,000** Our maximum liability in respect of any Claim or any series of Claims inclusive of costs and expenses. **$10,000,000** Our total aggregate liability for all Claims inclusive of costs and expenses.

This Certificate of Currency is subject to the Policy Documentation to be read in conjunction with the Definitions, Conditions and Exclusions in the Pest Controllers Combined Liability Insurance Policy.

Date Issued: 28 March 2025

priceforbes
Price Forbes & Partners
The Minster Building
21 Mincing Lane
London
EC3R 7AG
www.priceforbes.com

TO WHOM THIS MAY CONCERN

9th March 2026

Certificate of Currency

Dear Sir or Madam,

We, the undersigned Insurance Brokers acting on behalf of the Insured, hereby certify that the following described insurance is in force at this date.

TYPE OF INSURANCE:	Professional Indemnity Insurance
INSURED:	ACT Property Inspections Pty Ltd.
ADDRESS OF INSURED:	Unit 1/33 Altree Court, Phillip ACT 2606, Australia.
POLICY NUMBER:	B0507OE2600060
PERIOD:	From: 30th March 2026 to: 30th March 2027 At 4pm Local Standard Time at the Principal Address of the Insured.
LIMIT OF LIABILITY:	AUD 5,000,000 in the annual aggregate inclusive of costs and expenses plus one reinstatement.
INSURERS:	100% Lloyd's of London

This letter is provided as a matter of information only and confers no rights on the holder. Our duties in relation to this insurance are to our client and we accept no duty of care or responsibility to you or any other third party and any liability to you or a third party is excluded. This letter does not amend, extend, or alter the coverage afforded by the policy, nor does it purport to set out all of the policy terms, conditions and exclusions. The policy terms, conditions, limits, and exclusions may alter after the date of this document or the insurance may terminate or be cancelled, and the limits shown may be reduced to pay claims. We have no obligation to advise you of any changes which may be made to the policy or to advise you of their cancellation or termination.

Issued on behalf of Price Forbes & Partners

Adam Power
Executive Director

TAX INVOICE

Michael McCormack & Spencer Wright
10 Elliott St
CAMPBELL ACT 2612
AUSTRALIA

Invoice Date
31 Mar 2026

Invoice Number
INV-69343

ACT Property Inspections
(02) 6232 4540
Unit 1, 33 Altree Ct
PHILLIP ACT 2606
ABN: 33 600 397 466

Description	Quantity	Unit Price	GST	Amount AUD
ACTPLA Fees - No GST	1.00	186.70	GST Free	186.70
Property Report	1.00	1,475.73	10%	1,475.73
Energy Efficiency Report (Complimentary)	1.00	0.00		0.00
Deferred Payment (Complimentary)	1.00	0.00		0.00
			Subtotal	1,662.43
			TOTAL GST 10%	147.57
			TOTAL AUD	**1,810.00**

Due Date: 27 Sep 2026
Payment terms – Deferred payment account. This account should be paid in full within 14 days on the earlier of:
(a) Settlement of the property
(b) If the Property has not been listed for sale within 3 months of the Property Inspection Date
(c) If the property is no longer listed for sale
(d) 180 days after the Property Inspection Date

Please pay within the payment terms to avoid the Deferred Payment Fee. Note: all bank/legal fees incurred in obtaining payment will be the customer's responsibility

Payment Options

Pexa : please quote the invoice number as the reference

Direct Deposit : BSB: 012084 Account Number: 194679655
Account Name: ACT Property Inspections Pty Ltd
Please reference your name and invoice number

Cheques : please make payable to ACT Property Inspections Pty Ltd

View and pay online now